



Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: ARCH/ASS/SNT/045

SECTION I: IDENTIFICATION

1. Name ()

Present

Phulbari Devalaya

Past

Other Name (if any)

2. Location ()

LONGITUDE E93°45'672 LATTITUDE N26°52'740'

Address

Hawajan, Lakhpur

Village (village code)

Post Hawajan

District

Sonitpur

State

Assam.

PIN

784169

Approach

Through NH 52 towards east and then southward about 3 KM.

3. Property Type ()

Buildings

- Palace
- Fort
- Citadel
- Govt. building
- Railway station
- Defence building
- Industrial building
- Other public buildings
- Residential building

Engineering structure

- Bridge
- Tunnel
- Other engineering

Religious structures

- Temple
- Mosque
- Minar
- Church
- Monastery
- Stupa
- Tomb, Mausoleum

Open space and related structures

- Public square
- Park or garden
- Graveyard
- Baolis, Well

Other Structures

- Wall
- Gateway
- Pillar
- Others (specify)

structure

- Tank
 Cave

4. Property Use ()

ABANDONED / IN USE

Present

Temple of recent construction with antique objects

Past

Temple

5. Age (Source) ()

PERIOD ()

YEARS ()

Precise date of

Construction

1705 AD. (

Completion

Subsequent changes

Destruction / Demolition

6. Ownership / Level of Protection ()

SINGLE / MULTIPLE

Public

Archaeological Survey of India / State Archaeology Department /

Any Other (Please specify) Temple Committee

Private

Any other (Please specify)

Name

Address

Phone

7. Association ()

• WITH EVENTS

In History

In Rituals

In Building Construction

Any other (specify)

• WITH PERSONS

Patron

Architect / Engineer

Any other (specify)

King Rudra Singha (1696 - 1714 AD).

8. Statement of Significance ()

- Architectural
 Archaeological
 Historical
 Religious
 Any other (specify) _____

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features

• Context

* Drawings (Attach extra sheet if necessary)

Urban / Rural Setting
Surroundings

Stand in Isolation
Integral part of a Landscape Street Complex

• Quantification

Area Dimension (L x B x H)

Old temple is not in existence
(m / cm / feet / inch)

Number of Blocks

Number of Storeys

• Spatial Organization

Orientation

Plan

Allocation of Spaces

ARCHITECTURAL STYLE

• Ornamentation

Exteriors

Interiors

Movable Collections

* Any Other (specify)

*A dev's image in black stone, one
ringing bell with inscription, one
image of baruna are in stone in the
temple. The image is datable to 12th
C. AD according to scholars.*

10. Construction Technology

Structural System

Building Techniques

Material of Construction _____

11. Condition Assessment

In General

Good / Fair

- Sign of Deterioration
- Serious Deterioration
- Danger of Disappearance

In Brief (Attach extra sheet if necessary)

Instances of application of Sindoor-oil mixture and dirt is noticed in the image of Barua. Flaking is also noticed. The dev's image is kept with utmost care and is in good condition.

12. Threats to the Property

- Natural
- Negligence
- Vandalism
- Urban Pressures