

### INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

# **Documentation format for Archaeological / Heritage Sites / Monuments**

Serial No.: OR / PRI - 43

**SECTION I: IDENTIFICATION** 

1. Name

Present : Markandeya Tank, Puri Town, Dist- Puri

Past :

Other Name (if any):

2. Location

LONGITUDE 85<sup>0</sup>48'94"E LATITUDE 19<sup>0</sup>48'62"N ELEVATION 16 ft

Address : Village (village code) Markandesvara Sahi, Puri

Town

Post: Puri Via: Puri Town Tehsil: Puri District: Puri State: Orissa PIN: 752001

**Approach**: Markandeya tank is located behind the Markendesvara

Siva Temple across the compound wall, in upara Markandesvara Sahi, Puri. One can approach the site from the right side of the Markandesvara road leading from

Wall

Pillar

Gateway

Others (specify)

upara Markandesvara chowk to Brahmagiri.

3. Property Type

Buildings Religious structures Other Structures

Palace Temple
Fort Mosque
Citadel Minar
Govt. building Church

Railway station Monastery
Defence building Stupa
Industrial building Tomb, Mausoleum

Industrial building
Other public buildings
Residential building

Engineering structure Open space and related Note:

Bridge Structures

Public s

Tunnel Parl Other engineering structure Gra

Public square Park or garden Graveyard Baolis, Well

✓ Tank Cave The tank is an open structure and it enclosed within a masonry embankment made of dressed laterite blocks. The tank is 8.50 mtrs below the present road level.

# 4. Property Use

ABANDONED / IN USE: In use

Present : Living tank, presently used for rituals as well as normal

bathing.

**Past** : Rituals and bathings.

# 5. Age (Source)

**PERIOD** : Ganga Period **YEARS** : 12<sup>th</sup> Century AD.

Precise date of Construction : --Completion : --Subsequent changes : --Destruction / Demolition : ---

### 6. Ownership / Level of Protection

SINGLE /MULTIPLE : Multiple

Public: Archaeological Survey: Endowment Department, Government of Orissa

of India / State Archaeology Department / Any Other

(Please specify)

Private : Markandeya Siva Temple

Any other (Please specify) : ---

Name : Narsingha Tiadi, Chief Priest
Address : Upara Markandesvara Sahi, Puri

Phone : ---

#### 7. Association

#### WITH EVENTS

In History : ---

In Rituals : Offering of Pinda, Mundan Kriya, Gobadha papa

etc.

In Building Construction : --Any other (specify) : ---

WITH PERSONS

**Patron** : Endowment Department, Government of Orissa.

Architect / Engineer : --Any other (specify) : ---

### 8. Statement of Significance

Architectural ✓ Architectural

\_\_\_ Archaeological

Historical

Religious

Any other (specify) : On the basis of local tradition as well as related evidence with

Markandesvara temple, the tank can be dated back to the

### **SECTION II: DESCRIPTION**

# 9. Physical Description and Decorative Features

Context
 Urban / Rural Setting

\* **Drawings (**Attach extra sheet if necessary): No

Urban setting

Surroundings

Stand in Isolation

Integral part of a Landscape /

Street

Street / Complex :

Quantification

Area Dimension (LxBxH)

152.00 mts x 120.00 mts x 4.00 mts

(m / cm/ feet / inch)

Number of Blocks

Single N.A

Number of Storys :

Spatial Organization

Orientation

Plan

Bathing ghats are provided in southern side.

Rectangular on plan

Allocation of Spaces

152.00 mtrs (L) x 120.00 mtrs (B)

# **ARCHITECTURAL STYLE**

Ornamentation

Exteriors

In the north eastern corner of the compound wall there is a niche measuring 1.43 mtrs in height x 0.72 mtrs in width. In the northern wall there are fifteen niches. In the western wall there are thirty four niches. In two of these niches detached sculptures are there. It appears that originally these

niches of the tank house various cult images.

Interiors : N.A

Movable Collections

Two detached sculptures of female figure and Hanuman are noticed in the north eastern compound wall of the tank. In the south-eastern corner there is a modern shrine where eight detached sculptures are kept over a moulded

pedestal.

\* Any Other (specify)

The tank is fed by a natural spring from the under ground. The excess and waste water is discharged through an outlet channel in the north-eastern wall. As a result the water level of the tank remains

constant throughout the year.

10. Construction Technology

Structural System : Rectangular tank with embankment

**Building Techniques** Dry masonry **Material of Construction** Laterite 11. Condition Assessment In General Good / Fair : Fair Sign of Deterioration **Serious Deterioration** Danger of Disappearance In Brief (Attach extra sheet if necessary) The compound wall in the western side has partly collapsed. The sacred water became polluted highly due to lack of cleaning. 12. Threats to the Property Natural Negligence ✓ Vandalism **Urban Pressures** Х Х Х Х Х Х **SECTION III: REFERENCES** 13. Reference Sources (published and unpublished textual details) 14. Photographs (attach list as in page 6, in case of multiple photographs) **Photo Reference** CAPTION 15. Audio / Video (related to rituals / performance / festivals etc.) Reference DESCRIPTION 16. Maps/Plans/Drawings

17. Listers

**NAME:** B. B. Satpathy **NAME:** 

18. Reviewers

NAME: Dr. S. Pradhan NAME: COMMENTS

: