

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: 0R / PRI - 47

SECTION I : IDENTIFICATION

	SECTION 1 : IDENTIFICATION	
1. Name		
Present Past Other Name (if any): 2. Location	: Naga <i>Matha</i> , Harachan : :	di Sahi, Puri Town, Dist Puri
LONGITUDE 85° 48' 86" E	LATITUDE 19 ⁰ 48 ['] 16 ["] N	ELEVATION 31 ft
Address	: Village (village code) Post : Harachandi Sahi Tehsil: Puri town State : Orissa	
Approach		n Harachandi Sahi, Puri. It is 30 mtrs north-east of Barabati of Surangi <i>Matha</i> .
3. Property Type		
Buildings Palace Fort Citadel Govt. building Railway station Defense building Industrial building Other public building Residential building	Religious structures Temple Mosque Minar Church Monastery Stupa Tomb, Mausoleum	Other Structures Wall Gateway Pillar Others (specify)
Engineering structure Bridge Tunnel Other engineering structure	structures Public square Park or garden Graveyard Baolis, Well	Note: The Matha is affiliated to Gaudiya sect. Presently, the double storied monastery is used both for monastic activities and commercial purpose.

Present	:	ABANDONED / IN USE: In use Living temple, the presiding deities are Radha and Krisna.
Past	:	Worshipped.
5. Age (Source)		
PERIOD	:	Bhoi rule.
YEARS	:	18 th century A.D.
Precise date of Construction	:	
Completion	:	
Subsequent changes	:	
Destruction / Demolition	:	
6. Ownership / Level of Protection	on	
		SINGLE /MULTIPLE : Multiple
Public: Archaeological Survey of India / State Archaeology Department / Any Other (Please specify)	:	Endowment Department, Government of Orissa.
Private	:	
Any other (Please specify)	•	Under the care and maintenance of the <i>Matha</i> Mahanta Sachidananda Goswami.
Name	:	
Address	:	
Phone	:	
7. Association		
• WITH EVENTS		
In History	:	According to the <i>Matha</i> Mahanta, the <i>Matha</i> was constructed in 14 th century AD. It was founded by Naga Premdash Goswami, who was a disciple of Rupa Goswami. The <i>Matha Mahantas</i> are succeeded in hereditary succession.
In Rituals	:	Radhastami, Janmastami, Dolapurnima etc. are observed.
In Building Construction	:	
Any other (specify)	:	Thread ceremony, marriage ceremony etc are observed here.
 WITH PERSONS 		
Patron	:	Endowment Department, Government of Orissa.
Architect / Engineer	:	
Any other (specify)	:	Matha Mahanta Sachidananda Goswami.
8. Statement of Significance		
Architectural	/	Architectural
Archaeological Historical Religious		Archaeological
Any other (specify)		As per the Matha Mahanta, the monastery can be assigned

SECTION II: DESCRIPTION

9. Physical Description and Description	ecorati	ve Features
 Context Urban / Rural Setting Surroundings 	:	* Drawings (Attach extra sheet if necessary):No Urban setting
· ·		Stand in isolation/ Complex Integral part of a landscape / Street / Complex :
• Quantification Area Dimension (L x B x H)	:	First courtyard- 11.85mtrs x 10.40 mtrs (LxW)- Second courtyard- 7.95 mtrs x 6.05 mtrs (L x W) (m / cm/ feet / inch)
Number of Blocks Number of Storys	:	50 rooms. Double storied.
 Spatial Organization Orientation Plan Allocation of Spaces 	: :	Facing towards south. On plan the <i>Matha</i> has two courtyards surrounded by pillared verandah which leads into residential rooms. One-acre land.
ARCHITECTURAL STYLE Ornamentation Exteriors Interiors Movable Collections * Any Other (specify) 10. Construction Technology	: : : : : : : : : : : : : : : : : : : :	Plain At the centre of second courtyard there is a <i>Pidha</i> temple in which various modern paintings depicting the different activities of nagas on the eastern, western and southern wall Nil The roof of the <i>Matha</i> is made of R.C.C and supported by wooden beams.
Structural System Building Techniques Material of Construction 11. Condition Assessment	: : :	Double storied monastery. Ashlar masonry and English bond. Laterite and bricks.
In General	Good	/ Fair Good
		Sign of Deterioration Serious Deterioration Danger of Disappearance

In Brief (Attach extra sheet if necessary):

Out of fifty rooms, five are in dilapidated condition and the rest are in a good state of

					Vand	ral igence dalism in Press	sures					
X	x	х	х	х	х	x	х	x	х	x	х	
				SEC	TION II	<u>I.</u> KEF	EKEN	CES				
40 D C		_	/ 11						`			
13. Refer			es (publ	lished a	and unpu	ıblished	d textua	l details	s)			_
13. Refer			es (publ	lished a	-					multiple	e photo)(_
	ograp eference	hs	es (publ	lished a	-					multiple	e photo)(
14. Photo	ograp ferend	hs	es (publ	lished a	-	th list as	s in pag	je 6, in	case of	·	·	
14. Photo Photo Re CAPTION	ograp ferend	hs	es (publ	lished a	-	th list as	s in pag	je 6, in	case of	multiple mance,	·	

17. Listers			
NAME :	J.S Naik	NAME :	
18.Reviewe	ers		
NAME : COMMENT	Dr. S. Pradhan	NAME : COMMENTS :	