

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: 0R/PRI- 81

SECTION I : IDENTIFICATION 1. Name							
Present Past Other Name (if any):	: Tota Gopinath Matha, : :	Puri town, Dist. – Puri					
LONGITUDE 85 ⁰ 48'80" E	LATITUDE 19 ⁰ 47'85"N	ELEVATION 43 Ft.					
Address	: Village (village code) Post : Puri Tehsil: Puri State : Orissa	Gaudia Sahi, Puri Town Via: Puri District: Puri PIN:					
Approach		in Gaudabada Sahi, Puri. It is side of the road leading from the beach.					
3. Property Type							
Palace Fort Citadel Govt. building Railway station Defence building Industrial building Other public building Residential building	Religious structures Temple Mosque Minar Church ✓ Monastery Stupa Tomb, Mausoleum	Other Structures Wall Gateway Pillar Others (specify)					
Engineering structure Bridge Tunnel Other engineering structure	Open space and related structures Public square Park or garden Graveyard Baolis, Well Tank Cave	Note: The single storeyed matha is affiliated to the Gaudia sect.					

4. Property Use

	ABANDONED / IN USE: In use
Present	: It is a living matha. The enshrining deity is images of Radha-Krishna made out of chlorite.
Past	: Monasteric activity & ritual purpose.
5. Age (Source)	
PERIOD YEARS Precise date of Construction Completion Subsequent changes Destruction / Demolition 6. Ownership / Level of Protection	: Maratha rule : 18 th century AD : : : Renovated by Gopinath Trust Board. :
, , , , , , , , , , , , , , , , , , ,	SINGLE /MULTIPLE : Multiple
Public : Archaeological Survey of India / State Archaeology Department / Any Other (Please specify)	: Endowment Department, Govt. of Orissa.
Private Any other (Please specify) Name Address Phone 7. Association	 Gopinath Trust Board. Krushan Chandra Sahu (Chief) Gurukrupa Ashram, Lokanath Road, Puri,
WITH EVENTS In History In Rituals In Building Construction Any other (specify) WITH PERSONS Patron	 According to the Chief of Trust board, it has built during the Gajapati period. Dolapurnima, Nandautsava, Tandula mahotsava, Damodara utsava, Gamha purnima etc. Endowment Department, Govt. of Orissa & Gopinath Trust Poord
Architect / Engineer Any other (specify)	Trust Board. : :
8. Statement of Significance	
Architectural Archaeological Historical Religious Any other (specify)	 ∴ Architectural ∴ Archaeological ∴ ∴ On the basis of the Characteristic architectural features of the temple within the matha complex and iconography of enshrines deity, the Matha can be assigned to the to 18th century AD.

SECTION II: DESCRIPTION

9. Physical Description and Decor	ative Features			
Context Urban / Rural Setting Surroundings	* Drawings (Attach extra sheet if necessary) : No : Urban Setting			
	Stand in Isolation Street Integral part of a Landscape / Street / Complex :			
 Quantification 				
Area Dimension (LxBxH)	92.00 mtrs x 72.00 mtrs x 2.10 mtrs (compound wall) (m / cm/ feet / inch)			
Number of Blocks Number of Storys	10 rooms Single			
 Spatial Organization 				
Orientation :	The matha is facing towards east			
Allocation of Spaces	92.00 mtrs (L) x 72.00 mtrs (W)			
ARCHITECTURAL STYLE • Ornamentation				
Exteriors	Within the monastery complex there is a temple which has two <i>Udyota simhas</i> and the doorjambs is carved with five plain vertical bands. At the base of doorjambs there are two <i>Khakhara mundi</i> pilasters.			
Interiors	: Plain			
Movable Collections	Image of Madana Mohana, Chaitanya, bronze Aditya, and an image of Balaram are kept in the matha berandah.			
* Any Other (specify)	Out of 10 rooms of the monastery, five rooms are totally damaged. One room is used for ritualistic purpose and other four rooms have been let out.			
10. Construction Technology				
Structural System Building Techniques Material of Construction	Sing storeyed monastery Ashlar dry Masonry Sand stone & laterite			
11. Condition Assessment				
In General Good / Fair	Good			
Sign of Deterioration Serious Deterioration Danger of Disappearance				
In Dulat (Attack and a land of	A			

In Brief (Attach extra sheet if necessary):

The Matha is in good condition due to renovation work. The fire rooms which are not in used are totally damaged.

12. Threats to	the Property				
		Na Na	atural		
			egligence		
			andalism		
		U Ur	ban Pressures		
x	x x x x x x x x	xxxx	xxxxxxx	x	$x \times x \times x \times x \times x$
	<u>s</u>	ECTION	<u>I III:</u> REFEREN	ICES	
13. Reference	Sources (publishe	ed and ur	npublished textua	al details)	
1.					
2.					
14. Photograp	ons	(at	tach list as in na	ne 6 in case of n	nultiple photographs)
Dhata Dafara		. (41	tacii iist as iii pa	ge o, in case of h	iditiple priotographs)
Photo Reference CAPTION	nce	:			
OAI HOIL		•			
15. Audio / Vi	deo				
			(related t	o rituals / perform	nance / festivals etc.)
Reference		:			
DESCRIPTION	N	:			
16. Maps/Plan	ns/Drawings				
17. Listers					
NAME :	B. B. Satpatty		NAME :		
18. Reviewers	S				
NAME :	Dr. S. Pradhan		NAME:		
COMMENTS			COMMENTS:		