

1. Name

Janpath, New Delhi -110 001, www.ignca.gov.in


Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/SIR-217

SECTION I: IDENTIFICATION

Present Past Other Name (if any):	: Markundeshwar Mahadev Mandir :
2. Location	
LONGITUDE 73 ⁰ 10 ['] E	LATITUDE 27 ⁰ 17 ['] N
Address	Achalgarh, Mount Abu, Sirohi
	: Village (village code) Post : Mount Abu District: Sirohi State : Rajasthan PIN: 307501
Approach	: The Temple is situated at Mount Abu in Sirohi. It is 90 km. away from Sirohi district. It is well connected by regular bus service.

3. Property Type



4. Property Use

	ABANDONED / IN USE : In use
Present	: Religious
Past	: Religious
5. Age (Source)	
PERIOD	: 17 th Century AD
YEARS	:
Precise date of Construction Completion	
Subsequent changes	
Destruction / Demolition	
6. Ownership / Level of Protection	n
	SINGLE /MULTIPLE :
Public : Archaeological Survey of	:
India / State Archaeology	
Department / Any Other (Please	
specify)	
Private	: Dev Sthan Vibhag Board, Sirohi (Raj.)
Any other (Please specify) Name	
Address	
Phone	:
7. Association	
WITH EVENTS	
In History	:
In Rituals	:
In Building Construction	:
Any other (specify)	: Living temple
WITH PERSONS	
Patron Architect (Engineer	
Architect / Engineer Any other (specify)	· ·
Any other (specify)	
8. Statement of Significance	
Architectural	
Archaeological	

Historical Religious Any other (specify)

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features			
•	Context Urban / Rural Setting Surroundings		 * Drawings (Attach extra sheet if necessary) Rural setting surroundings Stand in Isolation Integral part of a Landscape / Street / Complex
•	Quantification Area Dimension (L x B x H) Number of Blocks Number of Storys	:	(m / cm/ feet / inch) 01 01
•	Spatial Organization Orientation Plan Allocation of Spaces	:	The Temple is oriented east-west and faces the west
•	RCHITECTURAL STYLE Ornamentation Exteriors Interiors Movable Collections Ny Other (specify)	::	Pointed arch openings. Shiva Lingam and Shiva family

10. Construction Technology

Structural System	:	Nagara Style
Building Techniques	:	Trabeate
Material of Construction	:	Stone and plaster

11. Condition Assessment

In General	Good / Fair Good	

\checkmark	

Sign of Deterioration Serious Deterioration Danger of Disappearance

In Brief (Attach extra sheet if necessary):

Discoloration, blackening, peeling of plaster etc.

12. Threats to the Property

✓ Natural
 ✓ Negligence
 ✓ Vandalism
 Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	
	(attach list as in page 6, in case of multiple photographs)
Photo Reference	
CAPTION	
15. Audio / Video	
	(related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS