

Janpath, New Delhi -110 001, <u>www.ignca.gov.in</u>

# Documentation format for Archaeological / Heritage Sites / Monuments

### Serial No.: OR / KDA/ BSR- 120

1. Name	SECTION I : IDENTIFICATION
Present Past Other Name (if any): 2. Location	<ul> <li>Minor Laterite Temple –III, Old Town, Bhubaneswar</li> <li></li> <li></li> </ul>
LONGITUDE 85 <sup>0</sup> 50'05" E	LATITUDE 20 <sup>0</sup> 14'17" N ELEVATION 91 ft
Address	: Village (village code) Post : Old Town Tehsil: Bhubaneswar State : Orissa Hata Sahi Road ,Old Town Via: Bhubaneswar District: Khurda PIN: 751002
Approach	: The temple is located on the right side of the Hata Sahi Road, at a distance of 100 mtrs north of Lingaraja temple.
3. Property Type	
Buildings         Palace         Fort         Citadel         Govt. building         Railway station         Defence building         Industrial building         Other public buildings         Residential building	Religious structures       Other Structures         Temple       Wall         Mosque       Gateway         Minar       Pillar         Church       Others (specify)         Monastery       Stupa         Tomb, Mausoleum
Engineering structure         Bridge         Tunnel         Other engineering structure	Open space and related structuresNote:Public square Park or garden Graveyard Baolis, Well Tank CaveOn both sides of the Hata Sahi Road there are four dilapidated and abandoned temples. All the temples are of identical size, features and material that is laterite. In the absence of any definite identity the temples have been documented under the title Minor laterite temples on account of their size and material.

		ABANDONED / IN USE : Abandoned
Present	:	It is a non-living temple and the presiding deity is missing now.
Past	:	Could not be ascertained.
5. Age (Source)		
PERIOD	:	Suryavamsi Gajapati rule.
YEARS	:	14 <sup>th</sup> /15 <sup>th</sup> century A.D.
Precise date of Construction	:	Last quarter of the 14 <sup>th</sup> century A.D. and first quarte of the 15 <sup>th</sup> century A.D.
Completion	:	
Subsequent changes	:	
Destruction / Demolition	:	
6. Ownership / Level of Protection	on	
		SINGLE /MULTIPLE :
Public : Archaeological Survey of	:	
India / State Archaeology		No Claimant
Department / Any Other (Please		
specify)		
Private	:	
Any other (Please specify)	:	
Name	:	
Address	:	
Phone	:	
7. Association		
WITH EVENTS		
In History	:	
In Rituals	:	
In Building Construction	:	Local people believe that this temple was erected ove
-		the burial of the family members of the royal family of Faridapur of unknown identity. So it was a <i>samadh</i> (burial) temple
Any other (specify)	:	
WITH PERSONS		
Patron	:	
Architect / Engineer	:	
Any other (specify)	:	Locals have not shown any concern for the temple.
8. Statement of Significance		, , , , , , , , , , , , , , , , , , ,
Architectural Archaeological Historical Religious	~	Architectural
Any other (specify)	:	On the basis of the architectural features and building materials, the temple can be dated to the 14 <sup>th</sup> /15 <sup>th</sup> centur, A.D.

# **SECTION II: DESCRIPTION**

#### 9. Physical Description and Decorative Features \* **Drawings** (Attach extra sheet if necessary) : No Context **Urban / Rural Setting** Urban setting 2 Surroundings Stand in Isolation Street Integral part of a Landscape / Street / Complex : Quantification Area Dimension ( $L \times B \times H$ ) 2.00 mtrs x 1.80 mtrs x 5.50 mtrs (height of the visible : portion from *jangha* to *mastaka*.) (m / cm/ feet / inch) Number of Blocks 2 One Number of Stories ---• **Spatial Organization** Orientation The temple is facing towards east. : Plan The *vimana* is square on plan and have a shallow porch : measuring 0.20mtrs in lengths. 2.00mtrs x 1.80mtrs in length and width respectively. Allocation of Spaces : ARCHITECTURAL STYLE Ornamentation • Exteriors : Plain Interiors plain : Movable Collections \* **Any Other** (specify) The temple is *trianga bada* in elevation. : **10.** Construction Technology Rekha vimana of impoverished Kalingan Order. Structural System : Building Techniques : Ashlar dry masonry. Material of Construction Laterite : 11. Condition Assessment In General Good / Fair : Fair $\checkmark$ | Sign of Deterioration ✓ Serious Deterioration

### In Brief (Attach extra sheet if necessary):

✓ Danger of Disappearance

Rain water seepage into the sanctum due to cracks. The temple is totally covered by creepers and lichens. Accumulation of earth and dirt are found all around the temple and the temple is buried up to the *jangha* portion. It is also encroached by the shops in eastern side and residential wall and building in western and southern sides.

# 12. Threats to the Property

✓	Natural
✓	Negligence
✓	Vandalism
✓	Urban Pressures

# **SECTION III:** REFERENCES

13. Reference Sources (published and unpublished textual details)				
1.				
2.				
14. Photogra	phs: 02 nos			
		(attach list as in page 6, in case of multiple photographs)		
Photo Refere CAPTION	nce			
15. Audio / Vi	deo			
Reference DESCRIPTIO	N	(related to rituals / performance / festivals etc.)		
16. Maps/Plans/Drawings				
17. Listers				
NAME :	A.R Sahoo.	NAME :		
18. Reviewers	\$			
NAME : COMMENTS	Dr. S. Pradhan	NAME : COMMENTS :		