

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: OR / KDA/ BSR- 154 **SECTION I: IDENTIFICATION** 1. Name Sisiresvara Temple, Bhubaneswar, Dist. - Khurda Present Past Other Name (if any): 2. Location **LONGITUDE** 85⁰ 50' 27 E 20⁰ 15' 57" N LATITUDE **ELEVATION** 52 ft **Address** Village (village code) Old Town Post: Old Town Via: Bhubaneswar **Tehsil:** Bhubaneswar **District:** Khurda State: Orissa **PIN**: 751002 **Approach** The temple is located within the precinct of Vaitala temple, on the left side of the road leading from Mausima chowk to Badhibanka chowk. 3. Property Type **Buildings** Religious structures Other Structures Palace Wall Temple Fort Mosque Gateway Citadel Minar Pillar Govt. building Church Others (specify) Railway station Monastery Defense building Stupa Industrial building Tomb, Mausoleum Other public buildings Residential building Engineering structure Open space and related Note: structures It has a rekha vimana and the Bridge Public square jagamohana has a flat terraced Park or garden Tunnel roofed structure with Other engineering structure Graveyard clerestory in between two tire Baolis, Well roof of early Kalingan order. Tank Cave

4. Property Use ABANDONED / IN USE: In use Present Living temple, the presiding deity is a Sivalinga within a circular yonipitha. **Past** Worshipped 5. Age (Source) PERIOD Bhaumakara rule YEARS 8th century AD First half of the 8th century AD **Precise date of Construction** Completion Repaired under the X & XI Finance Commission Subsequent changes Award by Orissa State Archaeology. **Destruction / Demolition** 6. Ownership / Level of Protection SINGLE /MULTIPLE : MULTIPLE **Public**: Archaeological Survey of: Protected Monument of Archaeological Survey of State Archaeology India. Department / Any Other (Please specify) **Private** Any other (Please specify) Lingaraja Temple Management Trust Name Address Archaeological Survey of India, Bhubaneswar Circle, 153 VIP Area, Navapali, Bhubaneswar, Orissa Phone 0674 2558170 7. Association WITH EVENTS In History In Rituals In Building Construction Any other (specify) WITH PERSONS Patron Now the Archaeological Survey of India (Chief priest.) Architect / : Engineer Any other (specify) Lingaraja Temple Management Trust

8. Statement of Significand	ce	
Architectural Archaeological	· · · · · · · · · · · · · · · · · · ·	Architectural
Historical Religious	· ✓	Religious
Any other (specify)	:	On architectural ground and sculptural embellishments, the temple is contemporaneous with the Vaital temple and is assign to the last half of the 8 th century A.D.

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features				
Context Urban / Rural Setting Surroundings	:	* Drawings (Attach extra sheet if necessary): No Urban setting		
		Stand in Isolation Complex Integral part of a Landscape / Street / Complex :		
 Quantification 				
Area Dimension (LxBxH)	:	10.60 mtrs x 5.50 mtrs x 8.00 mtrs (approximately) (m / cm/ feet / inch)		
Number of Blocks Number of Storys	: :	Two 		
Spatial Organization				
Orientation	:	Facing towards east.		
Plan	:	The <i>vimana</i> is square on plan and the <i>jagamohana</i> is rectangular and both stand over a low platform.		
Allocation of Spaces	:	26.80 mtrs (L) x 23.05 mtrs (B)		
ARCHITECTURAL STYLE • Ornamentation				
Exteriors	:	The temple is decorated with architectural motifs like <i>vajramundi, chaitya</i> motifs; scroll work, floral motifs, narrative scenes from of Mahabharata, animal processions and sculptures like various aspects of Siva, Ganesa, Kartikeya, Mahishamardinee Durga, amorous and erotic figures.		
Interiors	:	Plain		
Movable Collections * Any Other (specify)	:	It is a <i>pancharatha</i> temple having <i>triangabada</i> in elevation.		
10. Construction Technology				
Structural System	:	The <i>vimana</i> is a <i>rekha</i> temple and the <i>jagamohana</i> is a flat roofed of the early of <i>Kalingan</i> order.		
Building Techniques		Ashlar dry masonry		
Material of Construction	:	Sandstone used for the temple and laterite for the		
44.0 1111		foundation and compound wall.		
11. Condition Assessment				
In General Good / Fair	:	Fair		
✓ Sign of Deterioration Serious Deterioration Danger of Disappearance				

In Brief (Attach extra sheet if necessary):

The sculptures are deteriorated due to weathering; northern side of the temple is used as garbage yard by local resident. Proper attention by the concern authorities has not been given to this one of the ancient most temples in Orissa.

12. Threats to	o the Property	
.		✓ Natural Negligence Vandalism ✓ Urban Pressures X X X X X X X X X X X X X X X X X X X
^ ^ ^ ^ ^ ^ /		
	<u>5E(</u>	CTION III: REFERENCES
13. Reference	Sources (published	and unpublished textual details)
 Debala M T.E Dona 	litra, 1958, <i>Bhubanes</i> v Ildson, 1987, <i>Hindu te</i>	ology in Orissa, Vol I, New Delhi. wara, New Delhi. mple Art of Orissa, Vol I, Leiden. Orissa District Gazeteers, Puri, Cuttack.
14. Photogra	phs: 24 nos	
Photo Refere CAPTION 15. Audio / Vi		(attach list as in page 6, in case of multiple photographs):
		(related to rituals / performance / festivals etc.
Reference DESCRIPTIO		: :
16. Maps/Plai	ns/Drawings	
NAME:	Jaya Shankar Naik	NAME:
18. Reviewers	s	
NAME:	Dr. S. Pradhan	NAME: