

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS Janpath, New Delhi -110 001, <u>www.ignca.gov.in</u> Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: OR / KDA/ BSR- 168

1. Name	SECTION I : IDENTIFICATION			
Present Past Other Name (if any): 2. Location	 Astasambhu Siva Temple No-III, Bhubaneswar, DistKhurda 			
LONGITUDE 85 ⁰ 51'18" E	LATITUDE 20 ⁰ 14'62" N ELEVATION 107 ft.			
Address	: Village (village code) Post : Old Town Tehsil: Bhubaneswar State : Orissa Uttaresvara Temple precinct Via: Bhubaneswar District: Khurda PIN: 751002			
Approach 3. Property Type	: It is located on the northern embankment of Bindu Sagara Tank and within the Uttaresvara temple precinct. It is about 200 mtrs north-west of Anantabasudev temple. The temple is surrounded by Godavari tank in the east, Uttaresvara temple compound wall in west, Astasambhu Siva Temple No- II in north and Bindusagar tank in the south beyond the compound wall.			
Buildings Palace Fort Citadel Govt. building Railway station Defense building Industrial building Other public building Residential building	Religious structures Other Structures Image: Temple Wall Mosque Gateway Minar Pillar Church Others (specify) Monastery Stupa Tomb, Mausoleum			
Engineering structure Bridge Tunnel Other engineering structure	Open space and related structuresNote:Public squareInUttaresvaraSivatemple precinct there are eight temples of identical size and dimension locally known asBaolis, WellFive of them are arranged in one alignment, are also known as			

Cave

Panchu Pandava. This temple also one among them and have a *rekha vimana*. It is *pancharatha* on plan and *triangabada* in elevation and on the basis of its architectural feature, the temple can be dated to the 10th century A.D.

4. Property Use

		ABANDONED / IN USE : Abandoned
Present Past	:	It is a non-living temple. Worshipped
5. Age (Source)		
PERIOD	:	Somavamsi rule
YEARS	:	10 th century A.D.
Precise date of Construction	:	Third quarter of the10 th century A.D.
Completion	:	
Subsequent changes	:	The temple was repaired by Orissa State Archaeology under X and XI Finance Commission Award.
Destruction / Demolition	:	
6. Ownership / Level of Protection	on	
		SINGLE /MULTIPLE : Single
Public : Archaeological Survey of India / State Archaeology Department / Any Other (Please specify)	:	
Private	:	Ratnakara Gargabatu
Any other (Please specify)	:	
Name	:	Ratnakara Gargabatu
Address	:	Godipokhari Šahi OldTown, Bhubaneswara, Pin-751002
Phone	:	
7. Association		
WITH EVENTS		
In History	:	
In Rituals	:	
In Building Construction	:	
Any other (specify)	:	
WITH PERSONS		
Patron	:	Originally the Somavamsis but now Ratnakara Garga batu and his family
Architect / Engineer	:	
Any other (specify)	:	
8. Statement of Significance		
Architectural	~	Architectural

Archaeological	:	
Historical	:	
Religious	1	Religious
Any other (specify)	:	On the basis of its architectural features and motifs, it can be dated to the 10 th century A.D.

SECTION II: DESCRIPTION

 Context Urban / Rural Setting 	* Drawings (Attach extra sheet if necessary): No : Urban setting		
Surroundings	Stand in Isolation Complex Integral part of a Landscape / Street / Complex :		
 Quantification Area Dimension (L x B x H) 	: 2.55 mtrs X 2.10mtrs X 4.61mtrs		
Number of Blocks Number of Storys	(m / cm/ feet / inch : One block :		
 Spatial Organization Orientation Plan 	 Facing towards east The <i>vimana</i> is square on plan with a frontal porch of 0.45 mtrs. 		
Allocation of Spaces	:		
ARCHITECTURAL STYLE Ornamentation			
Exteriors	: The <i>parsvadevatas</i> niches which are decorated with <i>talagarbhika</i> and <i>urdhagarbhika</i> of <i>khakhara</i> order Above the niche <i>Bho</i> motifs are found. Right above the door jambs there is a <i>Sukanasa</i> with a <i>khakharamundi a</i> the center being flanked by two miniature <i>rekhadeulas</i> which is surmounted by a stylized <i>chaitya</i> and <i>udyotasimha</i> .		
Interiors	: plain		
Movable Collections * Any Other (specify)	 The temple is <i>pancharatha</i> on plan and <i>triangabada</i> in elevation 		
10. Construction Technology			
Structural System	: It has a single <i>rekha vimana</i> with a shallow porch in front.		
Building Techniques Material of Construction 11. Condition Assessment	Ashlar dry masonryCoarse grained Sandstone		

\checkmark	S
	S
	D

Sign of Deterioration : Serious Deterioration Danger of Disappearance

In Brief (Attach extra sheet if necessary):

Percolation of water into the sanctum from the cracks in the roof threats the property.

12. Threats to the Property

\checkmark	Natura
	Neglige
\checkmark	Vandal
\checkmark	Urban

al ence lism Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photogra	aphs	
	•	(Attach list as in page 6, in case of multiple photographs)
Photo Refere CAPTION	nce :	
15. Audio / V	/ideo	
		(Related to rituals / performance / festivals etc.)
Reference DESCRIPTIC	: DN :	
16. Maps/Pla	ans/Drawings	
17. Listers		
NAME :	Ashis Ranjan Sahoo	NAME :

NAME :	Ashis Ranjan Sahoo	NAME :	
		18. Reviewers	
NAME :	Dr. S. Pradhan	NAME :	
COMMENTS		COMMENTS :	