

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: OR / BDK- 02

	SECTION I: IDENTIFICATION
1. Name	
Present Past Other Name (if any):	 Bakresvara Mahadev Temple, Kaupur (Bazar Sahi), Dist-Bhadrak
2. Location	
LONGITUDE 86 ⁰ 25'48" E	LATITUDE 21 ⁰ 07'46" N ELEVATION 52 ft
Address	: Village (village code) Post: Kaupur Tehsil: Bhadrak State: Orissa Bazar Sahi, Kaupur Via: Bhadrak District: Bhadrak PIN: 756113
Approach	: It is situated on the right side of the road leading from Bhadrak to Anandapur and on the right bank of the river Salandi. It is about 15 kms north-west of Bhadrak.
3. Property Type	
Buildings Palace Fort Citadel Govt. building Railway station Defence building Industrial building Other public building Residential building	Religious structures Temple Mosque Minar Church Monastery Stupa Tomb, Mausoleum Religious structures Wall Gateway Pillar Others (specify) Sculpture Note: It is a recently made R.C.C. building, having a sanctum
Engineering structure Bridge Tunnel Other engineering structure	Open space and related structuresand open Mandapa. But it houses a four armed Ganesa image and an Akasha Chakra.Park or gardenThey are assigned to the 8th century AD.Baolis, WellTankCave

4. Property Use		
		ABANDONED / IN USE: In use
Present	:	It is a living temple and the presiding deity is a Sivalinga within a circular <i>yonitha</i> and both are made of chlorite.
Past	:	Not known
5. Age (Source)		
PERIOD YEARS Precise date of Construction Completion Subsequent changes Destruction / Demolition	: : : : : : : : : : : : : : : : : : : :	Bhaumakara rule 8 th century AD 8 th century AD
6. Ownership / Level of Protection	n	
		SINGLE /MULTIPLE : Multiple
India / State Archaeology Department / Any Other (Please specify)	:	No claimant
Private	:	
Any other (Please specify)	•	Under the care and maintenance of the villagers of Bazara Sahi, Kaupur.
Name	:	
Address	:	
Phone	:	
7. Association		
WITH EVENTS In History		
In Rituals	:	
In Building Construction	:	
Any other (specify)	:	
WITH PERSONS		Villagrama of the Domesta Cabi Kawawa
Patron Architect / Engineer	:	Villagers of the Bazara Sahi,Kaupur.
Any other (specify)	:	
8. Statement of Significance		
Architectural Archaeological Historical Religious Any other (specify)	: : : : : : : : : : : : : : : : : : : :	Archaeological Religious The akasha chakra found here indicates that earlier there was a huge Vishnu temple, close to the present temple. The image of Ganesa ichnographically can be dated to the 8 th century AD.

SECTION II: DESCRIPTION

9. Physical Description and Dec	orat	ive Features		
 Context Urban / Rural Setting Surroundings 	:	* Drawings (Attach extra sheet if necessary) : No Rural Setting		
Garround		Stand in Isolation Integral part of a Landscape / Street / Complex :	Stand in Isolation	
 Quantification Area Dimension (L x B x H) 	:	4.90 mtrs x 1.85 mtrs x 3.5 mtrs		
Number of Blocks Number of Storys	:	Two, consisting of a sanctum and	(m / cm/ feet / inch) d open <i>mandapa.</i>	
 Spatial Organization Orientation Plan Allocation of Spaces 	: :	Facing towards west Both the sanctum and mandapa 4.90 mtrs x 1.85 mtrs in length ar	•	
• Ornamentation Exteriors Interiors Movable Collections * Any Other (specify)	:	Devoid of any decoration. Plain Four armed seated image of G Akasha Chakra having four arm centre. The temple is a recent one but h and open mandapa.	ned Visnu image at the	
10. Construction Technology				
Structural System Building Techniques Material of Construction	: : :	It is a modern R.C.C. shrine hand open <i>mandapa</i> , and housing English bond with cement plaster Bricks are used for the temple Ganesa & Akasha chakra is made	g old images. r. e while the image of	
11. Condition Assessment				
In General Good / Fair	:	Fair		
✓ Sign of Deterioration Serious Deterioration Danger of Disappearance				
In Priof (Attack overs shoot if no		20m/):		

In Brief (Attach extra sheet if necessary):

The image of Ganesa is applied with a thick coat of oil paint and the *Akasha chakra* is given a coat of lime wash, which disfigure the aesthetic beauty of the sculptures.

12. Threats to	the Property	
	\checkmark	Natural
	√	Negligence
	✓	Vandalism Urban Pressures
		_ Orban Pressures
x x x x x x x		× × × × × × × × × × × × × × × × × × ×
	<u>SEC1</u>	ION III: REFERENCES
13 Reference	Sources (nublished an	d unpublished textual details)
	Codices (published al	d dripabilistica textual details)
1. 2.		
۷.		
14. Photograp	ohs :	6 Nos.
		(attach list as in page 6, in case of multiple photographs
Photo Referei	nce :	
CAPTION	:	
15 Audio / Vid	doo	
15. Audio / Vi	ueo	(related to rituals / performance / festivals etc
Reference		(volution to manier ponormanies viocavane etc
DESCRIPTION	J	
D2001(III 1101	•	
16. Maps/Plan	s/Drawings	
17. Listers		
NAME:	Ashis Ranjan Sahoo	NAME:
18. Reviewers	;	
NAME :	Dr. S. Pradhan	NAME: