

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: OR / BDK- 04

| | SECTION I: IDENTIFICATION | N |
|---|--|--|
| 1. Name | | |
| Present Past Other Name (if any): 2. Location | : Chandi Temple, Kaupu Dist - Bhadrak : : | ır (Chandipur Sahi), |
| 2. Location | | |
| LONGITUDE 86°25'48" E | LATITUDE 21 ⁰ 07'48" N | ELEVATION 52 ft. |
| Address | : Village (village code) Post : Kaupur Tehsil: Bhadrak State : Orissa | Chandipur Sahi,Kaupur Via: Bhadrak District: Bhadrak PIN: 756113 |
| Approach | right side of the ro | orth-west of Bhadrak town and leading from Bhadrak to situated on the right bank of the |
| 3. Property Type | | |
| Buildings Palace Fort Citadel Govt. building Railway station Defence building Industrial building Other public buildings | Religious structures ✓ Temple Mosque Minar Church Monastery Stupa Tomb, Mausoleum | Other Structures Wall Gateway Pillar Others (specify)sculpture Note: It is a recently made R.C.C. |
| Residential building Engineering structure Bridge Tunnel Other engineering structure | Open space and related structures Public square Park or garden Graveyard Baolis, Well Tank Cave | shrine, but houses a few rare and important Saivite sculptures. Iconographically they can be dated to the 11 th century AD. |

| 4. Property Use | |
|--|--|
| | ABANDONED / IN USE : In use |
| Present | : It is a living temple and the presiding deities are two Ganagadharamurti, one eight armed goddess and a Chlorite Sivalinga within a circular <i>Yonitpitha</i> made of cement concrete. |
| Past | : Not known |
| 5. Age (Source) | |
| PERIOD YEARS Precise date of Construction Completion Subsequent changes | Somavamsi rule 11th century AD Early part of the 11th century AD The images are now kept inside a modern R.C.C. |
| Destruction / Demolition | shrine, constructed by the villagers. : |
| 6. Ownership / Level of Protection | on |
| | SINGLE /MULTIPLE : Multiple |
| Public: Archaeological Survey of India / State Archaeology Department / Any Other (Please specify) | : No claimant |
| Private Any other (Please specify) | :: The temple is under the care & custody of Chief Priest, Juli Chakravarti. |
| Name Address Phone 7. Association | : : At/Po – Kaupur, Dist. – Bhadrak, Orissa : |
| WITH EVENTS In History In Rituals In Building Construction Any other (specify) WITH PERSONS Patron Architect / Engineer Any other (specify) | : : : : Originally by Somavansi but now under the care of the Chief Priest, Juli Chakravarti : : |
| 8. Statement of Significance | |
| Architectural Archaeological Historical Religious Any other (specify) | : |

rarely found in Orissa. Iconographically it can be date to the early part of the $11^{\mbox{\scriptsize th}}$ century A.D.

SECTION II: DESCRIPTION

| 9. Physical Description and Decorative Features | | |
|--|---|--|
| Context Urban / Rural Setting Surroundings | * Drawings (Attach extra sheet if necessary) : No : Rural Setting | |
| | Stand in Isolation Stand in Isolation Integral part of a Landscape / Street / Complex : | |
| Quantification | | |
| Area Dimension (LxBxH) | : 4.20 mtrs x 5.00 mtrs x 3.50 mtrs (m / cm/ feet / inch) | |
| Number of Blocks Number of Storys | : Two, sanctum preceded by an open pillared <i>mandapa</i> . : | |
| Spatial Organization | | |
| Orientation | : Facing towards east | |
| Plan | : Rectangular on plan | |
| Allocation of Spaces | : 4.20 mtrs x 5.00 mtrs in length and breadth respectively. | |
| ARCHITECTURAL STYLE | | |
| • Ornamentation | | |
| Exteriors | : Both the exterior and interior are plain in this modern shrine. | |
| Interiors | : | |
| Movable Collections | : Two images of Gangadharamurti of Siva, two Sivalingas and one eight armed goddess are housed inside the temple. | |
| * Any Other (specify) | : On the basis of iconogarphical features of the images, they can be dated to the 11 th century AD. | |
| 10. Construction Technology | | |
| Structural System | : It is a modern R.C.C. shrine with a rectangular sanctum and open pillared mandapa. | |
| Building Techniques Material of Construction | English Bond with cement mortar.Brick | |
| 11. Condition Assessment | | |
| In General Good / Fair | : Fair | |
| Sign of Deterioration Serious Deterioration Danger of Disappearance | | |
| In Brief (Attach extra sheet if nece | essary): | |

| 12. Threats to | the Property | |
|--------------------------|---------------------------------------|---|
| | ✓ ✓ ✓ | Natural Negligence Vandalism Urban Pressures |
| x x x x x x x | X X X X X X X X X X X X X X X X X X X | x x x x x x x x x x x x x x x x x x x |
| | SECT | TION III: REFERENCES |
| 13. Reference | Sources (published an | nd unpublished textual details) |
| 1. R.P. Moha | apatra, 1986, <i>Archeolgo</i> | oy in Orissa, Vo. II, New Delhi. |
| 14. Photograp | ohs : | 05 Nos. |
| Photo Referei CAPTION | nce : | (attach list as in page 6, in case of multiple photographs) |
| 15. Audio / Vie | deo | (related to rituals / performance / festivals etc.) |
| Reference DESCRIPTION | : I : | (related to fituals / performance / lestivals etc.) |
| 16. Maps/Plans/Drawings | | |
| 17. Listers | | |
| NAME : | Ashis Ranjan Sahoo | NAME: |
| 18. Reviewers | | |
| NAME: COMMENTS | Dr. S. Pradhan | NAME: COMMENTS: |

People regularly apply vermilion and oil over the images. This distorts the aesthetic beauty of the images.