

Other engineering structure

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: OR / CTC - 66 **SECTION I: IDENTIFICATION** 1. Name Present Brahma Temple, Niali, Dist. – Cuttack Past Other Name (if any): 2. Location 86⁰ 03' 46" E. 20⁰ 08' 24" N. LONGITUDE LATITUDE **ELEVATION** 31ft **Address** Village (village code) Niali Post : Niali Via: Niali Tehsil: Cuttack **District:** Cuttack State: Orissa **PIN:** 754004 Approach The temple, on the left bank of the river Prachi, a distributary of the river Mahanadi is situated on the north-eastern sector of the village Niali, which can be approached from the Niali-Madhava road (S.H.no-60). 3. Property Type **Buildings** Religious structures Other Structures Palace Temple Wall Fort Mosque Gateway Citadel Minar Pillar Govt. building Church Others (specify) Railway station Monastery Defence building Stupa Industrial building Tomb, Mausoleum Other public buildings Residential building Engineering structure Open space and related Note: structures The temple is a modern pidha Bridge Public square shrine rebuilt over the ruins of an Tunnel Park or garden earlier one. It enshrines an

> Graveyard Baolis, Well

Tank Cave extremely rare image of Bramha

and two detached Visnu images.

4. Property Use ABANDONED / IN USE: In use Present Living temple, the presiding deity is an image of Chaturmukha Brahma. He displays rosary in right hand and a spouted vase in the left hand. The image measures 0.62 mtrs x 0.35 mtrs x 0.30 mtrs in length, width and thickness respectively. Past Worshipped. 5. Age (Source) Earlier temple was built during the Sailodbhava rule PERIOD YEARS 7th century A.D. 7th century A.D. **Precise date of Construction** Completion Subsequent changes The present temple rebuilt on the ruins of an earlier shrine. **Destruction / Demolition** 6. Ownership / Level of Protection SINGLE /MULTIPLE : Multiple **Public**: Archaeological Survey of : Protected monument of Orissa state Archaeology. State Archaeology India / Department / Any Other (Please specify) Private Any other (Please specify) Under the care of the chief priest Surendra Mohapatra. Name Address Paryatan Bhawan, B.J.B. Nagar, Bhubaneswar, Orissa. **Phone** 0674-2432147 7. Association WITH EVENTS In History In Rituals ___ In Building Construction Any other (specify) WITH PERSONS Patron Presently under Orissa State Archaeology. Architect / Engineer Any other (specify) 8. Statement of Significance Architectural ✓ Architectural

Archaeological

The present temple dedicated to Bramha is extremely rare in

Archaeological

Any other (specify)

Historical Religious

Orissa but the sculpture on the basis of iconography can be assigned to the 7th century AD. The two detached images of Visnu, iconographically can be dated to the 12th century A.D.

SECTION II: DESCRIPTION

9. Physical Description and De	corative Features
 Context Urban / Rural Setting Surroundings 	* Drawings (Attach extra sheet if necessary) : No Rural Setting
Garroundings	Stand in Isolation Street Integral part of a Landscape / Street / Complex:
• Quantification Area Dimension (L x B x H)	: 10.00 mtrs x 6.00 mtrs x 7.25 mtrs
Number of Blocks	(m / cm/ feet / inch) : Two, consists of a <i>pidha vimana</i> and a R.C.C frontal
Number of Storys	mandapa. : N.A.
 Spatial Organization Orientation Plan Allocation of Spaces 	 Facing towards west. The <i>vimana</i> is square on plan whereas the frontal R.C.C. <i>mandapa</i> is rectangular. 10.00 mtrs x 6.00 mtrs in length and breadth respectively.
ARCHITECTURAL STYLE Ornamentation	
Exteriors Interiors Movable Collections	 Plain Pour- armed Visnu image - 1.00 mtrs (L) x 0.55 (W) mtrs X 0.25 mtrs (D) in dimension. Another broken four-armed Visnu image measuring 1.05 mtrs (L) x 0.50 mtrs (W) x 0.25 mtrs (D) are found along with images of Varaha, Mahavir Hanuman and an anchor stone.
* Any Other (specify)	:
10. Construction Technology	
Structural System	: Pidha vimana of impoverished Kalingan order & a R.C.C frontal mandapa.
Building Techniques Material of Construction	: Ashlar masonry: Stone and cement plaster.
11. Condition Assessment	
In General Good / Fair Sign of Deterioration Serious Deterioration	: Good

18. Reviewers NAME: COMMENTS	Dr. S. Pradhan	NAME: COMMENTS:
NAME:	Jaya Shankar Naik	NAME:
17. Listers		
16. Maps/Plan	s/Drawings	
DESCRIPTION	ı :	
Reference		(related to rituals / performance / festive
15. Audio / Vio	deo	(rolated to rituals / performance / feeting
Photo Referer CAPTION	nce :	
. A i notograp		Attach list as in page 6, in case of multiple photo
14. Photograp		, ,
		vin Orissa, Vol.I- I, New Delhi.
13. Reference	Sources (published and	unpublished textual details)
	SECTION	ON III: REFERENCES
x x x x	x x x x x x x x x x x x x	x x x x x x x x x x x x x x x x x x x
		Vandalism Urban Pressures
		Negligence
12. Tilleats to		Natural
	o the Property	
much mutilated		vation. However, the two detached Visnu images
	n a good state of preserv	ration Harvayan the two detected Viens images