INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

# Documentation format for Archaeological / Heritage Sites / Monuments

#### Serial No.: OR / KDA/ BSR- 128

	SECTION I : IDENTIFICATION		
1. Name			
Present Past Other Name (if any):	<ul> <li>Visnu Temple No-I, Muktesvara Temple Complex, Bhubaneswar, DistKhurda</li> <li></li> <li></li> </ul>		
2. Location			
LONGITUDE 85 <sup>0</sup> 50'26"E	<b>LATITUDE</b> $20^{\circ}14'33"N$ <b>ELEVATION</b> 52 ft.		
Address	<ul> <li>Village (village code)</li> <li>Post : Old Town</li> <li>Tehsil: Bhubaneswar</li> <li>State : Orissa</li> <li>Muktesvara Temple Complex, Old Town</li> <li>Via: Old Town</li> <li>District: Khurda</li> <li>PIN: 751002</li> </ul>		
Approach	<ul> <li>The temple is located within the precinct of Mukteswar temple, old town, and on the right side of the road leading from Bhubaneswar to Puri.</li> </ul>		
3. Property Type			
Buildings         Palace         Fort         Citadel         Govt. building         Railway station         Defence building         Industrial building         Other public buildings         Residential building	Religious structures       Other Structures         Image: Church       Image: Church         Ima		
Engineering structure         Bridge         Tunnel         Other engineering structure	Open space and related structures       Note :         Public square       It has a single rekha vimana with a shallow frontal porch of Graveyard         Graveyard       Kalingan order.         Baolis, Well       Tank         Cave       Cave		

		ABANDONED / IN USE : In use
Present	:	It is a living, temple and the presiding deity is V with seven hooded serpent crown and carrying <i>An</i> <i>Kalasa</i> in his hands.
Past	:	Worshipped
5. Age (Source)		
PERIOD		Somavansis rule
YEARS	:	10 <sup>th</sup> century AD
Precise date of Construction		To century AD
	:	
Completion	•	 Archaeological Curryov of India has repovered
Subsequent changes	•	Archaeological Survey of India has renovated preserved the temple.
Destruction / Demolition	:	
6. Ownership / Level of Protection	<u>n</u>	
		SINGLE /MULTIPLE : Single
	:	Protected Monument of Archaeological Survey
India / State Archaeology		India.
Department / Any Other (Please		
specify)		
Private	:	
Any other (Please specify)	:	
Name	:	
Address	:	Archaeological Survey of India, Bhubaneswar Ci 153, VIP Area, Nayapali, Bhubaneswar, Orissa
Phone	:	0674 -2558170
7. Association		
WITH EVENTS		
In History	:	
In Rituals	:	
In Building Construction		
Any other (specify)		
WITH PERSONS	•	
• WITH PERSONS Patron		Archaeological Survey of India.
	:	Archaeological Sulvey Of Illula.
Architect / Engineer	:	
Any other (specify)	•	
8. Statement of Significance		
Architectural		Architectural
Architectural Archaeological :	<i></i>	Architectural
Architectural Archaeological : Historical :		Architectural
Architectural Archaeological Historical Religious	<ul><li>I</li></ul>	Religious
Architectural Archaeological : Historical :		

# **SECTION II: DESCRIPTION**

Context Urban / Rural Setting Surroundings	* <b>Drawings (</b> Attach extra sheet if necessary) : No : Urban setting
Surroundings	Stand in IsolationComplexIntegral part of a Landscape /Street / Complex :
• Quantification	
Area Dimension (L x B x H)	: 2.45 mtrs x 2.15 mtrs x 4.70 mtrs ( <b>m</b> / cm/ feet / inch
Number of Blocks	: One
Number of Storys	:
Spatial Organization	
Orientation	: The temple is facing towards east.
Plan	: Square on plan.
Allocation of Spaces	:
ARCHITECTURAL STYLE  Ornamentation	
Exteriors	Plain except chaitya meddalion at the central raha above the parsvadevata niches and series of diminutive chaitya medallion in incipient stage found at the base of the gandi. Talagarbhika in parsvadevata niches are represented as khakharamundi design.
Interiors	: Plain
Movable Collections	: Nil
* Any Other (specify)	: The temple is <i>pancharatha</i> on plan and <i>triangabada</i> i elevation. The pabhaga has three plain moulding.
10. Construction Technology	
Structural System	: Rekha vimana of Kalingan order.
Building Techniques Material of Construction	: Ashlar dry masonry : Sand stone.
11. Condition Assessment	
In General Good / Fair	: Good
Sign of Deterioration	
Serious Deterioration Danger of Disappearance	

# In Brief (Attach extra sheet if necessary):

It is in a good state of preservation.

#### 12. Threats to the Property

Natural Negligence Vandalism Urban Pressures

#### **SECTION III:** REFERENCES

13. Reference Sources (published and unpublished textual details)					
1. 2.					
14. Photogra					
		(attach list as in page 6, in case of multiple photographs)			
Photo Refere CAPTION	nce :				
15. Audio / Vi	deo				
		(related to rituals / performance / festivals etc.)			
Reference DESCRIPTIO	N :				
16. Maps/Plans/Drawings					
17. Listers					
NAME :	Ashis Ranjan Sahoo	NAME :			
18. Reviewers					
NAME : COMMENTS	Dr. S. Pradhan	NAME : COMMENTS :			