

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: OR / KDA / BSR - 252

1. Name	SECTION 1: IDENTIFICATION
Present Past Other Name (if any): 2. Location	 Kapilesvara Temple (Temple No -123), Lingaraja Temple Complex, Bhubaneswar, Dist Khurda
LONGITUDE 85°50'05" E	LATITUDE 20°14'26" N ELEVATION 70 ft.
Address	: Village (village code) Post: Old Town Tehsil: Bhubaneswar State: Orissa Lingaraja Temple Complex Via: Old Town, Bhubaneswar District: Khurda PIN: 751002
Approach	: The temple is situated adjacent to the eastern enclosure wall of the Grand Lingaraja temple complex in Old Town, Bhubaneswar.
3. Property Type	
Buildings Palace Fort Citadel Govt. building Railway station Defence building Industrial building Other public building Residential building	Religious structures Temple Mosque Minar Church Monastery Stupa Tomb, Mausoleum Other Structures Wall Gateway Pillar Others (specify)
Engineering structure Bridge Tunnel Other engineering structure	Open space and related structures Public square Park or garden Graveyard Baolis, Well Tank Cave Note. The temple has a pidha vimana of impoverished Kalingan style.

4. Property Use

ABANDONED / IN USE: In use

Present: Living temple, the presiding deity is a Sivalinga within

a square *yonipitha* made of black chlorite.

Past : Worshipped.

5. Age (Source)

PERIOD : Suryavamsi Gajapati rule

YEARS : 16th century AD

Precise date of Construction : Second half of the 16th century AD

Completion : --Subsequent changes : ---

Destruction / Demolition: Now the crowing element of the temple is missing.

6. Ownership / Level of Protection

SINGLE /MULTIPLE: Multiple

Public: Archaeological Survey of : India / State Archaeology

Department / Any Other (Please

specify)

Protected monument of Archaeological Survey of

India.

Private : Lingaraja Temple Trust Board maintains the rituals of

the temple.

Any other (Please specify) : Endowment Department, Government of Orissa

manages the property of the temple.

Name : --

Address : Archaeological Survey of India, Bhubaneswar Circle,

153 - VIP Area, Nayapalli, Bhubaneswar, Orissa.

Phone : 0674- 2558170

7. Association

WITH EVENTS

In History : --

In Rituals : Sivaratri, Sankranti, Kartika Purnima, etc.

In Building Construction : ---

Any other (specify) : Thread ceremony, engagements, etc.

WITH PERSONS

Patron : Archeological Survey of India and Endowment

Department, Government of Orissa.

Architect / Engineer : --

Any other (specify) : Lingaraja Temple Trust Board

8. Statement of Significance

Architectural ✓ Architectural Archaeological

Historical

Religious ✓ Religious

Any other (specify)

On the basis of architectural style, the temple can be assigned to the second half of the $16^{\rm th}$ century A.D.

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features				
Context Urban / Rural Setting Surroundings	:	* Drawings (Attach extra sheet if necessary) No Urban setting		
Can can amg		Stand in Isolation Integral part of a Landscape Complex / Street / Complex :		
 Quantification Area Dimension (L x B x H) 	:	2.00 mtrs x 2.00 mtrs x 5.00 mtrs (approximate height) (m / cm/ feet / inch)		
Number of Blocks Number of Storys	:	One N.A.		
 Spatial Organization Orientation Plan Allocation of Spaces 	:	Facing towards west. A square <i>vimana that</i> stands over a platform of 0.70 mtrs in height. 158.49 mtrs x 141.73 mtrs in length and breadth respectively.		
• Ornamentation Exteriors Interiors Movable Collections * Any Other (specify)	: : : : : : : : : : : : : : : : : : : :	Devoid of any artistic decorations in the temple. Plain Nil The temple is <i>pancharatha</i> on plan and <i>triangabada</i> in elevation.		
10. Construction Technology Structural System Building Techniques Material of Construction	:	Pidha vimana of Kalingan order. Ashlar dry masonry Laterite is used for the construction of the temple and		
11. Condition Assessment	•	lime plaster applied later on.		
In General Good / Fair Sign of Deterioration Serious Deterioration Danger of Disappearance	:	Fair		

In Brief (Attach extra sheet if necessary):

Lichen and moss are noticed on the temple and at places the plaster is chipped off.

12. Threats to the Property			
Vatural Negligence Vandalism ✓ Urban Pressures ××××××××××××××××××××××××××××××××××××	x x x x x x x x x x x x x x x x x x x		
SECTION III: REFERENCES			
13. Reference Sources (published and unpublished textual details)			
 K. S. Behera, 2008, The Lingaraja Temple of Bhubane Delhi. 	swar, Art and Cultural Legacy, New		
 Debala Mitra, 1961, <i>Bhubaneswar</i>, ASI, New Delhi. 4. 			
14. Photographs: 04 nos			
Photo Reference : CAPTION : 15. Audio / Video	e 6, in case of multiple photographs)		
(related to	rituals / performance / festivals etc.)		
Reference : DESCRIPTION :			
16. Maps/Plans/Drawings			
17. Listers			
NAME : Jaya Shankar Naik NAME :			
18. Reviewers			
NAME: Dr. S. Pradhan NAME: COMMENTS:			