LINDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments


Serial No.: RJ/CRG - 153

SECTION I : IDENTIFICATION

1. Name		
Present Past Other Name (if any):	: Kund :	
2. Location		
LONGITUDE 74° 54' E	LATITUDE 24°32' N	
Address	: Sarneshwar Mahadev Mandi	ir, Gangrar
	: Village (village code)	
	Post: Gangrar	District: Chittaurgarh
	State: Rajasthan	PIN: 312901
Approach	: The Kund is situated near by mandir, Gangrar at Chittaurgarh fo 22 Km away from Chittaurgarh	ort in Chittaurgarh. It is

connected by regular bus services.

3. Property Type



4. Property Use

ABANDONED / IN USE

Present : Past :

5. Age (Source)

PERIOD	:	18 th Century AD
YEARS	:	
Precise date of Construction	:	
Completion	:	
Subsequent changes	:	
Destruction / Demolition	:	

6. Ownership / Level of Protection

SINGLE /MULTIPLE :

Public : Archaeological Survey of India / State Archaeology Department / Any Other (Please specify)	:	
Private	:	
Any other (Please specify)	:	
Name	:	
Address	:	

: √

7. Association

•	WITH EVENTS In History	:
	In Rituals	:
	In Building Construction	:
	Any other (specify)	:
•	WITH PERSONS	

Patron	:
Architect / Engineer	:
Any other (specify)	:

8. Statement of Significance

\checkmark	Architectural	: Rectangular 'Kund' having staircase
	Archaeological	
	Historical	
	Religious	
	Any other (specify)	:

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features _____

Context

* Drawings (Attach extra sheet if necessary)

	Urban / Rural Setting		Urban Setting
	Surroundings		
			Stand in Isolation
			Integral part of a Landscape / Street / Complex
•	Quantification		
	Area Dimension (L x B x H)	:	
			(m / cm/ feet / inch)
	Number of Blocks	:	
	Number of Storys	:	
•	Spatial Organization		
	Orientation	:	The Kund is oriented east- west and faces the west.
	Plan	:	
	Allocation of Spaces	:	

ARCHITECTURAL STYLE

•	Ornamentation	
	Exteriors	:
	Interiors	:
	Movable Collections	:
Ar	ny Other (specify)	:


10. Construction Technology

Structural System	:	Rectangular 'Kund' made up of rubble stone
Building Techniques	:	
Material of Construction	:	Stone etc.

1. Condition Assessment

In General


Good / Fair Good



In Brief (Attach extra sheet if necessary):

Badly damaged

12. Threats to the Property



SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	
Photo Reference	(attach list as in page 6, in case of multiple photographs)
CAPTION	
15. Audio / Video	
Reference	(related to rituals / performance / festivals etc.)
Kelelelice	
DESCRIPTION	
16. Maps/Plans/Drawings	

17. Listers

NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS