

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/KRL-319

| 1. Name | SECTION I : IDENTIFICATION | | |
|--|---|--|--|
| Present Past Other Name (if any): 2. Location | Shree Sita Ram Mandir | | |
| LONGITUDE 77 ⁰ 4 [°] E | LATITUDE 27 ⁰ 3 [°] N | | |
| Address | Near Bhairo jee Mandir, Toda Bhim, Karauli | | |
| Approach | Village (village code) Post : Toda Bhim State : Rajasthan The Temple is situated at Toda Bhim in Karauli district. It is 72 km. away from Karauli. It is well connected by regular bus services. | | |

3. Property Type

| Buildings | | Religious structures | _ | Other Structures |
|----------------------------|--------------|--|--|---|
| Palace | \checkmark | Temple | | Wall |
| Fort | | Mosque | | Gateway |
| Citadel | | Minar | | Pillar |
| Govt. building | | Church | | Others (specify) |
| Railway station | | Monastery | | |
| Defence building | | Stupa | | |
| Industrial building | | Tomb, Mausoleum | | |
| Other public buildings | | | | |
| Residential building | | | | |
| | | | | |
| Engineering structure | • | en space and related ructures | | te: This temple is made up on elevated platform. It has |
| Engineering structure | • | • | an | |
| | • | uctures | an don | elevated platform. It has |
| Bridge | • | <i>ructures</i> Public square | an don has by | elevated platform. It has nical superstructure. Temple a chhajja which is supported brackets. Inside temple has |
| Bridge Tunnel | • | uctures Public square Park or garden | an don has by pilla | elevated platform. It has nical superstructure. Temple a chhajja which is supported brackets. Inside temple has ars with capital giving support |
| Bridge Tunnel | • | uctures Public square Park or garden Graveyard | an don has by pilla to u | elevated platform. It has nical superstructure. Temple a chhajja which is supported brackets. Inside temple has ars with capital giving support upper structure. It has pointed |
| Bridge Tunnel | • | Public square Park or garden Graveyard Baolis, Well | an don has by pilla to u arcl | elevated platform. It has nical superstructure. Temple a chhajja which is supported brackets. Inside temple has ars with capital giving support upper structure. It has pointed hes. Capital of the pillars are |
| Bridge Tunnel | • | <i>uctures</i> Public square Park or garden Graveyard Baolis, Well Tank | an don has by pilla to u arcl dec | elevated platform. It has nical superstructure. Temple a chhajja which is supported brackets. Inside temple has ars with capital giving support upper structure. It has pointed |

4. Property Use

| | ABANDONED / IN USE : Abandoned |
|--|--|
| Present Past | : Religious |
| 5. Age (Source) | |
| PERIOD YEARS Precise date of Construction Completion Subsequent changes Destruction / Demolition | 18 th Century A.D. |
| 6. Ownership / Level of Protection | |
| India / State Archaeology Department / Any Other (Please specify) Private Any other (Please specify) Name Address Phone 7. Association | SINGLE /MULTIPLE : : : : : |
| WITH EVENTS In History In Rituals In Building Construction | Canopied Chhatri |
| Architectural Archaeological Historical Religious Any other (specify) | Canopied Chhatri |

SECTION II: DESCRIPTION

| 9. | 9. Physical Description and Decorative Features | | |
|----|---|---|--|
| • | Context Urban / Rural Setting Surroundings | | * Drawings (Attach extra sheet if necessary) Rural Setting Stand in Isolation Integral part of a Landscape / Street / Complex |
| • | Quantification Area Dimension (L x B x H) Number of Blocks Number of Storys | : | (m / cm/ feet / inch) 01 01 |
| • | Spatial Organization Orientation Plan Allocation of Spaces | : | The Temple is oriented North-South and faces the North |
| • | RCHITECTURAL STYLE Ornamentation Exteriors Interiors Movable Collections Ny Other (specify) | : | Canopied chhatri, pointed arch |

10. Construction Technology

| Structural System Building Techniques | : | Indo – Persian Arcuate system |
|--|---|----------------------------------|
| Material of Construction | | Stone and Plaster |

11. Condition Assessment

In General

Good / Fair Good

Sign of Deterioration Serious Deterioration Danger of Disappearance

In Brief (Attach extra sheet if necessary):

Plaster peeling off, Blackening of Surface, Dust and Dirt deposition

12. Threats to the Property

Natural Negligence Vandalism Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

| 14. Photographs | |
|-------------------------|---|
| | (attach list as in page 6, in case of multiple photographs) |
| Photo Reference | |
| CAPTION | |
| 15. Audio / Video | |
| | (related to rituals / performance / festivals etc.) |
| Reference | |
| DESCRIPTION | |
| 16. Maps/Plans/Drawings | |
| | |
| | |
| 17. Listers | |
| NAME | NAME |
| 18. Reviewers | |
| NAME | NAME |
| COMMENTS | COMMENTS |