

**INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS** 

Janpath, New Delhi -110 001, www.ignca.gov.in

## Documentation format for Archaeological / Heritage Sites / Monuments

### Serial No.: RJ/SKR-396

1. Name	SECTION I : IDENTIFICATION
Present Past Other Name (if any): 2. Location	: Purushottam Lal Podar ki Haveli :
LONGITUDE 75° 15 <sup>°</sup> E	LATITUDE 27 <sup>°</sup> 36 <sup>°</sup> N
Address	<ul> <li>Bhumia Jath ki Gali, Ward No. 8, Ramgarh Shekhawati</li> <li>Village (village code)</li> <li>Post : Ramgarh</li> <li>District: Sikar</li> <li>State : Rajasthan</li> <li>PIN: 331024</li> </ul>
Approach	: The Haveli is situated Churugate at Ramgarh Shekhawati. It is 60 km from Sikar. And well connected by regular bus services from big cities.

### 3. Property Type

Buildings		Religious structures	Other Structures		
	Palace	Temple	Wall		
	Fort	Mosque	Gateway		
	Citadel	Minar	Pillar		
	Govt. building	Church	Others (specify)		
	Railway station	Monastery			
	Defence building	Stupa			
	Industrial building	Tomb, Mausoleum			
	Other public buildings				
$\checkmark$	Residential building				
-	r toolaontiai ballaling				
	Engineering structure	Open space and related structures	<b>Note:</b> It is a two storied building with panels of painting on the wall.		
	C C		<b>Note:</b> It is a two storied building with panels of painting on the wall. Cusped arched entrance, high		
	Engineering structure	structures	with panels of painting on the wall.		
	Engineering structure Bridge	structures Dublic square	with panels of painting on the wall. Cusped arched entrance, high		
	Engineering structure Bridge Tunnel	Structures Public square Park or garden	with panels of painting on the wall. Cusped arched entrance, high reliefs depicting arcade patterns,		
	Engineering structure Bridge Tunnel	structures         Public square         Park or garden         Graveyard	with panels of painting on the wall. Cusped arched entrance, high reliefs depicting arcade patterns, decorated brackets are noticed as		
	Engineering structure Bridge Tunnel	structures         Public square         Park or garden         Graveyard         Baolis, Well	with panels of painting on the wall. Cusped arched entrance, high reliefs depicting arcade patterns, decorated brackets are noticed as		

#### 4. Property Use ABANDONED / IN USE : In use Residence Present 2 Residence Past • 5. Age (Source) PERIOD 19<sup>th</sup> Century A.D. YEARS 2 Precise date of Construction 2 Completion : Subsequent changes : **Destruction / Demolition** : 6. Ownership / Level of Protection SINGLE /MULTIPLE : **Public** : Archaeological Survey of : Not protected India / State Archaeology Department / Any Other (Please specify) Private 2 Any other (Please specify) : Name 2 Address : Phone ÷ 7. Association WITH EVENTS In History In History 2 In Rituals In Building Construction : Any other (specify) : WITH PERSONS Patron : Purushotam lal Poddar ji **Architect / Engineer** 2 Any other (specify) : 8. Statement of Significance Architectural

Archaeological
 ✓ Historical
 Religious
 Any other (specify)

<b>SECTION II: DESCRIPTION</b>
--------------------------------

9. Physical Description and Decorative Features				
•	Context Urban / Rural Setting Surroundings		* <b>Drawings</b> (Attach extra sheet if necessary) Urban	
			Stand in Isolation Integral part of a Landscape / Street / Complex	
•	<b>Quantification</b> Area Dimension ( L x B x H)	:	(m/cm/foot/inch)	
	Number of Blocks Number of Storys	:	(m / cm/ feet / inch) 02 02	
•	<b>Spatial Organization</b> Orientation Plan Allocation of Spaces	:	The Haveli is oriented East - West & faces to the East Rectangular	
A	ARCHITECTURAL STYLE			
•	Ornamentation Exteriors	:	Cusped arched entrance; arcade patterns on high reliefs, decorated brackets, panels of wall paintings are noticed.	
Ar	Interiors Movable Collections ny Other (specify)	:	Intricately carved wooden door is also seen.	

### **10. Construction Technology**

Structural System	: Element of Indo-Islamic architecture is evident.
Building Techniques	: Corbelling
Material of Construction	: Stone, Cement mortar, wood & paints are used.

### **11. Condition Assessment**

#### In General

#### Good / Fair Good

Sign of Deterioration Serious Deterioration

Danger of Disappearance

### In Brief (Attach extra sheet if necessary):

Detachment of plaster, fading of colour in paintings are noticed.

### 12. Threats to the Property

✓ Natural
 Negligence
 Vandalism
 Urban Pressures

# SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	
	(attach list as in page 6, in case of multiple photographs)
Photo Reference	
CAPTION	
15. Audio / Video	
	(related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS