

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: 0R/PRI- 19

SECTION I: IDENTIFICATION 1. Name					
Present Past Other Name (if any): 2. Location	: Dakhina Parsva Matha,F : Sri Ramadas Matha or E :				
LONGITUDE 85 ⁰ 49 ['] 08 ["] E	LATITUDE 19 ⁰ 48 ² 1 N	ELEVATION 57 ft			
Address	: Village (village code) Post : Puri Tehsil: Puri State : Orissa.	Dakshina Parsva Matha, Via: Balisahi Lane District: Puri PIN: 752001			
Approach	: It is located on the left s from Emara matha to Lo	side of the Varahi Lane leading kanath Temple.			
3. Property Type					
Buildings Palace Fort Citadel Govt. building Railway station Defense building Industrial building Other public building Residential building	Religious structures Temple Mosque Minar Church Monastery Stupa Tomb, Mausoleum	Other Structures Wall Gateway Pillar Others (specify)			
Engineering structure Bridge Tunnel Other engineering structure	structures	Note : The <i>matha</i> is affiliated to Ramanuja sect.			

4. Property Use		
		ABANDONED / IN USE: In use
Present Past	:	Living monastery. Used
5. Age (Source)		
PERIOD YEARS Precise date of Construction Completion Subsequent changes Destruction / Demolition 6. Ownership / Level of Protection	: : : :	Suryavamsi rule 16 th century A.D. 16 th century A.D. 16 th century A.D.
or emissions / Level of Frederic	/11	SINGLE /MULTIPLE : Multiple
Public: Archaeological Survey of India / State Archaeology Department / Any Other (Please specify) Private Any other (Please specify) Name	: : : : : :	Endowment Department of Govt. of Orissa. The matha is looked after by the present matha mahanta named Sri Srinivas Ramanuja Das. Sri Srinivas Ramanuja Das.
Address Phone	:	Varahi Lane, Bali Sahi, Puri.
7. Association		
WITH EVENTS In History In Rituals	:	Rituals like Jhulana Yatra, Janmastami, Ramnavami, Dolapurnima, Vamana Janma, Guru Sradha Utsav etc. observed.
In Building Construction Any other (specify) • WITH PERSONS	:	Public meetings are organized.
Patron Architect / Engineer	:	Originally the Suryavamsi Gajapatis, but now by the Endowment Department of Govt. of Orissa.
Architect / Engineer Any other (specify)	:	Present matha Mahanta is Sri Srinivas Ramanuja Das
8. Statement of Significance		
Architectural Archaeological Historical	✓	Architectural
Religious Any other (specify)	:	Religious As per the <i>matha</i> tradition the <i>matha</i> was built in 16 th century AD.

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features						
 Context Urban / Rural Setting Surroundings 	:	* Drawings (Attach extra sheet if necessary):No Urban setting				
Surroundings		Stand in isolation Street Integral part of a landscape / Street / Complex :				
 Quantification Area Dimension (L x B x H) 	:	(m / cm/ feet / inch)				
Number of Blocks Number of Storys	:	Single storied building with long <i>verandah</i> .				
Spatial Organization Orientation Plan Allocation of Spaces	:	Facing towards west. The <i>matha</i> has a central courtyard of square on plan. The courtyard is surrounded by pillared <i>verandah</i> leading into the residential rooms. The <i>matha</i> stands on three acres of land. It has 40 rooms.				
ARCHITECTURAL STYLE • Ornamentation						
Exteriors Interiors	:	In the right side of the courtyard there is a <i>torana</i> supported by two pillars. There are many paintings in the interiors wall of the monastery, which are not clearly visible. The entrance of the central room is decorated with pilaster design.				
Movable Collections * Any Other (specify)	:	In the architecture there are conch and wheel in the corners and Ramanuja symbol at the centre.				
10. Construction Technology						
Structural System Building Techniques Material of Construction	: : :	Ashlar dry masonry with lime mortar. Grey sand stone and laterite stone are used. It was repaired and given lime plaster later during renovation.				
11. Condition Assessment						
In General	Go	Good / Fair : Good				
	√	Sign of Deterioration Serious Deterioration Danger of Disappearance				
In Brief (Attach extra sheet if necessary):						

Out of the 40 rooms 30 are totally damaged. Cracks are noticed on the walls, ceiling and

growth of vegetation all over the outer wall. Water percolation and stagnation during rainy seasons are causes of concern. 12. Threats to the Property Natural Negligence Vandalism **Urban Pressures** Χ Х Χ **SECTION III: REFERENCES 13. Reference Sources** (published and unpublished textual details) 14. Photographs (Attach list as in page 6, in case of multiple photographs) Photo Reference CAPTION 15. Audio / Video (Related to rituals / performance / festivals etc.) Reference **DESCRIPTION** 16. Maps/Plans/Drawings

17. Listers					
NAME :	K. B. Barik	NAME :			
18. Reviewers					
NAME : COMMENTS	Dr. S. Pradhan	NAME : COMMENTS :			