

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: 0R / PRI- 59

1. Name	SECTION I: IDENTIFICATION				
Present Past Other Name (if any): 2. Location	: Panchupandava Siva Te : :	mple, Puri Town, Dist. Puri			
LONGITUDE 85°48'94" E	LATITUDE 19 ⁰ 48 ['] 62 ["] N	ELEVATION 16 ft			
Address	: Village (village code) Post : Puri Tehsil: Puri State : Orissa	Upara Markandesvara Sahi Via: Puri District: Puri PIN: 752001			
Approach	: The temple is located within the Markandesvara temple precinct in the Upara Markadesvara Sahi, Puri which can be approached on the right side of Markandesvara road leading from Markandesvara Chowk to Puri-Brahmagiri road.				
3. Property Type					
Buildings Palace Fort Citadel Govt. building Railway station Defense building Industrial building Other public building Residential building	Religious structures Temple Mosque Minar Church Monastery Stupa Tomb, Mausoleum	Other Structures Wall Gateway Pillar Others (specify)			
Engineering structure Bridge Tunnel Other engineering structure	structures	Note : Pidha temple of impoverished Kalingan order.			

4. Property Use ABANDONED / IN USE: In use **Present** Living temple, the presiding deities are five Sivalinga within a circular Yonipitha. Worshipped. Past 5. Age (Source) **PERIOD** Suryavamsi Rule 15th century A.D. YEARS 15th century A.D. Precise date of Construction Completion Subsequent changes **Destruction / Demolition** 6. Ownership / Level of Protection SINGLE /MULTIPLE : Multiple **Public**: Archaeological Survey of: / State Archaeology Endowment Department, Govt. of Orissa. Department / Any Other (Please specify) **Private** Daksina Kali Trust Board Any other (Please specify) Looked after by the Chief Priest Narasingha Tiadi Name Upara Markandesvara Sahi, Puri Address Phone 7. Association WITH EVENTS In History The locals ascribe the temple to the Gangas. Sivaratri, Sankranti, Jalabhiseka etc. are observed. In Rituals In Building Construction Any other (specify) WITH PERSONS **Patron** Originally the Suryavamsi Gajapati, but now the Endowment Department, Govt. of Orissa. Architect / Engineer Any other (specify) 8. Statement of Significance ✓ Architectural Architectural Archaeological ✓ Archaeological Historical

SECTION II: DESCRIPTION

On the basis of architectural features and the building materials the temple can be assigned to the 15th century AD.

Religious

Any other (specify)

9. Physical Description and Decorative Features								
 Context Urban / Rural Setting Surroundings 	:	* Drawings (Attach extra sheet if necessary: No Urban setting						
		Stand in isolation Complex Integral part of a landscape / Street / Complex :						
 Quantification 								
Area Dimension (LxBxH)	:	3.55 mtrs x 3.00 mtrs x 4.86 mtrs. (m / cm/ feet / inch)						
Number of Blocks Number of Storys	:	One						
Spatial Organization								
Orientation Plan	:	Facing towards east. The temple has a rectangular <i>vimana</i> which is a departure of <i>Kalingan</i> order temple.						
Allocation of Spaces	:	30 mtrs (L) x 22.00 mtrs (B).						
ARCHITECTURAL STYLE Ornamentation								
Exteriors	:	Decorated with two images of Visnu & one Hanuman image are inserted in the western wall of the <i>sanctum</i> . The Vaisnavaite images are four armed & held their usual attributes.						
Interiors	:	Plain						
Movable Collections	:	Nil The temple is trivathe on plan and penebangahada in						
* Any Other (specify)	•	The temple is <i>triratha</i> on plan and <i>panchangabada</i> in elevation.						
10. Construction Technology								
Structural System		The temple is a <i>pidha deula</i> of impoverished <i>Kalingan</i>						
-	•	order.						
Building Techniques Material of Construction	:	Ashlar dry masonry Laterite is used both for the foundation and temple						
	•	construction.						
11. Condition Assessment								
In General	Go	Good / Fair : Good						
	√	Sign of Deterioration						
		Serious Deterioration						
		Danger of Disappearance						

In Brief (Attach extra sheet if necessary):

Due to proper care & maintenance the temple is in a good condition. But the low elevation of the temple precinct from the present road level creates water stagnant problem in rainy season.

12. Threats to	the Property								
X x	x x	x SECT	Natural Negligend Vandalisr Urban Prox x x	n essures x	×	x	x	x	x
13. Reference	Sources (pub	olished an	ıd unpublish	ed textua	al details	s)			
14. Photograp	nhs								
			(Attach list	as in pag	ge 6, in	case of	multiple	e photo	graphs)
Photo Referen	ice	: :			-				-
15. Audio / Vi	deo								
			(Related	to rituals	s/ perfoi	mance	/ festiva	als etc.)
Reference DESCRIPTION	N	: :							
16. Maps/Plar	ns/Drawings								
17. Listers									
NAME :	J. S. Naik		NAN	1Ε:					
18. Reviewers	S								
NAME : COMMENTS	Dr. S. Pradha	n	NAM COM	E : MENTS :					