

## INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

## **Documentation format for Archaeological / Heritage Sites / Monuments**

Serial No.: OR/JPR-70

SECTION I : IDENTIFICATION  1. Name				
Present	: Bimala Temple, Varaha Town, Dist Jajpur	ınatha Temple Complex, Jajpur		
Past Other Name (if any):	:			
2. Location				
<b>LONGITUDE</b> 86° 20' 08" E	<b>LATITUDE</b> 20 <sup>0</sup> 51' 30" N	<b>ELEVATION</b> 15 ft		
Address	: Village (village code)  Post : Jajpur Town Tehsil: Jajpur Town State : Orissa	Varahanatha Temple Complex, Varahanatha Via: Jajpur Town District: Jajpur PIN: 755001		
Approach	within the complex is picturesque surroundin has been branched off	outh of the Varahanatha temple, is located on an island with legs, where the river Vaitarani on both sides. It is about 1 km is stand and opposite to the		
3. Property Type				
Buildings  Palace Fort Citadel Govt. building Railway station Defence building Industrial building	Religious structures  ✓ Temple  Mosque  Miner  Church  Monastery  Sputa  Tomb, Mausoleum	Other Structures  Wall Gateway Pillar Others (specify):		
Other public buildings Residential building		Note: It has a <i>rekha vimana</i> followed by a pillared frontal porch.		
Engineering structure  Bridge Tunnel Other engineering structure	Open space and related structures  Public square Park or garden Graveyard Baolis, Well Tank	by a piliared frontal porch.		

	Cave				
4. Property Use					
	ABANDONED / IN USE: In use				
Present Past	<ul><li>Living temple, the presiding deity is goddess Vimala.</li><li>Worshipped.</li></ul>				
5. Age (Source)					
PERIOD YEARS Precise date of Construction Completion Subsequent changes Destruction / Demolition	<ul> <li>Suryavamsi Gajapati rule</li> <li>16<sup>th</sup> century A.D.</li> <li>First quarter of the 16<sup>th</sup> century AD</li> <li></li> <li></li> <li></li> </ul>				
6. Ownership / Level of Protection					
	SINGLE /MULTIPLE : Multiple				
Public: Archaeological Survey of India / State Archaeology Department / Any Other (Please specify)					
Private	:				
Any other (Please specify) Name	<ul><li>: Endowment Department, Government of Orissa</li><li>:</li></ul>				
Address Phone	<ul><li>: Archaeological Survey of India, Bhubaneswar Circle,</li><li>153 VIP Area, Nayapalli, Bhubaneswar, Orissa</li><li>: 0674-2558170</li></ul>				
7. Association					
WITH EVENTS					
In History	:				
In Rituals	: Vimala puja				
In Building Construction	<b>:</b>				
Any other (specify) • WITH PERSONS	:				
Patron	: Now it is under the care of Archaeological Survey of India.				
Architect / Engineer	:				
Any other (specify)	:				
8. Statement of Significance					
Architectural	: ✓ Architectural				
Archaeological	: Delivieus				
Historical Religious	: Religious · ✓				
Any other (specify)	On the basis of the iconography of the enshrined image, the				

## SECTION II: DESCRIPTION

9. Physical Description and Decorative Features						
Context Urban / Rural Setting Surroundings		* Drawings (Attach extra sheet if necessary) : No Rural setting				
· ·		Stand in Isolation Integral part of a Landscape / Street / Complex :	Complex			
<ul> <li>Quantification         Area Dimension ( L x B x H)     </li> <li>Number of Blocks</li> </ul>	:	5.20 mtrs x 5.20 mtrs x 9.00 mtrs (approximate height) (m / cm/ feet / inch) Two				
Number of Storys	:	N.A.				
<ul> <li>Spatial Organization         Orientation         Plan     </li> <li>Allocation of Spaces</li> </ul>	: : :	Facing towards east. The <i>vimana</i> is square on plan whereas the frontal porch is rectangular on plan. 5.20 mtrs (L) x 5.20 mtrs (W)				
·	•	5.25 mas (E) x 5.26 mas (W)				
• Ornamentation Exteriors	:	Projecting lion on each <i>raha</i> and images				
Interiors Movable Collections * Any Other (specify)	: :	& Hanuman are there on either side of the entrance. Plain Nil The temple is <i>pancharatha</i> on plan & <i>triangabada</i> in elevation.				
10. Construction Technology						
Structural System Building Techniques Material of Construction  11. Condition Assessment	:	Rekha vimana of impoverished Kalingan order. Ashlar masonry with mortar Khandolite stone & lime plaster				
In General Good / Fair	:	Fair				
Sign of Deterioration Serious Deterioration Danger of Disappearance						

In Brief (Attach extra sheet if necessary):

the *gandi* of the temple. 12. Threats to the Property Natural Negligence Vandalism **Urban Pressures SECTION III: REFERENCES 13. Reference Sources** (published and unpublished textual details) 1. 2. 14. Photographs: 07 nos. (attach list as in page 6, in case of multiple photographs) **Photo Reference CAPTION** 15. Audio / Video (related to rituals / performance / festivals etc.) Reference DESCRIPTION 16. Maps/Plans/Drawings 17. Listers B. B. Satpathy NAME: NAME: 18. Reviewers

NAME:

**COMMENTS:** 

Dr. S. Pradhan

NAME:

**COMMENTS** 

Plaster patches are flaking from the temple wall and growth of lichen and moss are noticed on