

# INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS Janpath, New Delhi -110 001, www.ignca.gov.in

## **Documentation format for Archaeological / HeritageSites / Monuments**

Serial No.: OR/GJM-15

	SECTION I: IDENTIFICATION
1. Name	
Present	: Jagadisvaraswamy Temple, Gangadharaswamy Temple Complex, Buddhakhol Hillock, Kottakolla, Dist Ganjam
Past Other Name (if any):	: :
2. Location	
<b>LONGITUDE</b> 84 <sup>0</sup> 49' 26" E	<b>LATITUDE</b> 19 <sup>0</sup> 49' 13" N <b>ELEVATION</b> 720 ft
Address	: Village (village code) Post: Buguda Town Tehsil: Buguda Town State: Orissa  Buddhakhol Hillock, Kottakolla Via: Buguda Town District: Ganjam PIN: 761118
Approach	: The temple, on the northern side of Gangadharaswamy temple complex in the middle terrace of Buddhakhol hillock is situated at a distance of 3 kms east of Buguda township in Ganjam district.
3. Property Type	
Buildings  Palace Fort Citadel Govt. building Railway station Defence building	Religious structures   ✓ Temple Wall   Mosque Gateway   Minar Pillar   Church Others (specify):   Monastery Stupa
Industrial building Other public buildings	Tomb, Mausoleum  Note.
Residential building	It is a <i>rekha</i> temple o
Engineering structure  Bridge Tunnel Other engineering structure	Open space and related structures impoverished Kalingan order consists of a rekha vimana and an open-pillared mandapa.  Public square an open-pillared mandapa.  Graveyard Baolis, Well Tank Cave

#### 4. Property Use

ABANDONED / IN USE: In use

**Present** Living temple, enshrining a Sivalinga within a circular

yonipitha.

**Past** Worshipped

5. Age (Source)

PERIOD	:	During the rule of the Bhanjas of ex-Ghumsar state.
YEARS	:	18 <sup>th</sup> century A.D.
Precise date of Construction	:	
Completion	:	
Subsequent changes	:	The temple was renovated by Archaeological Survey of India in 2007.
Destruction / Demolition	:	

#### 6. Ownership / Level of Protection

SINGLE /MULTIPLE : Multiple

**Public**: Archaeological Survey of: Protected monument of Archaeological Survey of India.

State Archaeology / Department / Any Other (Please

specify)

Buddhakhol Unnayana Samiti

Ditikrishna Nanda, the priest of the temple Any other (Please specify)

Name

Address Archaeological Survey of India, Bhubaneswar Circle,

153, VIP Area, Nayapalli, Bhubaneswar, Orissa.

**Phone** 0674-2558170

7. Association

**Private** 

WITH EVENTS

In History Local people ascribed the temple to Gajapati

Mukundadeva Harichandan

Sivaratri, Kartika Purnima, Rakhi Purnima, etc are In Rituals

observed here.

In Building Construction

Mundanakriya, thread ceremony, etc are performed Any other (specify)

here.

WITH PERSONS

**Patron** Archaeological Survey of India

**Architect / Engineer** 

Any other (specify) Buddhakhol Unnayana Samiti

8. Statement of Significance

Architectural Architectural Archaeological Archaeological Historical

Religious

On architectural ground the temple can be assigned to the Any other (specify)

18<sup>th</sup> century AD i.e. the rule of Bhanjas of ex-Ghumsar state.

# **SECTION II: DESCRIPTION**

9. Physical Description and Decorative Features					
<ul> <li>Context</li> <li>Urban / Rural Setting</li> <li>Surroundings</li> </ul>	:	* Drawings (Attach extra sheet if necessary): No Hillock			
		Stand in Isolation Integral part of a Landscape / Complex Street / Complex :			
<ul> <li>Quantification</li> <li>Area Dimension ( L x B x H)</li> </ul>	:	3.50 mtrs x 3.50 mtrs x 11.00 mtrs (approximate height)  (m / cm/ feet / inch)			
Number of Blocks Number of Storys	:	Two			
<ul> <li>Spatial Organization</li> <li>Orientation</li> <li>Plan</li> <li>Allocation of Spaces</li> </ul>	:	Facing towards east. The <i>vimana</i> is square on plan, whereas the <i>nandimandapa</i> is rectangular. 11.60 mtrs (L) x 4.20 mtrs (W)			
ARCHITECTURAL STYLE  • Ornamentation Exteriors Interiors Movable Collections  * Any Other (specify)	: : : : : : : : : : : : : : : : : : : :	The temple is devoid of sculptural embellishment except the <i>parsvadevata</i> images. Plain  Amlakasila, dopichhasimha, etc. The temple is <i>pancharatha</i> on plan and <i>triangabada</i> in elevation.			
10. Construction Technology					
Structural System  Building Techniques  Material of Construction	: : :	Rekha vimana of impoverished Kalingan order fronted by an open-pillared mandapa. Ashlar masonry Khandolite stone			
11. Condition Assessment					
In General Good / Fair  Sign of Deterioration Serious Deterioration Danger of Disappearance	:	Good			

## In Brief (Attach extra sheet if necessary):

Due to the recent renovation work by Archaeological Survey of India, the temple is in a good state of preservation.

12. Threats to	the Property	
x x x x x x x	Ne Va	tural gligence ndalism pan Pressures K X X X X X X X X X X X X X X X X X X X
	SECTION	III: REFERENCES
13. Reference	Sources (published and un	published textual details)
1. R. P. Moh	apatra, 1986, <i>Archaeology ii</i>	n Orissa, Vol I, New Delhi.
14. Photograp		
	(att	ach list as in page 6, in case of multiple photographs)
Photo Referer CAPTION	1 <b>ce</b> : :	
15. Audio / Vid	deo	
		(related to rituals / performance / festivals etc.)
Reference DESCRIPTION	i :	
16. Maps/Plan	s/Drawings	
17. Listers		
NAME :	Ashis Ranjan Sahoo	NAME:
18. Reviewers	•	
NAME: COMMENTS	Dr. S. Pradhan	NAME: COMMENTS: