



Documentation format for Archaeological / Heritage Sites / Monuments

Serial No. ARU/ASS/DBR/002**SECTION I : IDENTIFICATION****1. Name ()**

Present

Bugar Soul

Past

Other Name (if any)

2. Location ()

Address

LONGITUDE E 94° 46' 40" ATTITUDE N 27° 09' 34.6"

State

AssamVillage (village code) Bugar Pathar, Ahenesi, AmowPost AhenesiDistrict Sibsagarh

PIN

Approach

4 KM to left from Digari liniali while moving from Itreogae to Sibpurgh through NH37.**3. Property Type ()**Buildings

- Palace
 Fort
 Citadel
 Govt. building
 Railway station
 Defence building
 Industrial building
 Other public buildings
 Residential building

Engineering structure

- Bridge
 Tunnel
 Other engineering

Religious structures

- Temple
 Mosque
 Minar
 Church
 Monastery
 Stupa
 Tomb, Mausoleum

Open space and related structures

- Public square
 Park or garden
 Graveyard
 Baolis, Well

Other Structures

- Wall
 Gateway
 Pillar
 Others (specify)

structure

- Tank
 Cave

4. Property Use ()

ABANDONED / IN USE

Present

Temple

Past

Temple

5. Age (Source) ()

PERIOD ()

YEARS ()

Precise date of
Construction
Completion
Subsequent changes
Destruction / Demolition

During Ahom reign

6. Ownership / Level of Protection ()

SINGLE / MULTIPLE

Public Archaeological Survey of India / State Archaeology Department /
Any Other (Please specify)

Private

Any other (Please specify)

Name

Address

Phone

7. Association ()

• WITH EVENTS

- History
 In Rituals
In Building Construction
Any other (specify)

• WITH PERSONS

- Patron
Architect / Engineer
Any other (specify)

One physician belonging to 'Chang'-clan
among six clans during Ahom reign

8. Statement of Significance ()

- Architectural
 Archaeological
 Historical
 Religious
 Any other (specify) _____

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features

• Context

* Drawings (Attach extra sheet if necessary)

Urban / Rural Setting
Surroundings

Stand in Isolation
Integral part of a Landscape / Street / Complex

• Quantification

Area Dimension (L x B x H)

(m / cm / feet / inch)

Number of Blocks

One

Number of Storeys

Single

• Spatial Organization

Orientation

East facing

Plan

Octagonal

Allocation of Spaces

ARCHITECTURAL STYLE

• Ornamentation

Exteriors

Interiors

Movable Collections

* Any Other (specify)

10. Construction Technology

Structural System

Building Techniques

Masonry - brick

Material of Construction Brick, traditionally made cementing mixture.

11. Condition Assessment

In General

Good / Fair

- Sign of Deterioration
- Serious Deterioration
- Danger of Disappearance

In Brief (Attach extra sheet if necessary)

The temple is lying neglected and graffiti, algae etc are noticed.

12. Threats to the Property

- Natural
- Negligence
- Vandalism
- Urban Pressures