



## Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: ARCH/ASS/DBR/005

SECTION I: IDENTIFICATION1. Name ( )

Present

Old British Cemetery

Past

Other Name (if any)

2. Location ( )

Address

LONGITUDE E94°54'30Z LATITUDE N27°29'110'A.T. Road, Opp. Iyurudwara

Village (village code)

State

AssamPost C. R. Building District Sibsbugarh

PIN

Approach

On the Sibsbugarh town, over near court of District and Session Judge.3. Property Type ( )Buildings

- Palace  
 Fort  
 Citadel  
 Govt. building  
 Railway station  
 Defence building  
 Industrial building  
 Other public buildings  
 Residential building

Engineering structure

- Bridge  
 Tunnel  
 Other engineering

Religious structures

- Temple  
 Mosque  
 Minar  
 Church  
 Monastery  
 Stupa  
 Tomb, Mausoleum

Open space and related structures

- Public square  
 Park or garden  
 Graveyard  
 Baolis, Well

Other Structures

- Wall  
 Gateway  
 Pillar  
 Others (specify)

structure

- Tank  
 Cave

4. Property Use (   )

ABANDONED / IN USE

Present

Graveyard.

Past

Graveyard ( Cemetery of the Britishers in 19<sup>th</sup> c. AD )

5. Age (Source) (   )

PERIOD (  )

YEARS (  )

Precise date of

Construction

Completion

Subsequent changes

Destruction / Demolition

19<sup>th</sup> century AD.

6. Ownership / Level of Protection (   )

SINGLE / MULTIPLE

Public

Archaeological Survey of India / State Archaeology Department /  
Any Other (Please specify) District Authority

Private

Any other (Please specify) \_\_\_\_\_

Name

Address

Phone

7. Association (  )

• WITH EVENTS

In History

In Rituals

In Building Construction

Any other (specify)

• WITH PERSONS

Patron

Architect / Engineer

Any other (specify)

8. Statement of Significance (          )

- Architectural
- Archaeological
- Historical
- Religious
- Any other (specify) \_\_\_\_\_

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features

● Context

\* Drawings (Attach extra sheet if necessary) \*

Urban / Rural Setting  
Surroundings

Stand in Isolation  
Integral part of a Landscape /  Street / Complex

● Quantification

Area Dimension ( L x B x H)

\_\_\_\_\_ (m / cm / feet / inch)

Number of Blocks \_\_\_\_\_

Number of Storeys \_\_\_\_\_

● Spatial Organization

Orientation \_\_\_\_\_

Plan

Rectangular

Allocation of Spaces \_\_\_\_\_

ARCHITECTURAL STYLE

● Ornamentation

Exteriors

NA

Interiors

NA

Movable Collections

NA

\* Any Other (specify) \_\_\_\_\_

10. Construction Technology

Structural System \_\_\_\_\_

Building Techniques \_\_\_\_\_

---

Material of Construction \_\_\_\_\_

---

---

### 11. Condition Assessment

---

In General

Good / Fair

- Sign of Deterioration
- Serious Deterioration
- Danger of Disappearance

In Brief (Attach extra sheet if necessary)

*This cemetery is lying neglected in midst of the surrounding commercial area. Vegetation is the first noticed problem.*

### 12. Threats to the Property

---

- Natural
- Negligence
- Vandalism
- Urban Pressures