



Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: ARCH/ASS/NBR/013**SECTION I : IDENTIFICATION****1. Name ()**

Present

Barbarua Maidam

Past

Other Name (if any)

2. Location ()

Address

LONGITUDE E94° 51' 895" LATITUDE N27° 20' 415"Barbaruah, LepetkataVillage (village code) Chetta

State

Post Barbaruah District Sivasagar Dibrugarh

PIN

Assam

Approach

About 24 KM west from Dibrugarh
on the right side of NH 37.**3. Property Type ()****Buildings**

- Palace
 Fort
 Citadel
 Govt. building
 Railway station
 Defence building
 Industrial building
 Other public buildings
 Residential building

Engineering structure

- Bridge
 Tunnel
 Other engineering

Religious structures

- Temple
 Mosque
 Minar
 Church
 Monastery
 Stupa
 Tomb, Mausoleum

Open space and related structures

- Public square
 Park or garden
 Graveyard
 Baolis, Well

Other Structures

- Wall
 Gateway
 Pillar
 Others (specify)

structure

- Tank
 Cave

4. Property Use ()

ABANDONED / IN USE

Present

Burial place of Alan Dikongia Barbarua
and Lan Chongkon (Duka Dikongia Barbarua)

Past

5. Age (Source) ()

PERIOD ()

YEARS ()

Precise date of

Construction

Completion

Subsequent changes

Destruction / Demolition

16th - 17th Century AD. (During Gadadhar
Singha (1681-1696).

6. Ownership / Level of Protection ()

SINGLE / MULTIPLE

Public

Archaeological Survey of India / State Archaeology Department /
Any Other (Please specify) District authority

Private

Any other (Please specify)

Name

Address

Phone

7. Association ()

• WITH EVENTS

In History

In Rituals

In Building Construction

Any other (specify)

• WITH PERSONS

Patron

Architect / Engineer

Any other (specify)

8. Statement of Significance ()

- Architectural
- Archaeological
- Historical
- Religious
- Any other (specify) _____

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features

● Context

* Drawings (Attach extra sheet if necessary)

Urban / Rural Setting
Surroundings

Stand in Isolation
Integral part of a Landscape / Street / Complex

● Quantification

Area Dimension (L x B x H)

_____ (m / cm / feet / inch)

Number of Blocks
Number of Storeys

Three

● Spatial Organization

Orientation

By the side of NH37.

Plan

Allocation of Spaces

ARCHITECTURAL STYLE

● Ornamentation

Exteriors

NA

Interiors

NA

Movable Collections

NA

* Any Other (specify)

10. Construction Technology

Structural System

Typical burial system of that period

Building Techniques

Material of Construction

Mud (earth), brick, wooden ~~beam~~
Chamber

11. Condition Assessment

In General

Good / Fair

- Sign of Deterioration
- Serious Deterioration
- Danger of Disappearance

In Brief (Attach extra sheet if necessary)

Although the area is bounded with a brick wall, some actions which playing destructive effects are still going on.

12. Threats to the Property

- Natural
- Negligence
- Vandalism
- Urban Pressures