



Documentation format for Archaeological / Heritage Sites / Monuments

Serial No. ARCH/A44/DBR/018

SECTION I : IDENTIFICATION1. Name ()

Present

Tirikotia Mosque

Past

Other Name (if any)

2. Location ()

Address

LONGITUDE E94°54'95" LATTITUDE N27°29'43"

Near Tirikotia Police Point

Village (village code)

Post C.R. Building District Akrugurh

State

Odisha

Approach

Near Tirikotia police point, on the bank of River Brahmaputra

3. Property Type ()Buildings

- Palace
 Fort
 Citadel
 Govt. building
 Railway station
 Defence building
 Industrial building
 Other public buildings
 Residential building

Engineering structure

- Bridge
 Tunnel
 Other engineering

Religious structures

- Temple
 Mosque
 Minar
 Church
 Monastery
 Stupa
 Tomb, Mausoleum

Open space and related structures

- Public square
 Park or garden
 Graveyard
 Baolis, Well

Other Structures

- Wall
 Gateway
 Pillar
 Others (specify)

structure

- Tank
 Cave

4. Property Use ()

ABANDONED / IN USE

Present

Mosque

Past

Mosque

5. Age (Source) ()

PERIOD ()

YEARS ()

Precise date of

Construction

Completion

• Subsequent changes

Destruction / Demolition

Probably mid 19th century AD.

6. Ownership / Level of Protection ()

SINGLE / MULTIPLE

Public

Archaeological Survey of India / State Archaeology Department /
Any Other (Please specify)

Private

Any other (Please specify)

Name

Address

Phone

7. Association ()

• WITH EVENTS

In History

In Rituals

In Building Construction

Any other (specify)

• WITH PERSONS

Patron

Architect / Engineer

Any other (specify)

Father of Meherunissa Begam
who died crossing 100 years on year
back.

8. Statement of Significance ()

- Architectural
- Archaeological
- Historical
- Religious
- Any other (specify) 1st mosque in Dibrugarh

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features

- **Context** * Drawings (Attach extra sheet if necessary)

Urban / Rural Setting
Surroundings

Stand in Isolation
Integral part of a Landscape / Street / Complex

- **Quantification**

Area Dimension (L x B x H)

L = 57 feet B = 30 feet.
(m / cm / feet / inch)

Number of Blocks

Two

Number of Storeys

- **Spatial Organization**

Orientation

On the south bank of Brahmaputra
facing west.

Plan

Rectangular

Allocation of Spaces

—

ARCHITECTURAL STYLE

- **Ornamentation**

Exteriors

Not much ornamentation outside

Interiors

Style of the minbar is typically
space for lamp and pillars is also
to be noted.

Movable Collections

- * **Any Other (specify)**

10. Construction Technology

Structural System

Elements of local architectural
pattern is noticeable.

Building Techniques

Mixed.

Material of Construction Reed, wood, cementing mixture prepared locally, brick etc.

11. Condition Assessment

In General

Good / Fair

- Sign of Deterioration
- Serious Deterioration
- Danger of Disappearance

In Brief (Attach extra sheet if necessary)

12. Threats to the Property

- Natural
- Negligence
- Vandalism
- Urban Pressures