



Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: ARCH/AS4/DBR/023

SECTION I: IDENTIFICATION1. Name ()

Present

Mairamara Ruins

Past

Other Name (if any)

2. Location ()

Address

LONGITUDE $E94^{\circ}55'750$ LATITUDE $N27^{\circ}20'116'$

State

Assam

Village (village code) Khamtighat, Tengri Manja, Khowang
 Post Napaam Than gaon District Sibsagarh
 PIN 786003

Approach

Around 19 KM from Sibsagarh

3. Property Type ()Buildings

- Palace
 Fort
 Citadel
 Govt. building
 Railway station
 Defence building
 Industrial building
 Other public buildings
 Residential building

Engineering structure

- Bridge
 Tunnel
 Other engineering

Religious structures

- Temple
 Mosque
 Minar
 Church
 Monastery
 Stupa
 Tomb, Mausoleum

Open space and related structures

- Public square
 Park or garden
 Graveyard
 Baolis, Well

Other Structures

- Wall
 Gateway
 Pillar
 Others (specify)

structure

- Tank
 Cave

4. Property Use (□□□□□□ □□ □□□□□)

ABANDONED / IN USE

Present

A *Thar (vaishnavite) institution*
The ruins are lying in the premise
of present structure.

Past

Temple.

5. Age (Source) (□□□□□□ □□ □□□)

PERIOD (□□□)

YEARS (□□□□)

Precise date of
Construction
Completion
Subsequent changes
Destruction / Demolition

1703 AD (according to the local sources).

6. Ownership / Level of Protection (□□□□□□ □□ □□□□□ □□ □□□□□□ □□ □□□□)

SINGLE / MULTIPLE

Public Archaeological Survey of India / State Archaeology Department /
Any Other (Please specify) _____

Private _____

Any other (Please specify) _____

Name _____

Address _____

Phone _____

7. Association (□□□□□)

• WITH EVENTS

- History
In Rituals
In Building Construction
Any other (specify)

• WITH PERSONS

- Patron
Architect / Engineer
Any other (specify)

8. Statement of Significance ()

- Architectural
- Archaeological
- Historical
- Religious
- Any other (specify) _____

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features

● Context

* Drawings (Attach extra sheet if necessary)

Urban / Rural Setting
Surroundings

Stand in Isolation (On the bank of Siking river)
Integral part of a Landscape / Street / Complex

● Quantification

Area Dimension (L x B x H)

The ruins of the old structure
is lying in the _____
(m / feet / inch)

Number of Blocks

Number of Storeys

● Spatial Organization

Orientation

East facing - on the bank of Siking river

Plan

Unknown

Allocation of Spaces

ARCHITECTURAL STYLE

● Ornamentation

Exteriors

Interiors

Movable Collections

* Any Other (specify)

The images like dwarapalika, one male figure with a kamandalu and a trishul, lady figure with a child, a lady holding something with both the hands all show tribal elements in their execution. Broken padma, parts of door frame, and the brick structure just showing its existence from a mound proves the existence of an old temple

10. Construction Technology

Structural System

Regional elements with depiction of regional physiognomical features proves development of a new style

Building Techniques

Masonry, brick

Material of Construction Stone, brick, iron clump, cementing mixture prepared from local ingredients.

11. Condition Assessment

In General

Good / Fair

- Sign of Deterioration
- Serious Deterioration
- Danger of Disappearance

In Brief (Attach extra sheet if necessary)

Negligence and flood in the area put serious threat to the preservation of this site.

12. Threats to the Property

- Natural
- Negligence
- Vandalism
- Urban Pressures