



Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: ARCH/ASS/JRT/004

SECTION I : IDENTIFICATION

1. Name ()

Present

Solalk Jank (Pukhuri)

Past

Other Name (if any)

2. Location ()

Address

LONGITUDE 94°00'964" LATTITUDE N26°45'726"

Solalbaxi Tea Estate, Ephraigan

Village (village code)

Post

District

PIN

forhat

State

Assam

Approach

3. Property Type ()

Buildings

- Palace
- Fort
- Citadel
- Govt. building
- Railway station
- Defence building
- Industrial building
- Other public buildings
- Residential building

Religious structures

- Temple
- Mosque
- Minar
- Church
- Monastery
- Stupa
- Tomb, Mausoleum

Other Structures

- Wall
- Gateway
- Pillar
- Others (specify)

Engineering structure

- Bridge
- Tunnel
- Other engineering

Open space and related structures

- Public square
- Park or garden
- Graveyard
- Baolis, Well

structure

- Tank
- Cave

4. Property Use ()

ABANDONED / IN USE

Present

Low land with parts of bank.

Past

Tank

5. Age (Source) ()

PERIOD ()

YEARS ()

Precise date of

Construction

Completion

Subsequent changes

Destruction / Demolition

Not known.

6. Ownership / Level of Protection ()

SINGLE / MULTIPLE

Public

Archaeological Survey of India / State Archaeology Department / Any Other (Please specify) Locals.

Private

Any other (Please specify)

Name

Address

Phone

7. Association ()

• WITH EVENTS

In History

In Rituals

In Building Construction

Any other (specify)

• WITH PERSONS

Patron

Architect / Engineer

Any other (specify)

8. Statement of Significance ()

- Architectural
- Archaeological
- Historical
- Religious
- Any other (specify) _____

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features

● Context

* Drawings (Attach extra sheet if necessary)

Urban / Rural Setting
Surroundings

Stand in Isolation *In midst of Salabar T.E.*
Integral part of a Landscape / Street / Complex

● Quantification

Area Dimension (L x B x H)

About 2 Bigha

(m / cm/ feet / inch)

- Number of Blocks
- Number of Storys

● Spatial Organization

Orientation

Plan

Rectangular

Allocation of Spaces

ARCHITECTURAL STYLE

● Ornamentation

Exteriors

Interiors

Movable Collections

* Any Other (specify)

10. Construction Technology

Structural System

Building Techniques

Material of Construction _____

11. Condition Assessment

In General

Good / Fair

- Sign of Deterioration
- Serious Deterioration
- Danger of Disappearance

In Brief (Attach extra sheet if necessary)

The tank is in the verge of extinct due to negligence and vandalism and some natural causes.

12. Threats to the Property

- Natural
- Negligence
- Vandalism
- Urban Pressures