



Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: ARCH/ASS/SNT/002

SECTION I : IDENTIFICATION

1. Name ()

Present

Minguleswar (Siva temple remnants)

Past

Other Name (if any)

2. Location ()

Address

LONGITUDE E 92°46'08" LATITUDE N 26°37'706'

State

ASSAM

Village (village code) Jespur
Post Boam-parvatia District SONITPUR

PIN

Approach

South-east to Jespur town

3. Property Type ()

Buildings

- Palace
- Fort
- Citadel
- Govt. building
- Railway station
- Defence building
- Industrial building
- Other public buildings
- Residential building

Engineering structure

- Bridge
- Tunnel
- Other engineering

Religious structures

- Temple
- Mosque
- Minar
- Church
- Monastery
- Stupa
- Tomb, Mausoleum

Open space and related structures

- Public square
- Park or garden
- Graveyard
- Baolis, Well

Other Structures

- Wall
- Gateway
- Pillar
- Others (specify)

structure

- Tank
 Cave

4. Property Use (□□□□□□ □□ □□□□□□)

ABANDONED / IN USE

Present

The linga is still worshipped

Past

Temple

5. Age (Source) (□□□□□□ □□ □□□□)

PERIOD (□□□)

YEARS (□□□□)

Precise date of

Construction Not known.
Completion
Subsequent changes
Destruction / Demolition

6. Ownership / Level of Protection (□□□□□□ □□ □□□□□□ □□□ □□□□□□ □□ □□□□)

SINGLE / MULTIPLE

Public Archaeological Survey of India / State Archaeology Department /
Any Other (Please specify) Community

Private _____

Any other (Please specify) _____

Name _____

Address _____

Phone _____

7. Association (□□□□□□)

• WITH EVENTS

- In History
 In Rituals
 In Building Construction
Any other (specify)

• WITH PERSONS

- Patron
Architect / Engineer
Any other (specify)

8. Statement of Significance ()

- Architectural
 Archaeological
 Historical
 Religious
 Any other (specify) _____

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features

• Context

* Drawings (Attach extra sheet if necessary)

Urban / Rural Setting
Surroundings

Stand in Isolation
Integral part of a Landscape / Street / Complex

• Quantification

Area Dimension (L x B x H)

Could not find out.
(m / cm / feet / inch)

Number of Blocks

Number of Storeys

Not excavated fully yet.

• Spatial Organization

Orientation

East-west.

Plan

Suggestively square type.

Allocation of Spaces

Not clear.

ARCHITECTURAL STYLE

• Ornamentation

Exteriors

Interiors

Movable Collections

a few
Only stone pillars and blocks are scattered
outside the present temple having minimal
ornamental craftsmanship.

* Any Other (specify)

One Lintel with the motif of Kalpatriksha and
one door jamb with plain vertical parts are
lying in front of the present structure

10. Construction Technology

Structural System

Not known.

Building Techniques

Masonry.

Material of Construction Stone, brick.

11. Condition Assessment

In General

Good / Fair

- Sign of Deterioration
- Serious Deterioration
- Danger of Disappearance

In Brief (Attach extra sheet if necessary)

The temple (old) is non-existent, only stones and bricks are found there

12. Threats to the Property

- Natural
- Negligence
- Vandalism
- Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

Neog, Maheswar (1991) "Pabitra Asom". Guwahati: LBS.

14. Photographs

(attach list as in page 6, in case of multiple photographs)

Photo Reference _____

CAPTION _____

15. Audio / Video

(related to rituals / performance / festivals etc.)

Reference _____

DESCRIPTION _____

16. Maps/Plans/Drawings

17. Listers

NAME _____

NAME _____

18. Reviewers

NAME _____

NAME _____

COMMENTS _____

COMMENTS _____