



Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: ARCH/ASS/SNT/008

SECTION I: IDENTIFICATION

1. Name ()

Present

Hagarapukhuri

Past

Other Name (if any)

2. Location ()

LONGITUDE $E92^{\circ}47'010''$ LATITUDE $N26^{\circ}37'722''$

Address

Hagarapukhuri

Village (village code)

Post Jorapur

District Sonitpur

PIN

State

Assam

Approach

About 3 km from Jorapur

3. Property Type ()

Buildings

- Palace
 Fort
 Citadel
 Govt. building
 Railway station
 Defence building
 Industrial building
 Other public buildings
 Residential building

Engineering structure

- Bridge
 Tunnel
 Other engineering

Religious structures

- Temple
 Mosque
 Minar
 Church
 Monastery
 Stupa
 Tomb, Mausoleum

Open space and related structures

- Public square
 Park or garden
 Graveyard
 Baolis, Well

Other Structures

- Wall
 Gateway
 Pillar
 Others (specify)

structure

- Tank
 Cave

4. Property Use ()

Present ABANDONED IN USE (partly)
Fishery (partly), under engrossment (partly).

Past Tank

5. Age (Source) ()

PERIOD ()
YEARS ()

Precise date of
Construction During Harjara Varman (815-832AD).
Completion
Subsequent changes
Destruction / Demolition

6. Ownership / Level of Protection ()

SINGLE MULTIPLE

Public Archaeological Survey of India / State Archaeology Department
Any Other (Please specify) District authority

Private

Any other (Please specify)

Name

Address

Phone

7. Association ()

• WITH EVENTS

- In History
 In Rituals
 In Building Construction
Any other (specify)

• WITH PERSONS

- Patron King Harjara Varman (815-832AD)
 Architect / Engineer
Any other (specify)

8. Statement of Significance ()

- Architectural
 Archaeological
 Historical
 Religious
 Any other (specify) One of the big tanks constructed during King's reign.

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features

- Context * Drawings (Attach extra sheet if necessary)

Urban Rural Setting
Surroundings

Stand in Isolation
Integral part of a Landscape / Street Complex

- Quantification

Area Dimension (L x B x H) 70 acres (1000 Bighas?)
(m / cm / feet / inch)

Number of Blocks —

Number of Storeys —

- Spatial Organization

Orientation _____

Plan Rectangular

Allocation of Spaces _____

ARCHITECTURAL STYLE

- Ornamentation

Exteriors NA

Interiors NA

Movable Collections NA

- * Any Other (specify) _____

10. Construction Technology

Structural System Elaborate processing during construction

Building Techniques —

Material of Construction _____

11. Condition Assessment

In General

Good / Fair

- Sign of Deterioration
- Serious Deterioration
- Danger of Disappearance

In Brief (Attach extra sheet if necessary)

The tank loses its grandeur and construction of fishery department's office and some other structures within its banks is striking. Only a small portion is used for fishery.

12. Threats to the Property

- Natural
- Negligence
- Vandalism
- Urban Pressures