



Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: AROM/ASS/SNT/009

SECTION I : IDENTIFICATION

1. Name ()

Present

Archaeological remains of Doulguri Smashan

Past

Other Name (if any)

2. Location ()

LONGITUDE E92°47'499" LATITUDE N26°38'441"

Address

Ghanpora Chubuni, Jorapur

Village (village code)

Post Jorapur

District Somitpur

State

Assam

PIN 784001

Approach

About 2KM from Jorapur Town

3. Property Type ()

Buildings

- Palace
- Fort
- Citadel
- Govt. building
- Railway station
- Defence building
- Industrial building
- Other public buildings
- Residential building

Engineering structure

- Bridge
- Tunnel
- Other engineering

Religious structures

- Temple
- Mosque
- Minar
- Church
- Monastery
- Stupa
- Tomb, Mausoleum

Open space and related structures

- Public square
- Park or garden
- Graveyard
- Baolis, Well

Other Structures

- Wall
- Gateway
- Pillar
- Others (specify)

structure

- Tank
 Cave

4. Property Use ()

ABANDONED / IN USE

Present

Graveyard.

Past

Temple remains are lying - may be temple existed in the site.

5. Age (Source) ()

PERIOD ()

YEARS ()

Precise date of

- Construction Not reported.
Completion
Subsequent changes
Destruction / Demolition

6. Ownership / Level of Protection ()

SINGLE / MULTIPLE

Public Archaeological Survey of India / State Archaeology Department /
Any Other (Please specify) Local people.

Private

Any other (Please specify)

Name

Address

Phone

7. Association ()

• WITH EVENTS

- History
 In Rituals
 In Building Construction
Any other (specify)

• WITH PERSONS

- Patron
Architect / Engineer
Any other (specify)

8. Statement of Significance ()

- Architectural
- Archaeological
- Historical
- Religious
- Any other (specify) _____

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features

• Context

* Drawings (Attach extra sheet if necessary)

Urban / Rural Setting
Surroundings

Stand in Isolation

Integral part of a Landscape Street Complex

• Quantification

Area Dimension (L x B x H)

_____ (m / cm / feet / inch)

Number of Blocks

Number of Storeys

• Spatial Organization

Orientation

Not known

Plan

Not ascertained

Allocation of Spaces

ARCHITECTURAL STYLE

• Ornamentation

Exteriors

Interiors

Movable Collections

The big size door frame remains, stone pillars and other stone blocks, amalaka etc. suggests these are parts of a grand structure.

• Any Other (specify)

10. Construction Technology

Structural System

From the door frame, a temple with conical mukhadant sikhara is indicated.

Building Techniques

Masonry

Material of Construction Stone, brick

11. Condition Assessment

In General

Good / Fair

- Sign of Deterioration
- Serious Deterioration
- Danger of Disappearance

In Brief (Attach extra sheet if necessary)

Systematic study about its historical facts is in need. Excavation of the site, also will give some important facts.

12. Threats to the Property

- Natural
- Negligence
- Vandalism
- Urban Pressures