



Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: ARCH/ASS/SNT/020

SECTION I : IDENTIFICATION

1. Name ()

Present

Greave of Lt. Lewis Van Sardan

Past

Other Name (if any)

2. Location ()

Address

LONGITUDE $E93^{\circ}10'32.8''$ LATITUDE $N26^{\circ}39'62.9''$ Village (village code) Biswanathgar, Biswanath CharialiPost Biswanath District Sonitpur
PIN

State

Assam

Approach

About 65 km from Jorhat, near Biswanathgar.

3. Property Type ()

Buildings

- Palace
 Fort
 Citadel
 Govt. building
 Railway station
 Defence building
 Industrial building
 Other public buildings
 Residential building

Engineering structure

- Bridge
 Tunnel
 Other engineering

Religious structures

- Temple
 Mosque
 Minar
 Church
 Monastery
 Stupa
 Tomb, Mausoleum

Open space and related structures

- Public square
 Park or garden
 Graveyard
 Baolis, Well

Other Structures

- Wall
 Gateway
 Pillar
 Others (specify)

structure

- Tank
 Cave

4. Property Use ()

ABANDONED / IN USE

Present

Grave

Past

Grave

5. Age (Source) ()

PERIOD ()

YEARS ()

Precise date of

Construction

Completion

Subsequent changes

Destruction / Demolition

19th Century

6. Ownership / Level of Protection ()

SINGLE / MULTIPLE

Public

Archaeological Survey of India / State Archaeology Department /
Any Other (Please specify)

Private

Any other (Please specify)

Name

Address

Phone

7. Association ()

• WITH EVENTS

History

In Rituals

In Building Construction

Any other (specify)

• WITH PERSONS

Patron The Britishers

Architect / Engineer

Any other (specify)

8. Statement of Significance ()

- Architectural
- Archaeological
- Historical
- Religious
- Any other (specify) _____

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features

• Context

* Drawings (Attach extra sheet if necessary)

Urban / Rural Setting
Surroundings

Stand in Isolation
Integral part of a Landscape / Street / Complex

• Quantification

Area Dimension (L x B x H)

_____ (m / cm/ feet / inch)

Number of Blocks

One

Number of Storys

• Spatial Organization

Orientation

Near Bismarathgar

Plan

Rectangular

Allocation of Spaces

ARCHITECTURAL STYLE

• Ornamentation

Exteriors

NA

Interiors

NA

Movable Collections

NA

* Any Other (specify)

No epitaph is found nearby.

10. Construction Technology

Structural System

Typical structure of Christian grave

Building Techniques

Masonry - brick

Material of Construction Brick, cement etc.

11. Condition Assessment

In General

Good / Fair

- Sign of Deterioration
- Serious Deterioration
- Danger of Disappearance

In Brief (Attach extra sheet if necessary)

The surroundings are congested and no indication about this site can be found in written form.

12. Threats to the Property

- Natural
- Negligence
- Vandalism
- Urban Pressures