



## Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: ARCH/ASS/SNT/037**SECTION I : IDENTIFICATION****1. Name ( )**

Present

Haleswar Devalaya.

Past

Other Name (if any)

**2. Location ( )**LONGITUDE E92°46'045 LATTITUDE N26°42'503'

Address

Haleswar, Jorapur.Village (village code) HaleswarPost Haleswar District Sonitpur

State

Assam.PIN 784104.

Approach

Around 12 KM from Jorapur.**3. Property Type ( )**Buildings

- Palace  
 Fort  
 Citadel  
 Govt. building  
 Railway station  
 Defence building  
 Industrial building  
 Other public buildings  
 Residential building

Engineering structure

- Bridge  
 Tunnel  
 Other engineering

Religious structures

- Temple  
 Mosque  
 Minar  
 Church  
 Monastery  
 Stupa  
 Tomb, Mausoleum

Open space and related structures

- Public square  
 Park or garden  
 Graveyard  
 Baolis, Well

Other Structures

- Wall  
 Gateway  
 Pillar  
 Others (specify)

structure

Tank

Cave

4. Property Use (  )

ABANDONED /  IN USE

Present

Temple with old remains.

Past

Temple

5. Age (Source) (  )

PERIOD (  )

YEARS (  )

Precise date of

Construction 1705 AD.

Completion

Subsequent changes

Destruction / Demolition

6. Ownership / Level of Protection (  )

SINGLE / MULTIPLE

Public Archaeological Survey of India / State Archaeology Department /  
Any Other (Please specify) Temple Committee

Private

Any other (Please specify)

Name

Address

Phone

7. Association (  )

• WITH EVENTS

In History

In Rituals

In Building Construction

Any other (specify)

• WITH PERSONS

Patron King Rudra Sirga

Architect / Engineer

Any other (specify)

8. Statement of Significance (           )

- Architectural  
 Archaeological  
 Historical  
 Religious  
 Any other (specify) \_\_\_\_\_

**SECTION II: DESCRIPTION**

9. Physical Description and Decorative Features

● Context

\* Drawings (Attach extra sheet if necessary)

Urban / Rural ~~Setting~~  
Surroundings

Stand in Isolation  
Integral part of a Landscape / Street / Complex

● Quantification

Area Dimension ( L x B x H)

\_\_\_\_\_ (m / cm / feet / inch)

Number of Blocks \_\_\_\_\_

Number of Storys \_\_\_\_\_

● Spatial Organization

Orientation

East facing.

Plan

Allocation of Spaces

**ARCHITECTURAL STYLE**

● Ornamentation

Exteriors

The present construction is of recent origin.

Interiors

Movable Collections

A Siva linga and an image of Ganesh is preserved in the temple which are important from archaeological point of view.

\* Any Other (specify)

10. Construction Technology

Structural System \_\_\_\_\_

Building Techniques \_\_\_\_\_

---

Material of Construction \_\_\_\_\_

---

---

### 11. Condition Assessment

---

In General

Good / Fair

- Sign of Deterioration
- Serious Deterioration
- Danger of Disappearance

In Brief (Attach extra sheet if necessary)

The old structure is not in existence and the remains presently in stone was only chance finding by the locals. Need study for more information

### 12. Threats to the Property

---

- Natural
- Negligence
- Vandalism
- Urban Pressures