



## Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: ARCH/ASS/SMT/CR/3

SECTION I: IDENTIFICATION

## 1. Name ( )

Present

Buxhigoshal Khan

Past

Other Name (if any)

## 2. Location ( )

LONGITUDE  $92^{\circ}54'789$  LATITUDE  $N26^{\circ}44'283'$ 

Address

Jamugurhat.

Village (village code) Nandikewar.

Post Jamugurhat District Sonitpur

State

Assam

Approach

About 45KM from Jupur in  
north-east direction

## 3. Property Type ( )

Buildings

- Palace  
 Fort  
 Citadel  
 Govt. building  
 Railway station  
 Defence building  
 Industrial building  
 Other public buildings  
 Residential building

Engineering structure

- Bridge  
 Tunnel  
 Other engineering

Religious structures

- Temple  
 Mosque  
 Minar  
 Church  
 Monastery  
 Stupa  
 Tomb, Mausoleum

Open space and related structures

- Public square  
 Park or garden  
 Graveyard  
 Baolis, Well

Other Structures

- Wall  
 Gateway  
 Pillar  
 Others (specify)

structure

- Tank  
 Cave

4. Property Use ( )

ABANDONED / IN USE

Present

Temple Remains

Past

Temple.

5. Age (Source) ( )

PERIOD ( )

YEARS ( )

Precise date of

Construction

Completion

Subsequent changes

Destruction / Demolition

Probably during Rudra Singha (1696-1717 AD)

Yes.

6. Ownership / Level of Protection ( )

SINGLE / MULTIPLE

Public

Archaeological Survey of India / State Archaeology Department

Any Other (Please specify)

Private

Any other (Please specify)

Name

Address

Phone

7. Association ( )

• WITH EVENTS

History

In Rituals

In Building Construction

Any other (specify)

• WITH PERSONS

Patron King Rudra Singha

Architect / Engineer

Any other (specify)

8. Statement of Significance ( )

- Architectural
- Archaeological
- Historical
- Religious
- Any other (specify) \_\_\_\_\_

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features

• Context

\* Drawings (Attach extra sheet if necessary)

Urban / Rural Setting  
Surroundings

Stand in Isolation In a Thatched structure  
Integral part of a Landscape / Street - Complex

• Quantification

Area Dimension ( L x B x H)

Old structure is collapsed.  
(m / cm / feet / inch)

Number of Blocks \_\_\_\_\_

Number of Storeys \_\_\_\_\_

• Spatial Organization

Orientation \_\_\_\_\_

Plan \_\_\_\_\_

Allocation of Spaces \_\_\_\_\_

ARCHITECTURAL STYLE

• Ornamentation

Exteriors \_\_\_\_\_

Interiors \_\_\_\_\_

Movable Collections

An image of Kalyani Durga of stone and Krishna of bronze is present.

\* Any Other (specify)

A copper-plate inscription related to the temple is reported.

10. Construction Technology

Structural System \_\_\_\_\_

Building Techniques \_\_\_\_\_

---

Material of Construction

---

---

### 11. Condition Assessment

---

In General

Good / Fair

- Sign of Deterioration
- Serious Deterioration
- Danger of Disappearance

In Brief (Attach extra sheet if necessary)

The old structure is not present and the history of it is too slowly forgotten. Need approach in proper line for unfolding facts.

### 12. Threats to the Property

---

- Natural
- Negligence
- Vandalism
- Urban Pressures