

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: OR /BLS-17

	SECTION I: IDENTIFICATION	
1. Name		
Present Past Other Name (if any):	: Durga Temple, Shergarh, Dist Balasore : ny): : Mahisasuri Mandir	
2. Location		
LONGITUDE 86 ⁰ 49 ⁷ 41 ⁷ E	LATITUDE 21°26′11″ N	ELEVATION 35 feet
Address	: Village (village code) Post : Shergarh Tehsil: Remuna State : Orissa	Khajura Sahi, Shergarh Via: Khantapada District: Balasore PIN: 756060
Approach	: The temple in Khajura sahi, Shergarh is located at a distance of 2.5 kms west of Phandi chowk in Balasore on the National Highway No - 5 leading from Balasore to Bhubaneswar.	
3. Property Type		
Buildings Palace Fort Citadel Government building Railway station Defence building Industrial building	Religious structures Temple Mosque Minar Church Monastery Stupa Tomb, Mausoleum	Other Structures Wall Gateway Pillar Others (specify):
Other public buildings	,	Note:
Residential building Engineering structure Bridge Tunnel Other engineering structure	Open space and related structures Public square Park or garden Graveyard Baolis, Well Tank Cave	The temple has a rekha vimana of Kalingan order.

4.	Property	Use

ABANDONED / IN USE: In use

Present : Living temple, the presiding deity is the Mahisasura-

mardini Durga, made of black chlorite.

Past : Worshipped.

5. Age (Source)

PERIOD : Somavamsi rule

YEARS : 10th -11th century A.D.

Precise date of Construction : --Completion : ---

Subsequent changes : Orissa State Archaeology renovated this temple under

X & XI Finance Commission Award.

Destruction / Demolition :

6. Ownership / Level of Protection

SINGLE /MULTIPLE : Multiple

Public: Archaeological Survey of : Protected Monument of Orissa State Archaeology

India / State Archaeology Department / Any Other (Please

specify)

Private : ---

Any other (Please specify) : Under the care of Pandas (Sevayatas), patronised by

the Senapati family.

Name : Seshadhara Senapati

Address : Orissa State Archaeology, Paryatan Bhawan, B.J.B.

Nagar, Bhubaneswar, Orissa

Phone : 0674-2432147

7. Association

WITH EVENTS

In History : ---

In Rituals : Durga puja,

In Building Construction : --Any other (specify) : ---

WITH PERSONS

Patron : Presently under the care of the Senapati family.

Architect / Engineer : ---

Any other (specify) : Orissa State Archaeology

8. Statement of Significance

	Architectural	:	✓	Architectural
	Archaeological	:	✓	Archaeological
	Historical			

Religious : 🗸 Religious

Any other (specify) : The temple is a renovated one and probably built in

Zamindari period, but on the sculptural ground, the original temple can be dated to the Somavamsi period.

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features			
 Context Urban / Rural Setting Surroundings 	:	* Drawings (Attach extra sheet if necessary) : No Rural setting	
Gurroundings		Stand in Isolation Complex Integral part of a Landscape / Street / Complex :	
 Quantification Area Dimension (L x B x H) 	:	2.80 mtrs x 3.45 mtrs x 5.70 mtrs (m / cm/ feet / inch)	
Number of Blocks Number of Storys	:	One	
 Spatial Organization Orientation Plan Allocation of Spaces 	:	Facing towards west. A rectangular <i>vimana</i> that stands over a platform of 0.65 mtrs. high 21.40 mtrs (L) X 9.70 mtrs (W)	
ARCHITECTURAL STYLEOrnamentationExteriors	÷	Devoid of any decoration except the incipient pidha	
Interiors Movable Collections	:	mundi design on the parsvadevata niches. Plain Mahisasuramardini Durga, Manasa, Ganesa(02nos), Surya, female deity, part of a vajramastaka in which	
* Any Other (specify)	:	Uma -Mahesvara with Saptamarikas are found. The temple is trirathaa on plan and triangabada in elevation.	
10. Construction Technology			
Structural System Building Techniques Material of Construction	:	Rekha vimana of impoverished Kalingan style. Ashlar dry masonry. Laterite is used for the construction of the temple whereas chlorite, used for the doorjambs and sculptures.	
11. Condition Assessment			
In General Good / Fair	:	Fair	
Sign of Deterioration Serious Deterioration Danger of Disappearance			

In Brief (Attach extra sh	eet if necessary):
---------------------------	--------------------

COMMENTS

Growth of vegetation and living organism like pipal tree, lichen and moss are found on the temple's outer surface.

12. Threats t	o the Property	
		✓ Natural ✓ Negligence Vandalism Urban Pressures
x	x x x x x x x x x x	x x x x x x x x x x x x x x x x x x x
	<u>SI</u>	CTION III: REFERENCES
13. Referenc	e Sources (publishe	and unpublished textual details)
		Temple Art of Orissa, Vol I, Leiden. eology in Orissa, Vol II, New Delhi.
14. Photogra	aphs	: 12 Nos.
		(attach list as in page 6, in case of multiple photographs
Photo Refere	ence	: :
15. Audio / V	/ideo	
		(related to rituals / performance / festivals etc.)
Reference DESCRIPTIC	DN	: :
16. Maps/Pla	ns/Drawings	
17. Listers		
NAME :	Jaya Shankar Nai	NAME:
18. Reviewer	rs	
NAME ·	Dr S Pradhan	NAME ·

COMMENTS: