

## INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

## **Documentation format for Archaeological / Heritage Sites / Monuments**

Serial No.: OR / BLG- 07 **SECTION I: IDENTIFICATION** 1. Name Present Chausathi Yogini Temple, Ranipur-Jharial, Dist.-Bolangir **Past** Other Name (if any): 2. Location **LONGITUDE** 82<sup>0</sup>57'55" E **LATTITUDE** 20<sup>0</sup>16'51" N **ELEVATION** 685 ft Address Village (village code) Ranipur Jharial Post: Jharial Via: Bangomunda Tehsil: Kantabanji **District**: Bolangir State: Orissa **PIN**: 767040 Approach The site is 32 kms from Kantabanji and 05 kms east of Mudapadar chowk on the Kantabanji-Titlagarh road, and on the right bank of the river Tong, a tributary of the river Tel, which itself is a tributary of the Mahanadi. 3. Property Type **Buildings** Religious structures Other Structures Wall Palace Temple Fort Mosque Gateway Pillar Citadel Minar Govt. building Church Others (specify) Railway station Monastery Defence building Stupa Industrial building Tomb, Mausoleum Other public buildings Residential building Engineering structure Open space and related Note: structures The temple is circular on plan and Bridge Public square hypaetheral in elevation and is Park or garden Tunnel another characteristic feature of Graveyard Other engineering structure Orissan temple architecture. It Baolis, Well was dedicated to tantric yogini cult Tank which practised esoteric- kapalika Cave rituals in the past. It is one of the two such temples in Orissa, the

other one is at Hirapur in Khurda

district.

		ABANDONED / IN USE: Abandoned
Present	:	It is a non-living temple, but well conserved and preserved as a tourist attraction.
Past	:	Worshipped.
5. Age (Source)		
PERIOD	:	Somavamsi rule
YEARS	•	9 <sup>th</sup> – 10 <sup>th</sup> centuries A.D.
Precise date of Construction	•	Early part of the 10 <sup>th</sup> century A.D.
Completion	•	
Subsequent changes	:	Conserved by Archaeological Survey of India.
Destruction / Demolition	:	
6. Ownership / Level of Protection	on_	
		SINGLE /MULTIPLE : Single
<b>Public</b> : Archaeological Survey of India / State Archaeology Department / Any Other (Please specify)	:	Protected Monument of Archaeological Survey of India
Private	:	
Any other (Please specify)	:	
Name	:	Archeological Survey of India, Bhubaneswar Circle
Address	:	153, VIP Area, Nayapalli, Bhubaneswar
Phone	:	0674-2558170
7. Association		
WITH EVENTS		
In History	:	
In Rituals	:	
In Building Construction	:	
Any other (specify)  • WITH PERSONS	:	
Patron		Archeological Survey of India, Bhubaneswar Circle
Architect / Engineer	:	
Any other (specify)	:	
8. Statement of Significance		
8. Statement of Significance  Architectural	: [	✓ Architectural
Architectural Archaeological	: [ : [	Architectural Archaeological
Archaeological Historical	:	Archaeological
Architectural Archaeological	: [	

## **SECTION II: DESCRIPTION**

9. Physical Description and Decorative Features				
Context Urban / Rural Setting Surroundings	:	* Drawings (Attach extra sheet	if necessary): No Rural setting	
Carroundings		Stand in Isolation Integral part of a Landscape / Street / Complex :	Stand in isolation	
<ul> <li>Quantification</li> <li>Area Dimension ( L x B x H)</li> </ul>	:	Diameter – 16.60 mtrs externall	y, 13.60 mtrs internally. (m / cm/ ft. / inch)	
Number of Blocks Number of Storys	:	Single 	(III / CIII/ II. / IIICII)	
<ul> <li>Spatial Organization         Orientation         Plan         Allocation of Spaces     </li> </ul>	: :	Facing towards east. Circular 16.60		
• Ornamentation Exteriors Interiors  Movable Collections * Any Other (specify)  10. Construction Technology	: :	The exterior of the temple is detection. The interior is relieved with 65 rd 48 accommodating well present have either broken images or building images are missing. At the roofed pillared mandapa that he Nataraj along with Ganesa and	niches. Out of 65 niches ved images, 11 niches block of stones and in 7 the centre there is a flat nouses an eight armed	
Structural System Building Techniques Material of Construction  11. Condition Assessment	:	It is a single hypaethral structur Ashlar dry masonry Granite	e and circular on plan.	
In General Good / Fair	:	Fair		
Sign of Deterioration Serious Deterioration Danger of Disappearance				
In Brief (Attach extra sheet if necessary):				
A few images are in obliterated conditions.				

12. Threats to	the Property	
	Ne Va	tural gligence ndalism pan Pressures
x x x x x x x		III: REFERENCES
13. Reference	Sources (published and un	
<ol> <li>P. K. Nay Orissa, No</li> <li>J. K. Pat unpublish</li> </ol>	rak, 2006, Temple of Weste ew Delhi.	
14. Photograp	ohs : :	39 Nos.
Photo Reference CAPTION  15. Audio / Vio	1Ce : :	ach list as in page 6, in case of multiple photographs)
10. Addio 7 Th		(related to rituals / performance / festivals etc.)
Reference DESCRIPTION	i :	
16. Maps/Plan	s/Drawings	
17. Listers		
NAME :	Ashis Ranjan Sahoo	NAME:
18.Reviewers		
NAME: COMMENTS	Prof. S. Pradhan	NAME: COMMENTS: