

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS Janpath, New Delhi -110 001, www.ignca.gov.in Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: OR / CTC - 75

SECTION I: IDENTIFICATION				
1. Name				
Present	: Mahamaya Bhattarika Tem Dist. – Cuttack	nple, Sasanga,		
Past Other Name (if any): 2. Location	: :			
LONGITUDE 85° 16 '19" E	LATITUDE 20° 22′ 06″ N	ELEVATION 163 feet		
Address	: Village (village code) Post : Sasanga Tehsil: Barambagarh State : Orissa	Sasanga Via: Barambagarh District: Cuttack PIN: 754031		
Approach	situated on the left side Athgarh to Narasinghpur I	of N.H – 65 leading from branching at a distance of 6 wk in Gopapura village. It is ba.		
3. Property Type				
Palace Fort Citadel Govt. building Railway station Defence building Industrial building Other public building Residential building	Religious structures Temple Mosque Minar Church Monastery Stupa Tomb, Mausoleum	Other Structures Wall Gateway Pillar Others (specify)		
Engineering structure Bridge Tunnel Other engineering structure	Park or garden vin Graveyard mu	te: e temple has a pidha nana, jagamohana and a nktimandapa of impoverished lingan order.		

4. Property Use ABANDONED / IN USE: In use Present Living temple, the presiding deity is Mahamaya Bhattarika seated crossed legged over a lotus seat. She displays varadmudra in the right hand and a fullblown lotus in the left hand. Past Worshipped 5. Age (Source) PERIOD During the princely rule of ex- state of Baramba. YEARS 18th century A.D. Precise date of Construction Completion Subsequent changes The present temple is a renovated one. **Destruction / Demolition** 6. Ownership / Level of Protection SINGLE /MULTIPLE: Multiple **Public**: Archaeological Survey of: Endowment Department, Government of Orissa. / State Archaeology Department / Any Other (Please specify) **Private** Any other (Please specify) Village Temple Committee Name Address Phone 7. Association WITH EVENTS In History According to the local people, the temple was built by Padmanabha Deva, the ruler of ex- princely state of Barambagarh. In Rituals Durgapuja is celebrated here with great pomp and rejoicings. In Building Construction Any other (specify) Marriage, thread ceremony, engagements, etc are performed here.

Endowment Department, Government of Orissa.

Village Temple Committee

8. Statement of Significance

WITH PERSONS

Architect / Engineer Any other (specify)

Patron

Architectural : ✓ Architectural Archaeological : ✓ Archaeological Historical :

Religious Religious Any other (specify) Though the present temple is renovated one but on the basis of loose sculptures and parsvadevata images, the original temple can be dated to the 18th century

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features

*Drawings (Attach extra sheet if necessary): No Context Rural setting

Urban / Rural Setting

Surroundings

Stand in Isolation

Integral part of a Landscape Stand in isolation

A.D. i.e. the rule of ex- princely state of Baramba.

/ Street / Complex :

Quantification

: 14.00 mtrs x 6.50 mtrs x 12.30 mtrs (approximate Area Dimension (LxBxH)

height)

(m / cm/ feet / inch)

Number of Blocks Three Number of Storys

Spatial Organization

Orientation Facing towards west.

Plan The vimana, jagamohana and muktimandapa of the

temple are square on plan.

Allocation of Spaces 17.00 mtrs (L) x 60.00 mtrs (W)

ARCHITECTURAL STYLE

Ornamentation

Exteriors Devoid of any decoration, except the deulacharinis

> over the beki and a pair of mastaka design in gandi on each side. The parsvadevata images are six-armed Mahisasuramardini Durga, four-armed Kartikeya and a four-armed Ganesa on the northern, eastern and

southern side respectively.

Interiors Plain

Movable Collections The loose sculptures of the original temple are either

> attached on the exterior wall or the inner wall of the temple are Nabagraha slab (Nos-03) Surya, Kuvera,

Ganesa.

* Any Other (specify) The temple is pancharatha on plan and

panchangabada in elevation.

10. Construction Technology

Structural System All the components i.e. vimana, jagamohana and

muktimandapa are pidha order of impoverished

Kalingan order

Building Techniques Ashlar masonry

Material of Co	onstruction	:	Stone is used for the construction of the temple and the entire surface is plastered and white washed.
11. Condition	Assessment		
In General	Good / Fair	:	Good
Serious E	eterioration Deterioration f Disappearance		
In Brief (Attac	ch extra sheet if nec	ess	ary):
Due to recent	renovation work by th	ne lo	cal people the temple is in good state of preservation.
12. Threats to	the Property		
x x x x x x x			Natural Negligence Vandalism Urban Pressures X X X X X X X X X X X X X X X X X X X
	<u>SE</u>	CTI	ON III: REFERENCES
13. Reference	Sources (published	and	l unpublished textual details)
1. R.P. Moh	apatra, 1986, <i>Archae</i>	olog	ny in Orissa, Vol II, Delhi.
14. Photograp	ohs: 55 nos		
			(attach list as in page 6, in case of multiple photographs)
Photo Refere	nce	:	
15. Audio / Vi	deo		(related to rituals / performance / festivals etc.)
Reference DESCRIPTION	N	:	(related to fituals / performance / restivals etc.)
16. Maps/Plar	ns/Drawings		
17. Listers			
NAME :	Jaya Shankar Naik		NAME:
18. Reviewers	S		
NAME: COMMENTS	Dr. S. Pradhan		NAME: COMMENTS: