

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in
Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: OR / KDA/ BSR- 218

SECTION I: IDENTIFICATION						
1. Name						
Present Past Other Name (if any): 2. Location		Barabhuji Gumpha (Cave No. 8 ASI), Khandagiri Hillock, Bhubaneswar,DistKhurda 				
LONGITUDE 85 ⁰ 45'20" E	LATITUDE 20 ⁰ 15'74" N	ELEVATION 247 ft.				
LONGITUDE 85 45 20 E	LATITUDE 20 1374 N	ELEVATION 247 II.				
Address	: Village (village code)	Khandagiri Hillock				
	Post : Khandagiri Tehsil: Bhubaneswar	Via: Bhubaneswar District: Khurda				
	State: Orissa	PIN : 751030				
 Approach It is situated close to the Navamunigumpha and on the right side of the road (MDR-78), branching from the National Highway No. 5 at Khandagi square. 						
3. Property Type Buildings	Religious structures	Other Structures				
Palace	Temple	Wall				
Fort	Mosque	Gateway				
Citadel	Minar	Pillar				
Govt. building	Church	Others (specify)				
Railway station	Monastery					
Defence building	Stupa					
Industrial building	Tomb, Mausoleum					
Other public buildings Residential building						
Residential building						
Engineering structure	Open space and related structures	lote: t is an elongated cell,				
Bridge	Public square	preceded by a pillared				
Tunnel	Park or garden ;					
Other engineering structure	Graveyard	rerandah.				
	Baolis, Well					
	Tank					
	✓ Cave					

4. Property Use

ABANDONED / IN In use

USE:

The Tirthankara and Sasanadevi images are now Present

worshipped by the people as Brahaminical deities.

Past : It was both dwelling and worshipping place for

Jaina monks.

5. Age (Source)

PERIOD Mahameghavahana Chedi dynasty

1st century B.C. YEARS

Precise date of Construction

Completion

Subsequent changes Though it is protected by Archaeological Survey of

> India, modern constructions like concrete roof and a new Siva temple have been constructed in front

of the cave.

Destruction / Demolition

6. Ownership / Level of Protection

SINGLE /MULTIPLE Single

Public: Archaeological Survey: Protected Monument of Archaeological Survey of India

of India / State Archaeology Other

Department / Any

(Please specify)

Private ---Any other (Please specify) ---Name

Bhubaneswar Circle, 153, VIP Area, Nayapalli, Address

Bhubaneswar, Pin - 751015

Phone 0674-2558170

7. Association

WITH EVENTS

In History In Rituals In Building Construction Any other (specify)

WITH PERSONS

Patron Originally Kharavela, the Emperor of Kalinga, now

Archaeological Survey of India.

Architect / Engineer Any other (specify)

8. Statement of Significance

1	Architectural	✓	Architectural
1	Archaeological	✓	Archaeological
/	Historical	✓	Historical
	Religious	✓	Religious
	Any other (specify)	:	Epigraphic red

Epigraphic record in Hatigumpha ascribes it to the Kharavela who was ruling in 1st century BC in Kalinga. But the images carved in the cell are iconographically dated to the 10th- 11th century AD.

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features

Context * Drawings (Attach extra sheet if necessary): No Urban / Rural Setting : Urban setting

Surroundings

Stand in Isolation Complex

Integral part of a Landscape

/ Street / Complex :

Quantification

Area Dimension (L x D x H) : 6.75 mtrs x 2.00 mtrs x 2.20 mtrs

(m / cm/ feet / inch)

Number of Blocks : Two, consists of a cella & verandah

Number of Storys : One

Spatial Organization

Orientation : Facing towards East

Plan : Both the cella and *verandah* is rectangular on plan

Allocation of Spaces :

ARCHITECTURAL STYLE

Ornamentation

Exteriors : ---

Interiors : There are altogether twenty five figures of

Tirthankaras on the walls of the cell on three sides, Parsvanatha being repeated twice. Beneath the Tirthankara, their respective Sasanadevis are found. Twelve armed Chakareswari and Rohini are represented in the left and right wall of *Verandah*

respectively.

Movable Collections : --* Any Other (specify) : ---

10. Construction Technology

Structural System : A large chamber as like a dormitory preceded by a

pillared Verandah.

Building Techniques : Rock cut **Material of Construction** : Sandstone

11. Condition Assessment							
In General	Good / : Fair						
	Fair						
	✓ Sign of Deterioration :						
	Serious Deterioration						
	Danger of Disappearance						
In Brief (Attach extra sheet if necessary): The images are now worshipped as Brahminical deity. People apply vermilion, oil and water over the image .This is a great threat for the defacing of sculptures.							
12. Threats to the Property							
	✓ Natural						
	Negligence						
	✓ Vandalism Urban Pressures						
* * * * * * * * * * * * * * * * * * * *	Orban Pressures						
<u> </u>	SECTION III: REFERENCES						
13. Reference Sources (publ	ished and unpublished textual details)						
 Debala Mitra, 1985, <i>Udayagiri & Khandagiri</i>, New Delhi. R. P. Mohapatra, 1986, <i>Archaeology in Orissa</i>, Vol I, New Delhi. Nilamani Senapati (Ed.), 1977, <i>Orissa District Gazetteers</i>, Puri, Cuttack. 							
14. Photographs: 11 nos							
14. 1 notographs. 11 nos	(attach list as in page 6, in case of multiple photographs)						
Photo Reference	:						
CAPTION	:						
15. Audio / Video							
IO. Addio / Video	(related to rituals / performance / festivals etc.)						
Reference	:						
DESCRIPTION	:						
16. Maps/Plans/Drawings							
17. Listers							
NAME: Ashis Ranjan Sa	ahoo NAME :						
19 Paviawara							
18. Reviewers NAME: Dr. S. Pradhar	NAME :						
COMMENTS	COMMENTS						
COMMENTO	·						