

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in
Documentation format for Archaeological / Heritage Sites / Monuments
Serial No.: OR / KDA/ BSR- 228

SECTION I : IDENTIFICATION 1. Name		
Present Past Other Name (if any): 2. Location		pha (Cave No- 11 ASI), ubaneswar,DistKhurda
LONGITUDE 85 ⁰ 47'28" E	LATITUDE 20 ⁰ 10'74" N	ELEVATION 245 ft.
Address Approach 3. Property Type	temple of Khandagiri, (MDR-78), branching No. 5 at Khandagiri Sq	Via: Bhubaneswar District: Khurda PIN: 751030 In north of Astabhuja Duga on the left side of the road from the National Highway uare.
Buildings Palace Fort Citadel Govt. building Railway station Defence building Industrial building Other public buildings Residential building Engineering structure Bridge Tunnel Other engineering structure	structures Public square Park or garden Graveyard Baolis, Well F F F F F F F F F F F F	Other Structures Wall Gateway Pillar Others (specify) Note: Rock cut caves hewn out rom natural rock bed in a nuch higher level than the ground. It has two lilapidated cell proceeded

✓ Cave

by a pillared Verandah.

4. Property Use

ABANDONED / **IN** Abandoned

USE:

: It is abandoned now but a point of tourist Present

attraction.

Past : It was used for worship as well as dwelling place

of Jaina Monks.

5. Age (Source)

Mahameghavahana Chedi dynasty PERIOD

1st century B.C. YEARS

Precise date of Construction Completion ___

The caves are hewn out during 1st century BC but Subsequent changes

the sculptures are carved in the cell can be dated

to Samavamsis period i.e. 11th century AD.

Destruction / Demolition

6. Ownership / Level of Protection

SINGLE /MULTIPLE Single

India

Protected Monument of Archaeological Survey of **Public**: Archaeological Survey:

of India / State Archaeology

Department / Other Any

(Please specify)

Private Any other (Please specify) ---Name

Address Bhubaneswar Circle, 153, VIP Area, Nayapalli,

Bhubaneswar, Pin - 751015

Phone 0674-2558170

7. Association

WITH EVENTS

In History In Rituals In Building Construction Any other (specify)

WITH PERSONS

Originally Kharavela, the Emperor of Kalinga, now Patron

Archaeological Survey of India.

Architect / Engineer ---Any other (specify) ---

8. Statement of Significance

✓ Architectural Architectural

Archaeological Archaeological Historical Historical Religious Religious Any other (specify) Epigraphic record in Hatigumpha ascribes it to Kharavela who was ruling in 1st century BC. But the sculptures engraved in the rear and side wall of the cell are of Somavamsis period i.e. 11th century AD. **SECTION II: DESCRIPTION** 9. Physical Description and Decorative Features * Drawings (Attach extra sheet if necessary): No Context **Urban / Rural Setting** Urban setting Surroundings Stand in Isolation Complex Integral part of a Landscape / Street / Complex : Quantification Right Cell: 3.20 mtrs. X 2.10 mtrs. x 2.05 mrts Area Dimension (LxDxH) Left Cell: 3.22 mtrs x 2.15 mtrs. x 2.10 mtrs. (m / cm/ feet / inch) Number of Blocks Two Number of Storys **Spatial Organization** Orientation Facing towards south Plan Two Rectangular cells with traces of rectangular pillared Verandah. 6.50 mtrs x 5.00 mtrs in length & breadth Allocation of Spaces respectively. ARCHITECTURAL STYLE Ornamentation Exteriors Interiors Five Tirthankara images, two are of Rishabhanatha and three are of Parsvanatha are engraved in the rear side wall of the cell No. 1. In other hand cell No.2 represented two Parsvanatha images and one Rishabhanatha image in the rear wall. Movable Collections Both the ceiling of the Verandah and the cellas are * Any Other (specify) flat-roofed.

10. Construction Technology

Structural System : Originally it consisted of two cells preceded by a

pillared verandah. Now two pillars and floor of the

	two cells along with the <i>verandah</i> were quarried by stone cutter.	
Building Techniques Material of Construction	Hewed out of natural rock.Sandstone	
11. Condition Assessment	. Salidstone	
In General	Good / : Fair	
	Fair	
	Sign of Deterioration : Erosion due to weathering	
	Serious Deterioration	
	Danger of Disappearance	
	f necessary): done upto a 5.60 mtrs below the floor level of the caves.	
12. Threats to the Property	✓ Natural	
	Negligence	
	✓ Vandalism	
	Urban Pressures	
x x x x x x x x x x x x x x x x x x x	× × × × × × × × × × × × × × × × × × ×	
SECTION III: REFERENCES		
13. Reference Sources (published and unpublished textual details)		
2. R. P. Mohapatra, 1986, A.	agiri & Khandagiri, New Delhi. rchaeology in Orissa, Vol I, New Delhi. 1977, Orissa District Gazetteers, Puri, Cuttack.	
14. Photographs : 07 nos		
	(attach list as in page 6, in case of multiple photographs)	
Photo Reference CAPTION	: :	
15. Audio / Video		
Defenses	(related to rituals / performance / festivals etc.)	
Reference DESCRIPTION		
16. Maps/Plans/Drawings		
17. Listers		
NAME: Ashis Ranjan S	ahoo NAME :	
18. Reviewers		
NAME: Dr. S. Pradhan	NAME :	

COMMENTS

COMMENTS

: