

Other engineering structure

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: OR / NGH - 15

	SECTION I: IDENTIFICATION				
1. N	lame				
Pas	sent t er Name (if any):	: Gatisvara Temple, Malisahi, Dist Nayagarh : :			
LO	NGITUDE 85 ⁰ 04' 41" E	LATITUDE 20 ⁰ 10' 40" N ELEVATION 225 f	ť		
Ado	Iress	: Village (village code) Malisahi Post : Malisahi Via: Nayagarh Tehsil: Nayagarh District: Nayagarh State : Orissa PIN: 752069			
Approach		: The temple, on the right bank of the river Baghamari is located on the left side of the road leading from Nayagarh to Mahipur at a distance of 10 kms from Nayagarh town.			
3. P	roperty Type				
	Buildings	Religious structures Other Structures			
	Palace	✓ Temple			
	Fort	Mosque Gateway			
	Citadel	Minar Pillar			
	Govt. building	Church Others (specify):			
	Railway station	Monastery			
	Defence building	Stupa			
	Industrial building	Tomb, Mausoleum			
	Other public buildings	Note.			
	Residential building	I I I I I I I I I I I I I I I I I I I	pidha		
	Engineering structure Bridge	Open space and related vimana and a jagamoh structures impoverished Kalingan of			
	Tunnel	Public square Park or garden			

Graveyard Baolis, Well Tank Cave

		ABANDONED / IN USE : In use
Present		Living temple, the presiding deity is a Sivalinga withir a circular <i>yonipitha</i> which is submerged under water through out the year.
Past	:	Worshipped
5. Age (Source)		
PERIOD	:	During the rule of the former rulers of Nayagarh state.
YEARS	:	18 th century A.D.
Precise date of Construction	:	
Completion	:	
Subsequent changes	:	
Destruction / Demolition	:	
6. Ownership / Level of Protect	ion	
		SINGLE /MULTIPLE : Multiple
Public : Archaeological Survey o India / State Archaeology Department / Any Other (Please specify)	/	Endowment Department, Government of Orissa.
Private	:	
Any other (Please specify)	:	Village Temple Committee.
Name	:	
Address	:	
Phone	:	
7. Association		
WITH EVENTS		
In History	:	
In Rituals	:	Sivaratri, Durgapuja, etc are observed here.
In Building Construction	:	
Any other (specify)	:	Thread ceremony, engagement, marriage, etc are observed here.
WITH PERSONS		
Patron	:	Originally the rulers of former Nayagarh state, now Endowment Department, Government of Orissa.
	:	
Architect / Engineer	•	Village Temple Committee.
-	•	
Any other (specify)	•	
Any other (specify)	• :	✓ Architectural
Architect / Engineer Any other (specify) 8. Statement of Significance Architectural Archaeological		
Any other (specify) 8. Statement of Significance Architectural		
Any other (specify) 8. Statement of Significance Architectural Archaeological Historical Religious		✓ Architectural
Any other (specify) 8. Statement of Significance Architectural Archaeological Historical	·	

SECTION II: DESCRIPTION

 Context Urban / Rural Setting Surroundings 	:	* Drawings (Attach extra sheet if necessary) : No Rural setting
Surroundings		Stand in IsolationIntegral part of a Landscape /StreetStreet / Complex :
Quantification		
Area Dimension (L x B x H)	:	22.10 mtrs x 7.50 mtrs x 7.00 mtrs (m / cm/ feet / inc
Number of Blocks	:	Two
Number of Storys	:	N.A.
Spatial Organization		
Orientation	:	Facing towards east.
Plan	:	The vimana and jagamohana are square on plan the
Allocation of Spaces	:	stands over a <i>pista</i> of 0.85 mtrs high. 58.50 mtrs (L) x 53.00 mtrs (W).
ARCHITECTURAL STYLE		
Ornamentation		
Exteriors	:	Devoid of any decorations, except <i>deulacharinis</i> a <i>dopichhasimhas</i> over the <i>beki</i> to support the <i>amlas</i> and projecting lion on each side of the <i>gandi</i> .
Interiors	:	Plain
Movable Collections	:	Uma-Mahesvara <i>murty</i> (03 Nos.), Varaha
* Any Other (specify)	:	The temple is provided with a buttress type platform to the half of its <i>bada</i> .
10. Construction Technology		
Structural System	:	Pidha vimana and jagamohana of impoverish
Building Tochniques		Kalingan order.
Building Techniques Material of Construction	:	Ashlar masonry. Khandolite stone is used for the construction of t temple and the entire temple is thickly lime plaster and white washed.
11. Condition Assessment		
In General Good / Fair	:	Good
Sign of Deterioration		

Sign of Deterioration Serious Deterioration Danger of Disappearance

In Brief (Attach extra sheet if necessary):

The temple is in a good state of preservation.

12. Threats to the Property

\checkmark	Natural
	Negligence
	Vandalism
	Urban Pressures
x x x x x x x x x x x x x x x x x x x	x x x x x x x x x x x x x x x x x

SECTION III: REFERENCES

13. Reference Sources	(published and unpublished textual of	details)
-----------------------	---------------------------------------	----------

- 1. R.P.Mohapatra, 1986, Archaeology in Orissa, Vol. -I, Delhi.
- 2.

Х

- 3.
- 4.

14. Photographs: 13 nos

	(attach list as in page 6, in case of multiple photographs)
Photo Reference CAPTION	

15. Audio / Video

		(related to rituals / performance / festivals etc.)
Reference DESCRIPTION	:	
16. Maps/Plans/Drawings		

17. Listers

NAME :	Jaya Shankar Naik	NAME :				
18. Reviewers						
NAME : COMMENTS	Dr. S. Pradhan	NAME : COMMENTS :				