INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS Janpath, New Delhi -110 001, www.ignca.gov.in

## Documentation format for Archaeological / Heritage Sites / Monuments

#### Serial No.: OR / NGH - 04

	SECTION I : IDENTIFICATION	
1. Name		
Present Past Other Name (if any):	<ul> <li>Gopinatha Temple, Nilama Kantilo, Dist Nayagarh</li> <li></li> <li></li> </ul>	adhava Temple Complex,
<b>LONGITUDE</b> 85 <sup>0</sup> 11' 42" E	<b>LATITUDE</b> 20 <sup>0</sup> 21' 52" N	ELEVATION 275 ft
Address	: Village (village code) Post : Kantilo Tehsil: Khandapadagarh State : Orissa	Nilamadhava Temple Complex, Kantilo Via: Kantilo District: Nayagarh PIN: 752070
Approach	• · ·	
3. Property Type		
Buildings         Palace         Fort         Citadel         Govt. building         Railway station         Defence building         Industrial building	Religious structures         ✓       Temple         Mosque	Other Structures Wall Gateway Pillar Others (specify):
Industrial building Other public buildings Residential building		l <b>ote.</b> he temple has a <i>rekha</i>
Engineering structure         Bridge         Tunnel         Other engineering structure	Open space and related V structures ja	<i>imana</i> and a <i>pidha</i> <i>agamohana</i> of impoverished <i>alingan</i> order.

	ABANDONED / IN USE : In use
Present	: Living temple, the presiding deities are lord Krism made of black chlorite and his consort Radha made of brass.
Past	: Worshipped
5. Age (Source)	
PERIOD	: During the princely rule of the former state of Khandapadagarh.
YEARS	: 19 <sup>th</sup> century Ă.D.
Precise date of Construction	:
Completion	:
Subsequent changes	:
<b>Destruction / Demolition</b>	:
6. Ownership / Level of Protectio	n
	SINGLE /MULTIPLE : Multiple
<b>Public</b> : Archaeological Survey of India / State Archaeology Department / Any Other (Please specify)	: Endowment Department, Government of Orissa
Private	:
Any other (Please specify)	:
Name	:
Address	:
Phone	:
7. Association	
• WITH EVENTS In History	
In Rituals	<i>Janmastami, Radhastami,</i> etc are observed here.
In Building Construction	· ····
Any other (specify)	Marriage, thread ceremony, etc are held here.
WITH PERSONS	
Patron	: Previously the ruling house of ex-state of
	Khandapadagarh, now Endowment Department, Government of Orissa
Architect / Engineer	:
Any other (specify)	:
8. Statement of Significance	
Architectural	: ✓ Architectural
Archaeological	
Historical	:
Thstorical	
Religious	: ✓ Religious
	: On architectural ground and local informations the temp
Religious	<ul> <li>✓ Religious</li> <li>On architectural ground and local informations the templ can be assigned to the last part of the 19<sup>th</sup> century AD.</li> </ul>

# **SECTION II: DESCRIPTION**

<ul> <li>Context</li> <li>Urban / Rural Setting</li> <li>Surroundings</li> </ul>	:	* <b>Drawings (Attach extra sheet if necessary)</b> : No Rural setting
Sunounungs		Stand in IsolationIntegral part of a Landscape /ComplexStreet / Complex :
• <b>Quantification</b> Area Dimension ( L x B x H)	:	9.75 mtrs x 4.20 mtrs x 8.00 mtrs (approximate height (m / cm/ feet / incl
Number of Blocks Number of Storys	:	Two N.A.
Spatial Organization     Orientation     Plan     Allocation of Spaces	:	Facing towards east. The <i>vimana</i> and <i>jagamohana</i> are square on plan tha stands over a platform of 0.65 mtrs high. 42.75 mtrs (L) x 34.00 mtrs (W)
ARCHITECTURAL STYLE • Ornamentation Exteriors	:	Decorated with architectural motifs like dopichhasimhas and Garuda image over the bek projecting lion on each raha and sporadic images of mithuna and maithuna, goose, lotus design etc.
Interiors Movable Collections * <b>Any Other</b> (specify)	:	Plain Nil The temple is <i>pancharatha</i> on plan an <i>panchangabada</i> in elevation.
10. Construction Technology		
Structural System Building Techniques Material of Construction	:	Rekha vimana and pidha jagamohana of impoverishe Kalingan order. Ashlar masonry Stone is used for the construction of the temple an the entire surface is thickly lime plastered and whit washed.
11. Condition Assessment         In General       Good / Fair		Good
Sign of Deterioration Serious Deterioration		

#### In Brief (Attach extra sheet if necessary):

Danger of Disappearance

The temple is in a good state of preservation.

## 12. Threats to the Property

Natural
Negligence
Vandalism
Urban Pressures

## **SECTION III:** REFERENCES

13. Reference Sources (published and unpublished textual details)			
1. 2.	R. P. Mohapatra, 1986, Archaeology in Orissa, Vol I, Delhi.		

#### 14. Photographs: 13 nos

	(attach list as in page 6, in case of multiple photographs)
Photo Reference CAPTION	:
15. Audio / Video	
	(related to rituals / performance / festivals etc.)
Reference	:
DESCRIPTION	:
16. Maps/Plans/Drawings	
17. Listers	

 NAME :
 Jaya Shankar Naik
 NAME :

 18. Reviewers
 NAME :

 NAME :
 Dr. S. Pradhan

 NAME :
 COMMENTS