

# INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

# **Documentation format for Archaeological / Heritage Sites / Monuments**

		Serial No.: OR / NGH - 13
1. Name	SECTION I: IDENTIFICATION	
Present  Past Other Name (if any):	<ul><li>: Gopinatha Temple, Ja Khandapadagarh, Dist</li><li>:</li><li>:</li></ul>	agannatha Temple Complex, Nayagarh
<b>LONGITUDE</b> 85 <sup>0</sup> 10' 21" E	<b>LATITUDE</b> 20 <sup>0</sup> 15' 47" N	<b>ELEVATION</b> 216 ft
Address	: Village (village code) Post : Khandapadagarh Tehsil: Khandapadagarl State : Orissa	
Approach	temple complex near palace is situated on th	reme north of the Jagannatha the Khandapadagarh royal e left side of the road leading Kantilo and about 17 kms from
3. Property Type		
Buildings  Palace Fort Citadel Govt. building Railway station Defence building	Religious structures  ✓ Temple     Mosque     Minar     Church     Monastery     Stupa	Other Structures  Wall Gateway Pillar Others (specify):
Industrial building Other public buildings	Tomb, Mausoleum	Note:
Residential building  Engineering structure	Open space and related structures	The temple consists of a pidha vimana, jagamohana and a processional path of
Bridge Tunnel Other engineering structure	Public square Park or garden Graveyard Baolis, Well Tank Cave	impoverished <i>Kalingan</i> order.

#### 4. Property Use ABANDONED / IN USE: In use **Present** Living temple, the presiding deities are Krisna and Radha made of black chlorite. **Past** Worshipped 5. Age (Source) During the princely rule of the former state of **PERIOD** Khandapadagarh. 19<sup>th</sup> century A.D. **YEARS** Last decade of the 19<sup>th</sup> century A.D. **Precise date of Construction** Completion Subsequent changes ---**Destruction / Demolition** 6. Ownership / Level of Protection SINGLE /MULTIPLE : Multiple **Public**: Archaeological Survey of: Endowment Department, Government of Orissa. India State Archaeology 1 Department / Any Other (Please specify) **Private** Under the care and maintenance of the present Any other (Please specify) successor Bibhuti Bhusan Singh Mardaraja Name Address Phone 7. Association WITH EVENTS In History In Rituals Janmastami, Radhastami, etc are observed here. In Building Construction Any other (specify) WITH PERSONS **Patron** Endowment Previously ex-rulers family, now Department, Government of Orissa. **Architect / Engineer** Any other (specify) 8. Statement of Significance Architectural

Architectural : ✓ Architectural
Archaeological : ✓ Archaeological
Historical :
Religious :

Any other (specify) : On the basis of architectural features and local information,

the temple can be assigned to the last decade of the 19th

century A.D.

## **SECTION II: DESCRIPTION**

### 9. Physical Description and Decorative Features

• Context \* Drawings (Attach extra sheet if necessary) : No

Urban / Rural Setting

Surroundings

Stand in Isolation

Integral part of a Landscape /

Street / Complex :

Quantification

Area Dimension ( $L \times B \times H$ ) : 19.40 mtrs  $\times$  10.00 mtrs  $\times$  7.50 mtrs (approximate

height)

(m / cm/ feet / inch)

Urban setting

Complex

Number of Blocks : Two Number of Storys : N.A.

• Spatial Organization

Orientation : Facing towards east.

Plan : The *vimana* and *jagamohana* are square on plan that

stands over a platform of 1.10 mtrs high.

Allocation of Spaces : ---

**ARCHITECTURAL STYLE** 

Ornamentation

Exteriors : Devoid of decoration, except *pidhamundi* niches over

the *parsvadevata* niches housing Varaha, Narasimha and Trivikrama on the southern, western and northern side respectively; *udyotasimhas* on the *gandi* on each side; *gaja-vidalas* and *nayika* figures are designed as a non-functional bracket and seven ornamental arches on the longitudinal and three arches on lateral side of the temple. The doorjambs are decorated with scroll

motif.

Interiors : Plain Movable Collections : Nil

\* **Any Other** (specify) : In elevation, the temple has multi-segmented *bada*.

10. Construction Technology

Structural System : Pidha vimana and pidha jagamohana of impoverished

Kalingan order.

**Building Techniques** : Ashlar mashnory and English bond technique.

Material of Construction : Stone and bricks are used for the construction of the

temple and the entire surface is thickly lime plastered

and white washed.

11. Condition Assessment

In General Good / Fair : Fair

Serious Deterioration Danger of Disappearance  In Brief (Attach extra sheet if necessary):  Lichen and moss are noticed on the exterior surface and plastered are chipped off places of the temple.  12. Threats to the Property    V	fin som
Lichen and moss are noticed on the exterior surface and plastered are chipped off places of the temple.  12. Threats to the Property    V	f in som
places of the temple.  12. Threats to the Property    V	f in som
✓ Natural ✓ Negligence ✓ Vandalism Urban Pressures	
✓ Negligence	
	xxxx
SECTION III. DEFEDENCES	
<u>SECTION III:</u> REFERENCES	
13. Reference Sources (published and unpublished textual details)	
1	
14 Photographs: 46 nos	
14. Photographs: 16 nos  (attach list as in page 6, in case of multiple pho	otograp
Photo Reference : CAPTION :	5 1
15. Audio / Video	
(related to rituals / performance / fes	tivals e
Reference : DESCRIPTION :	
16. Maps/Plans/Drawings	
· ·	
17. Listers	
17. Listers  NAME: Jaya Shankar Naik NAME:	