

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

		Serial No., OK / NGH - 12		
SECTION I: IDENTIFICATION				
1. Name				
Present	: Narayana Temple, Jaga Khandapadagarh, Dist N	•		
Past	:			
Other Name (if any):	:			
LONGITUDE 85 ⁰ 10' 21" E	LATITUDE 20 ⁰ 15' 47" N	ELEVATION 216 ft		
Address	: Village (village code) Post : Khandapadagarh Tehsil:Khandapadagarh State : Orissa	Khandapadagarh Via:Khandapadagarh District: Nayagarh PIN: 752077		
Approach	shrine Jagannatha, within	of 5 mtrs north of the main the complex is situated on leading from Nayagarh to from Nayagarh township.		
3. Property Type				
Buildings	Religious structures	Other Structures		
Palace	✓ Temple	Wall		
Fort	Mosque	Gateway		
Citadel	Minar	Pillar		
Govt. building	Church	Others (specify):		
Railway station	Monastery			
Defence building	Stupa			
Industrial building	Tomb, Mausoleum			
Other public buildings	N	ote.		
Residential building	T	he temple has a <i>pidha</i>		
Engineering structure	Open space and related ja structures	mana, an antarala and a gamohana of impoverished alingan order.		
Bridge	Public square	-		
Tunnel	Park or garden			
Other engineering structure	Graveyard			
	Baolis, Well			
	Tank			
	Cave			

4. Property Use				
		ABANDONED / IN USE: In use		
Present	:	Living temple, the presiding deity is a four-armed Visnu made of black chlorite which is kept on a high pedestal.		
Past	:	Worshipped		
5. Age (Source)				
PERIOD	:	During the princely rule of the former state of Khandapadagarh.		
YEARS	:	20 th century A.D.		
Precise date of Construction	:	Early part of the 20 th century A.D.		
Completion Subsequent changes	:			
Destruction / Demolition	:			
6. Ownership / Level of Protection				
•		SINGLE /MULTIPLE : Multiple		
Public: Archaeological Survey of India / State Archaeology Department / Any Other (Please	:	Endowment Department, Government of Orissa.		
specify) Private				
Any other (Please specify)	:	Under the care and maintenance of the present successor Bibhuti Bhusan Singh Mardaraja.		
Name	:			
Address Phone	:			
7. Association	•			
WITH EVENTS				
In History In Rituals In Building Construction Any other (specify) WITH PERSONS	: : :	Janmastami, Dola Purnima, etc are observed here		
Patron	:	Previously ex-rulers family, now Endowment Department, Government of Orissa.		
Architect / Engineer Any other (specify)	:			
	•			
8. Statement of Significance				
Architectural Archaeological Historical Religious	: : : : : : : : : : : : : : : : : : : :	✓ Architectural		
Any other (specify)	:	On architectural ground and local information, the temple can be assigned to the early part of the 20 th century A.D.		

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features

• Context * Drawings (Attach extra sheet if necessary) : No

Urban / Rural Setting :

Urban setting

Surroundings

Stand in Isolation

Integral part of a Landscape /

Complex

Street / Complex :

Quantification

Area Dimension (L x B x H) : 11.00 mtrs x 5.60 mtrs x 7.00 mtrs

(m / cm/ feet / inch)

Number of Blocks : Three, consists of a *vimana*, *antarala* and a

jagamohana.

Number of Storys : N.A.

Spatial Organization

Orientation : Facing towards east.

Plan : The *vimana* and *jagamohana* are square on plan that

stands over a platform of 0.78 mtrs high.

Allocation of Spaces : ---

ARCHITECTURAL STYLE

Ornamentation

Exteriors : Devoid of decoration, except *pidhamundi* niches over

the *parsvadevata* niches enshrining Varaha, Narasimha and Trivikrama on the south, west and northern side respectively, *deulacharinis* and *dopichhsimhas* over the *beki* and *udyotasimhas* on the

top tier of the *gandi* on each side.

Interiors : Plain Movable Collections : Nil

* Any Other (specify) : The temple is pancharatha on plan and

panchangabada in elevation. The jagamohana is provided with an ornamental arches opening one on

each side.

10. Construction Technology

Structural System : All the components are *pidha* order of impoverished

Kalingan style.

Building Techniques : English bond technique.

Material of Construction : Bricks are used for the construction of the temple and

the entire surface is thickly plastered and white

washed.

11. Condition Assessment

In General Good / Fair : Fair

Sign of Deterioration Serious Deterioration Danger of Disappearance	
In Brief (Attach extra sheet if n	ecessary):
Lichen and moss are noticed over	er the temple surface.
12. Threats to the Property	✓ Natural ✓ Negligence ✓ Vandalism Urban Pressures ✓ X X X X X X X X X X X X X X X X X X X
<u>\$</u>	SECTION III: REFERENCES led and unpublished textual details)
1	ed and unpublished textual details)
14. Photographs: 09 nos	(attach list as in page 6, in case of multiple photographs)
Photo Reference CAPTION	:
15. Audio / Video	
	(related to rituals / performance / festivals etc.)
Reference DESCRIPTION	: :
16. Maps/Plans/Drawings	
17. Listers	
NAME: Jaya Shankar Na	aik NAME:
18. Reviewers	
NAME: Dr. S. Pradhan COMMENTS	NAME: COMMENTS: