

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: 0R / PRI- 41

1. Name	SECTION I : IDENTIFICATIO	DN
Present Past Other Name (if any):	: Arjunesvara Temple , : :	Haladibasanta, DistPuri.
LONGITUDE	LATITUDE	ELEVATION
Address	: Village (village code Post : Khairi Tehsil: Pipili State : Orissa) Haladibasanta Via: Pipili District: Puri PIN: 752104
Approach	about 5 kms from Dh	left bank of the river Daya and auli. The site can be approached on the left embankment of the
3. Property Type		
Palace Fort Citadel Govt. building Railway station Defense building Industrial building Other public buildings	Religious structures Temple Mosque Minar Church Monastery Stupa Tomb, Mausoleum	Other Structures Wall Gateway Pillar Others (specify):
Residential building Engineering structure Bridge Tunnel	Open space and related structures Public square Park or garden	Note: The temple has a rekha vimana and pidha jagamohana of Kalingan order.
Other engineering structure	Graveyard Baolis, Well Tank Cave	

4. Property Use ABANDONED / IN USE: Abandoned Present It is a living temple and the presiding deity is a patalaphuta Sivalinga within a circular yonipitha made of black chlorite and 0.68 mtrs below the chandrasila level. Past Worshipped. 5. Age (Source) PERIOD Somavamsi rule 10th century A.D. YEARS **Precise date of Construction** 10th century A.D. Completion Subsequent changes The jagamohana is a latter addition and it was built in 2005 **Destruction / Demolition** 6. Ownership / Level of Protection SINGLE /MULTIPLE : Multiple **Public**: Archaeological Survey of: Endowment department, Govt. of Orissa State Archaeology Department / Any Other (Please specify) **Private** Any other (Please specify) Arjunesvara temple committee under the presidentship of Kailash Chandra Pradhan. Kailash Chandra Pradhan Name Address At- Haladibasanta, Po- Khairi, Dist- Puri, Pin-752104 Phone 7. Association WITH EVENTS In History In Rituals Sivaratri, Ekadasi, Kartika purnimka, Viswasanti mahayajna are held here. In Building Construction Any other (specify) Thread ceremony, engagement etc are performed here. WITH PERSONS Patron Originally the Somavamsi, but now the Endowment department, Govt. of Orissa. **Architect / Engineer** Any other (specify) Arjunesvara temple committee. 8. Statement of Significance Architectural : Architectural Archaeological Archaeological :

Historical

Religious Any other (specify)	: : SEC1	The temple is entirely renovated one, but on the basis of parsvadevata images and loose sculptures ,the original temple can be dated to the 10 th century A.D.	
9. Physical Description and Dec			
Context Urban / Rural Setting Surroundings	:	* Drawings (Attach extra sheet if necessary) : No Rural setting Stand in isolation Integral part of a	
		Integral part of a landscape / landscape Street / Complex:	
 Quantification 			
Area Dimension (LxBxH)	:	11.15 mtrs x 5.10 mtrs x 8.54 mtrs.	
Number of Blocks	•	(m / cm/ feet / inch) Two	
Number of Storys	:		
Spatial Organization			
Orientation	:	Facing towards east	
Plan	:	The vimana is square on plan and the jagamohana is	
Allocation of Spaces	:	rectangular on plan. 22.75mtrs x17.77mtrs in length and breadth respectively.	
ARCHITECTURAL STYLE • Ornamentation			
Exteriors	:	Devoid of decorations except an <i>Udyotasimha</i> on the western <i>raha</i> and two at the top and base of a miniature <i>rekha</i> shrine like designs in the frontal <i>raha</i> .	
Interiors	:	Plain	
Movable Collections	:	Sculptures of astikajaratkaru, nayikas, gaja vidala,	
* Any Other (specify)		naga figure and navagraha panel etc. The temple is pancharatha on plan and panchagabada	
Any Other (openny)	•	in elevation.	
10. Construction Technology			
Structural System	:	Rekha vimana and pidha jagamohana of Kalingan order.	
Building Techniques Material of Construction	:	Ashlar masonry Laterite	
11. Condition Assessment			
In General Good / Fair	•	Good	
50115141 5054 / 1 411	•		

Sign of Deterioration

	Deterioration f Disappearance	
In Brief (Attac	h extra sheet if ned	essary):
	acent to the temple	nce, the temple is in good state of preservation but the river boundary wall may create a great threat to the monument.
		Natural Negligence Vandalism Urban Pressures
x	. x x x x x x x x	××××××××××××××××××××××××××××××××××××××
	SF	ECTION III: REFERENCES
	<u> </u>	NEI ENERGES
13. Reference	Sources (published	and unpublished textual details)
2. B. K Rath	, 1996, The forgotter	eology in Orissa, Vol. I, New Delhi. n monuments of Orissa, vol3, New Delhi.
14. Photograp	ohs: 07 nos	(Attach list as in page 6, in case of multiple photographs
Photo Referer	псе	: :
15. Audio / Vid	deo	
		(Related to rituals / performance / festivals etc.
Reference DESCRIPTION	N .	: :
16. Maps/Plan	s/Drawings	
17. Listers		
NAME:	J.S Nayak	NAME:
18. Reviewers)	
NAME : COMMENTS	Dr. S. Pradhan	NAME: COMMENTS: