

## INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

## **Documentation format for Archaeological / Heritage Sites / Monuments**

Serial No.: 0R / PRI- 54

**SECTION I: IDENTIFICATION** 1. Name Bakresvara Temple, Kuapada, Dist.-Puri Present Past Other Name (if any): Vani Vakresvara Temple 2. Location **LONGITUDE** 85<sup>0</sup>44'11' E LATITUDE  $20^{0}04'52'N$ **ELEVATION** 10 ft Address Village (village code) Kuapada Post: Ghoradia Via: Delanga District: Puri Tehsil: Puri State: Orissa PIN: 752015 **Approach** Located on the left bank of the river Daya & on the right side of Khurda-Pattanayaikia road and 17 kms from Khurda & 3 kms. from Pahada Biswanatha Temple. 3. Property Type Religious structures Other Structures Buildings Palace Temple Wall Fort Mosque Gateway Citadel Minar Pillar Govt. building Church Others (specify) Railway station Monastery Defense building Stupa Industrial building Tomb, Mausoleum Other public buildings Residential building Engineering structure Open space and related Note: structures The temple has a rekha Bridge Public square vimana and pidha Tunnel Park or garden jagamohana of Kalingan order. Graveyard Other engineering structure Baolis, Well Tank Cave

## 4. Property Use ABANDONED / IN USE: In use **Present** Living temple, the presiding deity is a patalaphuta linga within a circular Yonipitha made of chlorite stone. **Past** Worshipped. 5. Age (Source) **PERIOD** Ganga rule 12<sup>th</sup> century AD YEARS 12<sup>th</sup> century AD Precise date of Construction Completion Subsequent changes Cement plaster is given to the gandi of jagamohana & a R. C. C pillar mandapa is attached to the temple recently by local people. **Destruction / Demolition** 6. Ownership / Level of Protection SINGLE /MULTIPLE : Multiple **Public**: Archaeological Survey of : Endowment Commission, Govt. of Orissa. India State Archaeology / Department / Any Other (Please specify) Private Bakresvara Temple Development Committee under the presidentship of Bauribandhu Routray. Any other (Please specify) Name Bauribandhu Routray At - Kuapada, P.O - Ghoradia, Dist.-Puri, PIN-752015 Address Phone 7. Association WITH EVENTS In History In Rituals Sivaratri, Kartika Purnima, Sankranti, Gamha Purnima etc. held here. In Building Construction Any other (specify) Marriage, Thread Ceremony, Engagement etc. observed here. WITH PERSONS **Patron Architect / Engineer**

Orissa State Archaeology renovated this temple under

X & XI Finance Commission Award.

Architectural

Archaeological

:

:

Any other (specify)

Architectural

Historical Religious

Archaeological

8. Statement of Significance

Any other (specify)	:	The special feature of the temple is that it stands over a high platform and <i>parsvadevata</i> shirnes are the integral part of the temple.	
		TION II: DESCRIPTION	
9. Physical Description and Decorative Features			
<ul> <li>Context</li> <li>Urban / Rural Setting</li> <li>Surroundings</li> </ul>	:	* <b>Drawings (</b> Attach extra sheet if necessary) : No Rural setting	
our our unity		Stand in isolation Street Integral part of a landscape / Street / Complex :	
<ul> <li>Quantification</li> </ul>			
Area Dimension (LxBxH)	:	13.80 mtrs x 7.85 mtrs x 15.00 mtrs (approximately) (m / cm/ feet / inch)	
Number of Blocks	:	<del></del>	
Number of Storys • Spatial Organization	:	<del></del>	
Orientation	:	Facing towards west.	
Plan	:	Both <i>vimana</i> and <i>jagamohana</i> are square on plan.	
Allocation of Spaces	:	37.50 mtrs (L) x 33.25 mtrs (W)	
ARCHITECTURAL STYLE			
<ul> <li>Ornamentation</li> <li>Exteriors</li> </ul>	:	Decorated with <i>nayika, dikpalas, vidalas,</i> erotic figure, royal science, animals & bird friezes, <i>naga</i> & <i>nagi</i> pilaster.	
Interiors	:	The interior of <i>jagamohana</i> is decorated with pilaster design & four <i>udyotasimha</i> at the ceiling.	
Movable Collections	:	Elephant figures, miniature <i>rekha temple</i> , warrior figure, large number of Nandis.	
* Any Other (specify)	:		
10. Construction Technology			
Structural System Building Techniques Material of Construction	:	Rekha vimana & pidha jagamohana of Kalingan order. Ashlar masonry Khandolite is used for the superstructure whereas laterite is used for foundation, compound wall and the frontal pillared mandapa.	
11. Condition Assessment			
In General Good / Fair	:	Good	
Sign of Deterioration Serious Deterioration Danger of Disappearance			

In Brief (Attach extra sheet if necessary):

12. Threats to	the Property	
		✓ Natural
		Negligence Vandalism
		Urban Pressures
		Oldan Flessules
x x x x x x x	x x x x x x x x	× × × × × × × × × × × × × × × × × × ×
	<u>s</u>	ECTION III: REFERENCES
13. Reference	Sources (publishe	d and unpublished textual details)
1. R. P. Moh	napatra, 1985, <i>Arch</i>	aeology in Orissa, Vol.1, New Delhi.
14. Photograp	ohs: 35 nos	
		(Attach list as in page 6, in case of multiple photographs)
Photo Referei	nce	:
CAPTION		:
15. Audio / Vi	deo	(5.1.1.1.1.1.1.1.1.1.1.1.1.1.1.1.1.1.1.1
		(Related to rituals / performance / festivals etc.)
Reference		:
DESCRIPTION	N	:
16. Maps/Plan	ns/Drawings	
17. Listers		
NAME .	A. R. Sahoo	NAME .
NAME:	A. K. Salloo	NAME:
18. Reviewers	5	
NAME:	Dr. S. Pradhan	NAME :
=		

**COMMENTS:** 

**COMMENTS** 

Except the few eroted images, the temple is in good condition due to the proper care and maintenance by the Bakresvara Temple Committee