

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: 0R/PRI- 11

SECTION I : IDENTIFICATION 1. Name									
Present Past Other Name (if any):	: Bata Lokanath Siva Temple,Puri Town, DistPuri : :								
LONGITUDE 85 ⁰ 49 ['] 14 ["] E	LATITUDE 19 ⁰ 47 ['] 90 ["] N ELEVATION 25 ft								
Address	: Village (village code) Balisahi Post : Puri Via: Puri Tehsil: Puri District: Puri State: Orissa. PIN: 752001								
Approach	: It is situated on the right side of Balisahi road leading from <i>Singhadvara</i> of Jagannath temple to <i>Swargadvara</i> near sea shore.								
Buildings Palace Fort Citadel Govt. building Railway station Defense building Industrial building Other public building Residential building	Religious structures Temple Mosque Minar Church Monastery Stupa Tomb, Mausoleum Other Structures Wall Gateway Pillar Others (specify) Others (specify)								
Engineering structure Bridge Tunnel Other engineering structure	Open space and related structures Public square Park or garden Graveyard Baolis, Well Tank Cave Note: The temple has a rekha vimana and pidha jagamohana of Kalingan order.								

4. Property Use ABANDONED / IN USE: In use **Present** Living temple, enshrining deity is a Sivalinga within a rectangular yonipitha at the centre of the sanctum. **Past** Worshipped. 5. Age (Source) **PERIOD** Ganga rule 13th century A.D. YEARS 13th century A.D. **Precise date of Construction** Completion Subsequent changes **Destruction / Demolition** 6. Ownership / Level of Protection SINGLE /MULTIPLE : Multiple **Public**: Archaeological Survey of: India State Archaeology Department / Any Other (Please specify) **Private** Any other (Please specify) The temple is looked after by the Balishai Brahmana Mahajana Seva Samiti Ashok Ku. Das & Kaliprasad Satpathy Name Address Balisahi, Puri Phone 7. Association WITH EVENTS In History In Rituals Sankranti, Sivaratri and Sitalsasthi. In Building Construction Any other (specify) Marriage and thread ceremony. WITH PERSONS **Patron** Originally the Gangas, but now by the Balisahi Brahmana Mahajana Seva Samiti is looked after the temple. Architect / Engineer Any other (specify) 8. Statement of Significance

assigned to Ganga period. SECTION II: DESCRIPTION

On the basis of the architectural features the temple

✓ Architectural

✓ Religious

Archaeological

Architectural

Historical

Religious

Archaeological

Any other (specify)

9. Physical Description and Decora	ative Features						
• Context Urban / Rural Setting : Surroundings	* Drawings (Attach extra sheet if necessary): No Urban setting						
	Stand in isolation Street Integral part of a landscape / Street / Complex :						
QuantificationArea Dimension (L x B x H) :Number of Blocks :	13.52 mtrs x 6.55 mtrs. X 10.92 mtrs. (m / cm/ feet / inch) Two						
Number of Storys :	·						
• Spatial Organization Orientation : Plan : Allocation of Spaces :	Facing towards east Both <i>vimana</i> and <i>jagamohana</i> are square on plan and <i>natamandapa</i> is rectangular on plan. 13.52 mtrs. X 6.80 mtrs.in length and breadth respectively.						
ARCHITECTURAL STYLE							
Ornamentation Exteriors : Interiors : Movable Collections : * Any Other (specify) : *** ** ** ** ** ** ** ** **	Since the exterior wall are plastered with a thick lim mortar the details of exterior decoration is not ascertained, except a few <i>mithuna</i> figure. Plain Nil Vimana is of rekha style where as the jagamohana is pidha order. Both vimana and jagamohana hav panchanga bada in elevation.						
10. Construction Technology							
Structural System : Building Techniques : Material of Construction :	The <i>vimana</i> is of <i>rekha</i> style and the <i>jagamohana</i> is <i>pidha</i> style of <i>Kalingan</i> order of architecture. Ashlar dry masonry along with use of iron dowells. Both sand stone and laterite stone are used in the construction of the temple. It was repaired and give lime plaster during renovation.						
11. Condition Assessment	inte placter during renovation.						
	Good / Fair : Good						
,	Sign of Deterioration Serious Deterioration Danger of Disappearance						
In Brief (Attach extra sheet if neces	ssarv):						

Cracks are noticed in the roof of the *natamandira* and in the *ganthiala* portion.

12. Threats t	o the Property								
X X	x x e Sources (publis	× SECTION	Natural Negligence Vandalism Urban Press x x ON III: REF	× ERENC		x	x	x	x
14. Photogra	•	sileu aliu	unpublished	lextual	ucians)	<u> </u>			
14. Filotogra	ipiiis	(/	Attach list as	s in page	e 6, in c	ase of	multiple	photog	raphs
Photo Refere CAPTION	nce	: :							
15. Audio / V	ideo								
			(Re	lated to	rituals /	perfor	mance.	/ festiva	ls etc.
Reference DESCRIPTIC	N	: :							
16. Maps/Pla	ns/Drawings								
17. Listers									
NAME :	K. B. Barik		NAME	:					
18. Reviewer	rs								
NAME : COMMENTS	Dr. S. Pradhan		NAME : COMME						