

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: 0R/PRI- 31

SECTION I: IDENTIFICATION 1. Name				
Present Past Other Name (if any): 2. Location	: Kuruma; A Buddhist m : : Yama Dharma/Jama Dl	•		
LONGITUDE 86 ⁰ 07' 24" E	LATITUDE 19 ⁰ 53' 62" N	ELEVATION 25 ft		
Address	: Village (village code) Post : Bali Dokana Tehsil: Konarka State : Orissa	Kuruma Via: Konarka District: Puri PIN: 752111		
Approach	Konarka–Kakatapur ro Konarka. It can be ap	situated on the left side of the ad and is about 6 km from proached by a road branching owk and is about 2 km from the		
3. Property Type				
Buildings Palace Fort Citadel Govt. building Railway station Defense building Industrial building	Religious structures Temple Mosque Minar Church Monastery Stupa Tomb, Mausoleum	Other Structures Wall Gateway Pillar Others (specify):		
Other public buildings Residential building		Note: This is a Buddhist monastery having twelve cells and an open		
Engineering structure Bridge Tunnel Other engineering structure	Open space and related structures Public square Park or garden Graveyard Baolis, Well Tank Cave	courtyard at the centre. The site was first reported by Brajabandhu Das, a local school teacher and subsequently excavated by Orissa state Archaeology from 1971 to 1975 A.D. On the basis of unearthed material the site can be dated to the 10 th century A.D.		

4. Property Use			
		ABANDONED / IN USE: In use	
Present	:	The monastery is abandoned now but the images retrieved from the site now worshiped within a small shed.	
Past	:	Worshipped.	
5. Age (Source)			
PERIOD YEARS Precise date of Construction Completion Subsequent changes	: : : : : : : : : : : : : : : : : : : :	Somavamsi Rule 9 th - 10 th centuries A.D. 9 th - 10 th centuries A.D. Excavated and conserved by the Orissa State	
oubsequent changes	•	Archaeology.	
Destruction / Demolition	:		
6. Ownership / Level of Protection	<u>n</u>		
		SINGLE /MULTIPLE : Multiple	
Public: Archaeological Survey of India / State Archaeology Department / Any Other (Please specify) Private	:	Protected site of Orissa State Archaeology	
Any other (Please specify)	:		
Name	:	Orissa State Archaeology	
Address	:	Paryatan Bhavan, BJB Nagar, Bhubanesvara	
Phone	•	0674-2432147	
7. Association			
WITH EVENTS			
In History In Rituals	:	Puddha nurnima mahaataya (may 21 8 22)	
In Building Construction	•	Buddha purnima mahostava(may 21 & 22)	
Any other (specify)	:	Engagement, , Thread Ceremony etc.	
• WITH PERSONS			
Patron	:	Originally the Somavamsi, but now the Orissa State Archaeology	
Architect / Engineer	:		
Any other (specify)	:		
8. Statement of Significance			
Architectural Archaeological Historical Religious Any other (specify)	: : : : : : : : : : : : : : : : : : : :	Architectural Archaeological	

On the basis of the antiquities and sculptures unearthed from the excavation the site can be dated to the 10th century A.D.

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features

Context

Urban / Rural Setting

Surroundings

* Drawings (Attach extra sheet if necessary) : No

Rural setting

complex

Stand in isolation

Integral part of a landscape / Street /

Complex:

Quantification

Area Dimension (L x B x H) : 29.00 mtrs x 29.00 mtrs x 2.10mtrs

(**m** / cm/ feet / inch)

Number of Blocks : Twelve Number of Storys : ---

Spatial Organization

Orientation : Oriented east to west.

Plan : The monastery in whole square on plan but the

cells are rectangular on plan.

Allocation of Spaces : 29mtrs x29mtrs in length and breadth respectively.

ARCHITECTURAL STYLE

Ornamentation

Exteriors : plain Interiors : Plain

Movable Collections : Buddha in *Bhumisparsa mudra*, *Heruka*, Bramha

and an image of Tivikrama.

* Any Other (specify) : The concept pf pillared verandah is absent here.

Instead of pillar, the wall of the court yard used as load bearer of the extended roof of the cells over

the verandah.

10. Construction Technology

Structural System : The monastic complex consists of twelve cells,

three in each cardinal direction and a large courtyard the centre. In between cells and

courtyard a passage is given.

Building Techniques

English bond

Material of Construction : Bricks (0.36x0.24x0.08mtrs) are mostly used for

constructional purpose except the central

courtyard which is made of khandolite stone.

11. Condition Assessment

In General Good / Fair : Fair

Sign of Deterioration Serious Deterioration Danger of Disappearance				
In Brief (Attach extra sheet if necessary):				
The conservation work done by Orissa State Archaeology was not properly executed as modern bricks were used in large number in a half hazard manner.				
12. Threats to the Property				
 ✓ Natural ✓ Negligence ✓ Vandalism Urban Pressures 				
x x x x x x x x x x x x x x x x x x x				
SECTION III: REFERENCES				
13. Reference Sources (published and unpublished textual details)				
R.P Mohapatra, 1986, Archaeology in Orissa, vol. 1, New Delhi.				
14. Photographs				
(Attach list as in page 6, in case of multiple photographs)				
Photo Reference : CAPTION :				
15. Audio / Video (Related to rituals / performance / festivals etc.)				
Reference :				
DESCRIPTION :				
16. Maps/Plans/Drawings				
17. Listers				
NAME: A.R. Sahoo NAME:				
18. Reviewers				
NAME: Dr. S. Pradhan NAME: COMMENTS:				