

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: 0R/PRI- 31

SECTION I: IDENTIFICATION 1. Name Chaitanya Matha Temple, Ghoradia, Dist. Puri Present Past Other Name (if any): 2. Location **LONGITUDE** 85⁰48⁷79["] E 19⁰47[']90" N LATITUDE **ELEVATION** 32 ft Address Village (village code) Ghoradia Post: Delang Via: Delang Tehsil: Puri **District:** Puri **PIN**: 752015 State: Orissa Located on the left bank of the river Daya & on the Approach right side of Khurda-Pattanayaikia road branching either at Gada Begunia Pada or Kuapada (it is about 2Km) and about 20 Kms from Khurda. 3. Property Type **Buildings** Religious structures Other Structures Palace Temple Wall Fort Mosque Gateway Citadel Minar Pillar Govt. building Church Others (specify) Railway station Monastery Defense building Stupa Industrial building Tomb, Mausoleum Other public buildings Residential building Engineering structure Open space and related Note: structures The temple has a square pidha Bridge Public square vimana and a rectangular Tunnel Park or garden pidha jagamohana of Kalingan Other engineering structure Graveyard order. Baolis, Well Tank Cave

4. Property Use		
		ABANDONED / IN USE: In use
Present	:	Living temple, the presiding deities are Chitanaya and Nityananda in dancing pose made of wood. Radha and Krisna made of eight metals (Asta Dhatu) are kept
Past	:	over a three moulded platform. Worshipped
5. Age (Source)		
PERIOD YEARS Precise date of Construction Completion Subsequent changes Destruction / Demolition 6. Ownership / Level of Protection	: : : :	Bhoi dynasty of Khurda 18 th century AD 18 th century AD
•		SINGLE /MULTIPLE : Multiple
Public: Archaeological Survey of India / State Archaeology Department / Any Other (Please specify)	:	
Private	:	Chaitanya Chandraya Committee under the presidentship of Dhruba Charana Naik & Secreatary, Dhanaswar Kunda.
Any other (Please specify) Name Address Phone 7. Association	: : :	 Priest – Biswanath Das AT/Po – Ghoradia, Dist – Puri, Orissa, 752015
WITH EVENTS In History In Rituals In Building Construction Any other (specify) WITH PERSONS	: : : :	Janmastami, Kartikapurnima, Chaitanya Janma, Ekadasi, etc. held here
Patron Architect / Engineer Any other (specify)	: :	Chaitanya Chandraya Committee Somanath Temple Committee
8. Statement of Significance		
Architectural Archaeological Historical Religious Any other (specify)	: : : : : : : : : : : : : : : : : : : :	 ✓ Architectural ✓ Archaeological On the sculptural ground (Parsyadevatas) the temple can be
	•	On the sculptural ground (Parsvadevatas) the temple can be assigned to the 18 th century AD.

SECTION II: DESCRIPTION

9. Physical Description and Deco	orati	ive Features
Context Urban / Rural Setting Surroundings	:	* Drawings (Attach extra sheet if necessary) : No Rural setting
Curroundings		Stand in isolation Street Integral part of a landscape / Street / Complex :
Quantification		
Area Dimension (LxBxH)	:	8.70 mtrs x 6.15 mtrs x 8.00 mtrs (approximately) (m / cm/ feet / inch)
Number of Blocks Number of Storys	:	
Spatial Organization		
Orientation Plan	:	Facing towards east. Consist of a square <i>vimana</i> and a <i>jagamohana</i> join by a Ganthiala that stands over a low pista of 0.45 mtrs high.
Allocation of Spaces	:	25.50 mtrs (L) x 25.00 mtrs (W)
• Ornamentation		
Exteriors	:	Devoid of any decorations except the <i>udyota simha</i> on the 3 rd tire of the <i>gandi, deula charini</i> and <i>dopicha simha</i> over the <i>beki</i> to support the <i>amalaka</i> .
Interiors Movable Collections	:	Plain Miniaturo Pokhamundi, doula charini
* Any Other (specify)	:	Miniature Rekhamundi, deula charini. The vimana is triratha on plan and panachagabada in elevation through it is entirely renovated by a coating of lime plaster & wash.
10. Construction Technology		
Structural System Building Techniques Material of Construction	: :	Pidha vimana & pidha jagamohana of Kalingan order. Ashlar dry masonry. Laterite is used for foundation, superstructure and the compound wall, Lime plaster is applied over this temple.
11. Condition Assessment		
In General Good / Fair	:	Fair
Sign of Deterioration Serious Deterioration Danger of Disappearance In Brief (Attach extra sheet if nec	cess	ary):
The frontal part of gandi of the jaga		• •

12. Threats to	the Property		
		✓ Natural ✓ Negligence Vandalism Urban Pressures	
XXXXXXX	(××××××××××××××××××××××××××××××××××××××	
	<u>s</u>	ECTION III: REFERENCES	
13. Reference	e Sources (publishe	d and unpublished textual details)	
14. Photograp	ohs: 05 nos		
		(Attach list as in page 6, in case of multiple photographs)	
Photo Refere CAPTION	nce	: :	
15. Audio / Vi	deo		
		(Related to rituals / performance / festivals etc.)	
Reference DESCRIPTION	N	: :	
16. Maps/Plans/Drawings			
17. Listers			
NAME :	A. R. Sahoo	NAME :	
18. Reviewers	s		
NAME: COMMENTS	Dr. S. Pradhan	NAME: COMMENTS:	