

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: 0R/PRI- 63

-		
1. Name	SECTION I: IDENTIFICATION	N
Present Past Other Name (if any): 2. Location	: Gopinath Temple, Nua : :	Somesvarpur, Dist.Puri
LONGITUDE 85 ⁰ 46' 29" E	LATITUDE 19 ⁰ 57' 14" N	ELEVATION 10 ft
Address	: Village (village code) Post:NuaSomesvarpu Tehsil: Satayabadi. State: Orissa	
Approach	Sakhigopal to Auagi	ight side of road, leading from uma and about 5 km. from situated on the right side of the
3. Property Type		
Buildings Palace Fort Citadel Govt. building Railway station Defense building Industrial building Other public building Residential building	Religious structures Temple Mosque Minar Church Monastery Stupa Tomb, Mausoleum	Other Structures Wall Gateway Pillar Others (specify)
Engineering structure Bridge Tunnel Other engineering structure	Open space and related structures Public square Park or garden Graveyard Baolis, Well Tank Cave	Note: The temple has a rekha vimana and pidha jagamohana of Kalingan order. Nisa shrines are provided in the parsvadevata niches.

4. Property Use

ABANDONED / IN USE: In use

Present: This is a living temple, and the presiding deity is a two

armed Venugopala image made of chlorite.

Past : Worshipped.

5. Age (Source)

PERIOD : Ganga rule.

YEARS : 13th-14th centuries A.D. Precise date of Construction : 13th-14th centuries A.D.

Completion : ---

Subsequent changes : Orissa State Archaeology renovated this temple under

X and XI Finance Commission Award.

Destruction / Demolition : ---

6. Ownership / Level of Protection

SINGLE /MULTIPLE : Multiple.

Protected monument of Orissa State Archaeology.

Public: Archaeological Survey of: India / State Archaeology
Department / Any Other (Please

specify)

Private : --

Any other (Please specify) : Under the care and maintenance of Jagatavallva

Mishra and Batakrushna Mohapatra president of

KOTHA Committee.

Name : Orissa State Archaeology.

Address : Paryatan Bhawan, B.J.B.Nagar, Bhuabaneswar,

Orissa.

Phone : 0674-2432147.

7. Association

• WITH EVENTS

In History : --

In Rituals : Chandana jatra, Janmasthami, Solapuja etc..

In Building Construction : --Any other (specify) : ---

• WITH PERSONS

Patron : Originally the Gangas, but now the Orissa State

Archaeology.

Architect / Engineer : ---

Any other (specify) : Under the care and maintenance of Kotha Committee.

8. Statement of Significance

Architectural

Archaeological

✓ Archaeological

Historical

Religious

✓ Religious

Any other (specify) : On architectural and sculptural ground the temple can be

SECTION II: DESCRIPTION

9. Physical Description and De	corative Features
 Context Urban / Rural Setting Surroundings 	* Drawings (Attach extra sheet if necessary):No : Rural setting.
Carroananigo	Stand in isolation Street. Integral part of a landscape / Street / Complex :
• Quantification Area Dimension (L x B x H)	: 11.25mtrs. x 6.40mtrs. x 10.00mtrs.(approximate.)
Number of Blocks Number of Storys	(m / cm/ feet / inch) : Two :
Spatial Organization Orientation Plan Allocation of Spaces	 The temple is facing towards east. Both <i>vimana</i> and <i>jagamohana are</i> square on plan. 19.50mtrs.x 10.95mtrs. in length and breadth respectively.
ARCHITECTURAL STYLE • Ornamentation	
Exteriors	: Decorated with <i>pidhamundi, khakharamundi, nayikas, gajavidala, naravidala</i> , erotic figure, amorous couple, war scenes ,royal discussion, elephant procession etc.
Interiors Movable Collections	 Plain Udyotasimha; images of Radha and Krisna, Chandrasekhara, parvati, Mahisasuramardini made of
* Any Other (specify)	asthdhatu.Both the vimana and jagamohana are pancharatha on plan and panchangabada in elevation.
10. Construction Technology	
Structural System	: Rekha vimana with parsavadevata shrine and pidha jagamohana of Kalingan order stands over a common high platform measuring 1.07mtrs. in height.
Building Techniques Material of Construction	: Ashlar dry Masonry : Khandolite.
11. Condition Assessment	
In General	Good / Fair : Fair. Sign of Deterioration Serious Deterioration

		Danger of Disappear	ance		
In Brief (Attac	ch extra sheet if n	ecessary):			
Wild vegetatio	ns like pipal tree, a	are noticed on the surface of	the temple.		
12. Threats to	the Property				
		Natural Negligence Vandalism Urban Pressures			
	x x x x e Sources (publish	x x x x x x SECTION III: REFERE and unpublished textual of		Х	Х
		y in Orissa, Vol-I, New Delhi ole Art of Orissa, Vol-II, 1986			
14. Photogra	phs: 26 nos				
		(Attach list as in page	6, in case of r	multiple pho	tographs
Photo Referer CAPTION	ıce	:			
15. Audio / Vi	ideo				
		(Related to r	rituals / perforr	mance / fest	ivals etc
Reference DESCRIPTIO	N	:			
16. Maps/Plai	ns/Drawings				
<u>-</u>					
17. Listers					
NAME :	A.R.Sahoo.	NAME :			
18.Reviewers	;				
NAME : COMMENTS	Dr. S. Pradhan	NAME : COMMENTS :			