

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: 0R / PRI- 45

1. Name	SECTION I: IDENTIFICATION	N
Present Past Other Name (if any):	Temple, Jiunti Sasan, Dist. Puri	
LONGITUDE 86 ⁰ 14'14"E	LATITUDE 19 ⁰ 59'13"N	ELEVATION 55 Ft.
Address	: Village (village code) Post : Kahala / Kendr Tehsil: Mulgada State : Orissa	
Approach		in the village of Jiunti Sasan and catpur; it is situated on the left i.
3. Property Type		
Palace Fort Citadel Govt. building Railway station Defense building Industrial building Other public building Residential building	Religious structures ✓ Temple Mosque Minar Church Monastery Stupa Tomb, Mausoleum	Other Structures Wall Gateway Pillar Others (specify)
Engineering structure Bridge Tunnel Other engineering structure	Open space and related structures Public square Park or garden Graveyard Baolis, Well Tank Cave	Note: Rekha vimana and pidha jagamohana of Kalingan Style of architecture

4. Property Use	
	ABANDONED / IN USE: In use
Present	: It is a living temple; the presiding deity is a Sivalinga within a square <i>Yonipitha</i> .
Past	: Worshipped
5. Age (Source)	
PERIOD YEARS	 Somavamsi rule. 9th century A.D.
Precise date of Construction Completion	: 9 th century A.D. :
Subsequent changes Destruction / Demolition	: Renovated by Orissa State Archaeology under X & XI Finance Commission Award.
6. Ownership / Level of Protection	
	SINGLE /MULTIPLE : Multiple
Public: Archaeological Survey of India / State Archaeology Department / Any Other (Please	: Protected monument of Orissa State Archaeology.
specify) Private Any other (Please specify) Name Address	 Jiunti Village Committee Orissa State Archaeology Paryatan Bhawan, BJB Nagar, Bhubaneswar.
Phone	: 0674-2432147
7. Association	
WITH EVENTS	
In History	:
In Rituals	: Sivaratir, Sankranti, Jalabhisekha, Rudrabhisekha etc. performed here.
In Building Construction Any other (specify)	:: Engagements thread ceremony, marriages etc. held here.
WITH PERSONS Patron	: Originally the Somavamsi, but now the Orissa State Archaeology
Architect / Engineer Any other (specify)	: : Jiunti Village Committee
8. Statement of Significance	
Architectural Archaeological Historical Religious	 ∴ Architectural ∴ Archaeological ∴ On architectural ground and building materials the temple
Any other (specify)	: On architectural ground and building materials the temple can be assigned to Circa 9 th – 10 th centuries A.D.

SECTION II: DESCRIPTION

9. Physical Description and Dec	orat	ive Features				
Context Urban / Rural Setting Surroundings		* Drawings (Attach extra sheet if necessary) : No Rural setting				
Quantification		Stand in isolation Integral part of a landscape / Street / Complex :	Street			
Area Dimension (L x B x H)	:	13.50. x 7.00 mtrs x 8.82 mtrs.	(m / cm/ feet / inch			
Number of Blocks Number of Storys • Spatial Organization	:	Two 	(117 0117 10017 111011			
Orientation Plan	:	Facing towards south-east. The temple consists of square <i>vimana</i> , <i>jagamohana</i> an an <i>antarala</i> which stands on a low <i>pista</i> of 0.31 mtrs i height.				
Allocation of Spaces	:	25 mtrs x 18 mtrs in length and bre	eadth respectively.			
ARCHITECTURAL STYLE • Ornamentation						
Exteriors	:	Decorated with a miniature rekharaha, two pidhamundis flanker jagamohana and rest part of the decorations.	d the doorjambs o			
Interiors Movable Collections	:	Plain A four armed Ganesa. Hanumana Royal figures probably the builder measures 70 cm x 38 cm x 22 cm	of this temple which			
* Any Other (specify)	:	Both the <i>vimana</i> and <i>jagamohana</i> are <i>panchangabada</i> is elevation and the <i>vimana</i> is <i>pancharatha</i> on plan while the <i>jagamohana</i> is <i>Saptaratha</i> on Plan.				
10. Construction Technology						
Structural System	:	Rekha vimana and pidha jagar order.	nohana of kalingan			
Building Techniques Material of Construction	:	English bond technique & use of ling Bricks are used for the foundation where as sandstone for the pave doorjambs of both <i>vimana</i> & <i>jag</i> colour wash is applied over this ten	n and superstructure ement, <i>pista</i> and the gamohana. Now red			
11. Condition Assessment						
In General Good / Fair Sign of Deterioration Serious Deterioration Danger of Disappearance	:	Fair				

ln	Brief	(Attach	extra	sheet	if	necessary	/)	1:

The temple is in fair condition because of the renovation work done by Orissa State Archaeology.

12. Threats to	the Property							
x x x x x x x	x x x x x x x x x	Van Urb	iligence Idalism an Pressi		« x x x	x	x	××
	SE	CTION	III: REFE	RENCES	;	<i>x x x x</i>	<i>X X X X</i>	X X
13. Reference	Sources (published	and unp	ublished	textual det	ails)			
Archaeolo	ay, <i>Archaeological</i> gy, Bhubaneswar. apatra, 1985, <i>Archa</i>	-	•	·		Valley,	Orissa	State
14. Photograp	hs: 07 nos							
		(Atta	ich list as	in page 6,	in case	of multip	le photo	graphs)
Photo Referer CAPTION	nce	: :						
15. Audio / Vid	deo							
			(Rel	ated to ritu	als / per	formance	e / festiva	als etc.)
Reference DESCRIPTION	I	: :						
16. Maps/Plan	s/Drawings							
17. Listers								
NAME :	K. B. Barik		NAME	:				
NAME: COMMENTS	Dr. S. Pradhan		NAME:	NTS :				