

## **INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS**

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: 0R/PRI- 30

**SECTION I: IDENTIFICATION** 1. Name Present Jagannath Bhallava Matha, Puri Town, Dist.- Puri Past Other Name (if any): 2. Location **LONGITUDE** 85<sup>0</sup> 49' 41" E 19<sup>0</sup> 48' 61" N LATITUDE **ELEVATION** 35 ft Address Village (village code) Dandimala Sahi, Market square Post :Puri Via: Puri Tehsil: Puri **District:** Puri State: Orissa **PIN**: 752111 It is on the right side of the Grand road leading from Approach Gundicha temple to the Jagannatha temple. 3. Property Type Buildings Religious structures Other Structures Palace Temple Wall Mosque Fort Gateway Citadel Minar Pillar Govt. building Church Others (specify): Railway station Monastery Defense building Stupa Industrial building Tomb, Mausoleum Other public buildings Note: Residential building The *matha* is affiliated to Open space and related Engineering structure Visnuswami sect. structures Bridge Public square Tunnel Park or garden Other engineering structure Graveyard Baolis, Well Tank Cave

## 4. Property Use

	ABANDONED / IN USE : In use
Present	: Living one and the presiding deity is Radha and Krisna.
Past	: Used.
5. Age (Source)	
PERIOD	:
YEARS	:
Precise date of Construction	:
Completion	:
Subsequent changes	:
<b>Destruction / Demolition</b>	:
6. Ownership / Level of Protection	on
	SINGLE /MULTIPLE : Multiple
Public: Archaeological Survey of	: It is under the Endowment Department, Govt. of
India / State Archaeology	Orissa.
Department / Any Other (Please	
specify)	
Private	:
Any other (Please specify)	: It is now look after by a Trust board having five
range career (a reduce expecting)	members appointed by the Endowment Department.
Name	:
Address	Dandimala sahi, Market square, Puri, pin- 752111
Phone	:
7. Association	
<ul> <li>WITH EVENTS</li> </ul>	
In History	:
In Rituals	: Monastic celebrations like Rukmani marriage, Snana
	yatra, Navajoubana Darsana, pankti bhoga, Jhulana
	yatra, sankanratriand Chandana yatra etc.
In Building Construction	:
Any other (specify)	:
<ul> <li>WITH PERSONS</li> </ul>	
Patron	: Endowment Department, Govt. of Orissa
Architect / Engineer	:
Any other (specify)	:
8. Statement of Significance	
Architectural	: 🗸 Architectural
Archaeological	:
Historical	<u> </u>
Religious	: ✓ Religious
Any other (specify)	;

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features				
Context Urban / Rural Setting Surroundings	:	* <b>Drawings (</b> Attach extra sheet if necessary) : No Urban setting		
Carroundinge		Stand in isolation Street Integral part of a landscape / Street / Complex :		
<ul> <li>Quantification</li> </ul>				
Area Dimension (LxBxH)	:	(m. Landforth linely)		
Number of Blocks Number of Storys	:	(m / cm/ feet / inch) Double storied building		
• Spatial Organization Orientation Plan	:	Facing towards east . The <i>matha</i> has a square central courtyard with pillared verandah that leading to the residential rooms		
Allocation of Spaces  ARCHITECTURAL STYLE	:	3 acres of land		
• Ornamentation Exteriors Interiors	:	Plain Wall paintings are noticed in the eastern wall of the central courtyard. The panel depicts Jagannatha, Balabhadra, Subhadra, Navagraha, Ramananda, Chaitanya, Krisna, Radha, Lalita, Ganesa, Sarasvati, Brahma and Kanchi abhijana.		
Movable Collections * Any Other (specify)	:	Within the <i>matha</i> precinct there are five Mahavira temples known as Sugriva Mahavira, Gumpha Mahavira, Guabadi Mahavira, Balabhadra bhallava Mahavira and Daria Mahavira.		
10. Construction Technology				
Structural System	:	Matha has a central courtyard with pillared verandah as leading to the residential rooms. There are 25 rooms among which 13 for residential rooms, 5 for rituals, 8 are for commercial purpose.		
Building Techniques Material of Construction	:	Ashlar masonry with lime wash. Laterite		
11. Condition Assessment				
In General Good / Fair Sign of Deterioration Serious Deterioration Danger of Disappearance In Brief (Attach extra sheet if necession)	:	Fair		

Growth of vegetations in the outer walls, mostly in the western wall and the cracks noticed in the roof endangered the monuments  12. Threats to the Property				
		Natural Negligence Vandalism Urban Pressures		
××××××××××××××××××××××××××××××××××××××				
SECTION III: REFERENCES				
13. Reference Sources (published and unpublished textual details)				
14. Photograp	ohs			
<u></u>		(Attach list as in page 6, in case of multiple photographs)		
Photo Reference CAPTION	nce	: :		
15. Audio / Vi	deo			
		(Related to rituals / performance / festivals etc.)		
Reference DESCRIPTION	1	: :		
16. Maps/Plans/Drawings				
17. Listers				
NAME:	K.B Barik	NAME:		
18. Reviewers				
NAME: COMMENTS	Dr. S. Pradhan	NAME: COMMENTS:		