

## **INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS**

Janpath, New Delhi -110 001, www.ignca.gov.in

## **Documentation format for Archaeological / Heritage Sites / Monuments**

Serial No.: 0R/PRI- 31

SECTION I : IDENTIFICATION  1. Name				
Present Past Other Name (if any):	: Jamesvara Siva Temp : Jamesvara Siva Temp :	le,Puri Town, Dist Puri le		
<b>LONGITUDE</b> 85 <sup>0</sup> 48 <sup>7</sup> 79 <sup>7</sup> E	<b>LATITUDE</b> 19 <sup>0</sup> 47 <sup>'</sup> 90 <sup>"</sup> N	ELEVATION 32 feet		
Address	: Village (village code) Post : Puri Tehsil: Puri State : Orissa.	Gaudabada Sahi Via: Puri District: Puri PIN: 752001		
Approach		in the south western direction of wards the end of the street in		
3. Property Type				
Buildings  Palace Fort Citadel Govt. building Railway station Defense building Industrial building Other public building Residential building	Religious structures  ✓ Temple Mosque Minar Church Monastery Stupa Tomb, Mausoleum	Other Structures  Wall Gateway Pillar Others (specify)		
Engineering structure  Bridge Tunnel Other engineering structure	Open space and related structures  Public square Park or garden Graveyard Baolis, Well Tank Cave	Note: It is a Kalingan order of temple having a rekha vimana & pidha jagamohana.		

4. Property Use				
		ABANDONED / IN USE: In use		
Present	:	The presiding deity is a Sivalinga within a circular <i>Yonipitha</i> inside the <i>sanctum</i> .		
Past	:	Worshipped		
5. Age (Source)				
PERIOD	:	Ganga rule		
YEARS Precise date of Construction	:	14 <sup>th</sup> century AD 14 <sup>th</sup> century AD		
Completion	:			
Subsequent changes	:			
Destruction / Demolition	:	<del></del>		
6. Ownership / Level of Protection				
		SINGLE /MULTIPLE : Multiple		
Public: Archaeological Survey of India / State Archaeology Department / Any Other (Please specify)	:	Endowment Department govt. of Orissa.		
Private	:	It is under Endowment Department through Trust Board		
Any other (Please specify)	:			
Name	:			
Address Phone	:	 		
	•			
7. Association  • WITH EVENTS				
In History	:			
In Rituals	:	Sitalasasthi, Chandana yatra etc. are observed		
In Building Construction Any other (specify)	:			
WITH PERSONS	•	<del></del>		
Patron	:	Originally the Ganga, but now by the Endowment Department, Govt. Of Orissa.		
Architect / Engineer	:			
Any other (specify)	:	<del></del>		
8. Statement of Significance				
Architectural	:	✓ Architectural		
Archaeological Historical	:	✓ Archaeological		
Religious	:	✓ Religious		
Any other (specify)	:	The architectural features assigned the temple to the last part of Ganga rule.		

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features				
Context Urban / Rural Setting Surroundings	:	* <b>Drawings (</b> Attach extra sheet if necessary) : No Urban setting		
Curroundings		Stand in isolation Complex Integral part of a landscape / Street / Complex :		
• Quantification				
Area Dimension (LxBxH)	:	35.40 mtrs x 12.30 mtrs x 12.28 mtrs ( <b>m</b> / cm/ feet / inch		
Number of Blocks Number of Storys	:	Four		
Spatial Organization				
Orientation Plan	:	The temple is facing towards east.  The <i>vimana</i> & <i>jagamohana</i> are square on plan and the <i>natamandapa</i> and <i>bhogamandapa</i> are rectangular.		
Allocation of Spaces	:	45.00 mtrs (L) x 35.00 mtrs (W) .		
ARCHITECTURAL STYLE  • Ornamentation				
Exteriors	:	Up to the <i>bada</i> portion the temple is decorated with architectural motifs like <i>pidhamundi</i> designs. The <i>gandi</i> is devoid of sculptural embellishment because it was covered with cement plaster & white wash.		
Interiors	:	Plain		
Movable Collections	:	Varaha image, Bhudevi image, dopicha simha (broken) etc. Found within the precinct.		
* Any Other (specify)	:	The temple is a <i>pancharatha</i> on plan an <i>panchangabada</i> in elevation.		
10. Construction Technology				
Structural System	:	Vimana is of rekha order, jagamohana is of pidha order and natamandapa & bhogamandapa are of flat roofed.		
Building Techniques	:	Ashlar dry masonry.		
Material of Construction	:	Sand stone and laterite are used in the construction. Originally the temple was made of sandstone but later on renovated with laterite.		
11. Condition Assessment				
In General Good / Fair Sign of Deterioration Serious Deterioration Danger of Disappearance In Brief (Attach extra sheet if necession)	:	Fair		

	•	nct because it is situated 6.40 mtrs below the present ground to discharge the rain water.
12. Threats to	the Property	
		✓ Natural Negligence Vandalism ✓ Urban Pressures
x x x x x x x	<pre>x x x x x x x x</pre>	
	<u>s</u>	ECTION III: REFERENCES
13. Reference	Sources (publishe	d and unpublished textual details)
1. R. P. Moh	napatra, 1986, <i>Arch</i>	aeology in Orissa, Vo. I, New Delhi.
14. Photograp	ohs	
		(Attach list as in page 6, in case of multiple photographs)
Photo Reference CAPTION	nce	: :
, 15. Audio / Vi	deo	
		(Related to rituals / performance / festivals etc.)
Reference DESCRIPTION	N	: :
16. Maps/Plar	ns/Drawings	
17. Listers		
NAME:	D. B. Garnayak	NAME:
18. Reviewers	3	
NAME:	Dr. S. Pradhan	NAME:

**COMMENTS:** 

**COMMENTS**